

		System Pit River at Alturas, Left Bank Levees Unacceptable - Inactive		North Fork Pit River - left bank - E of town (ALT2)		North Fork Pit River Alturas - left bnk SW of town (ALT4)											
General	Operations and Maintenance Manuals	A	A														
	Emergency Supplies and Equipment	A	A														
	Flood Preparedness and Training	A	A														
Levee Embankments	Unwanted Vegetation Growth	U	U														
	Sod Cover	NA	NA														
	Encroachments	U	U														
	Closure Structures	NA	NA														
	Slope Stability	A	A														
	Erosion/Bank Caving	A	A														
	Settlement	A	A														
	Depressions/Rutting	U	A														
	Cracking	A	A														
	Animal Control	U	U														
	Culverts/Discharge Pipes	NA	NA														
	Riprap Revetments & Bank Protection	NA	NA														
	Revetments other than Riprap	NA	NA														
	Underseepage Relief Wells/Toe Drainage Systems	NA	NA														
Seepage	A	A															
Flood Damage Reduction Channels	Vegetation and Obstructions	A	M														
	Shoaling	A	A														
	Encroachments	U	A														
	Erosion	A	A														
	Concrete Surfaces	NA	NA														
	Tilting, Sliding, or Settlement of Concrete	NA	NA														
	Foundation of Concrete Structures	NA	NA														
	Slab and Monolith Joints	NA	NA														
	Flap Gates/Flap Valves/Pinch Valves	NA	NA														
	Riprap Revetments & Banks	M	NA														
Revetments other than Riprap	U	NA															
												<b>Legend</b> A Acceptable M Minimally Acceptable U Unacceptable N/A Not Applicable					
The worst rating is used to determine the overall segment & system ratings and PL 84-99 Eligibility												1/27/2012					