2016/2017 Columbia/Snake River System Extended Navlock Outage The Dalles

Jeff Ament, P.E.

Project Manager

Portland District

May 27, 2015















US Army Corps of Engineers
BUILDING STRONG®

The Dalles

1956










59 Years



Current Issues/Plans - Downstream Gate


Gate and Pintle (bottom hinge point) replaced in 2011


- Included in 2016/17 Outage
 - ► Gudgeons (top hinge point)
 - ► Cathodic protection *
 - ▶ Vibration *



* Optional Items










Design by Tetra Tech


Current Issues/Plans - Upstream Gate

- Fracture critical structure
- Cracked welds and deformed members
- Gate is twisted, causing uneven lifting
- Included in 2016/17 Outage
 - ▶ Gate replacement











Current Issues/Plan - Controls

- High over-voltage at operator panel and interlock failure
 - ► 2013 temporary fix installed
- 59-year old hardware difficult to maintain
- Included in 2016/17 Outage
 - ► Operator Interface Controls upgrade
 - ► Electrical Power Distribution System upgrade







The Process


- FY14
 - ▶ Design Documentation Reports
- FY15
 - ▶ Plans & Specifications
 - ► Award power distribution supply contract
- FY16
 - ➤ Award construction contract
 - Contractor fabricate parts
- FY17
 - ▶ Lock outage






The Dalles FY17 Extended Lock Outage

- Outage Dec 12, 2016 6am, though March 20, 2017 20:59
- Estimated to be 14 weeks in duration











Other Opportunities

- John Day: Estimate 4 weeks (TBD)
 - ► DSQ1 Replacement (new switch purchased in 2012)
 - Friction Sheave and Bearings repair
 - Replacement of tainter valve operating cylinder
 - ▶ D/S gate wire rope replacement (~ 10 year replacement)
- Bonneville: Estimate 8 weeks (TBD)
 - NavLock Controls modernization and electrical repairs
 - ► In-place since 1993 no longer supported by industry
 - System Failures occurring more frequently





Questions?





