
US Army Corps of Engineers

St. Louis District®

Navigation Channel Condition Status Report - 05 June 2013



Dredge Status

Dredge Potter - Dockside

Channel Marker Status

Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.

The Pathfinder is dockside for maintenance this week.

Additional Risks / Concerns

Navigation Notices

Local Notice to Mariners

Current Weather

Highs in the upper 80s to the low 70s; lows in the high 60s to mid 50s. Chance of rain throughout the next week.

Hannibal, MO St. Louis, MO Cape Girardeau, MO Cairo, IL

Web Information

For additional info about New River Training Structures, see the link below: http://www.mvs.usace.army.mil/Missions/Navigation/Construction.aspx

For the most recent channel patrol and predredge surveys, see the link below: http://www.mvs.usace.army.mil/ Missions/Navigation/Surveys.aspx

The new electronic Navigation charts for the Upper Mississippi River are now available online for download or to order at the below link:

http://www2.mvr.usace.army.mil/NIC2/mrcharts.cfm

More Status Report

Please click for older status reports

<u>Cairo</u>

Gage = 40.8 ft 1 Week Forecast = 40.2 ft 2 Week Forecast = 33.4 ft

<u>Cairo</u>

Ohio River

Key			
•	Anticipated Dredging Locations		
*	Groundings		
Δ	Dredge Potter		
∇	Dredge Hurley		
	Dredge America		
Red	Very Likely to be Problematic at Low Water		
Yellow	Could be Problematic at Low Water		
Green	Problem Resolved		

Probable "Hot" Spots Within 4 Weeks					
River Mile	Estimated Problematic Date	Dredge ETA	Dredge Complete	Dredge	

Please click below to email comments or suggestions:

mvsnavstatus@usace.army.mil

Generation Time: 06-06-2013 8:34