




**US Army Corps of Engineers**  
St. Louis District

## Navigation Channel Condition Status Report - 6 July 2016



**Dredge Status:**

**Dredge Potter:** The Dredge Potter completed RM 203, 200.5 and 195.8.

The Potter has returned to the Service Base due to higher river stages. Resume date TBD.

**Channel Marker Status:**

Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.

For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.

The Pathfinder will conduct a lower river channel patrol next week

**Additional Risks / Concerns**

**Navigation Notices**

**Local Notice to Mariners**

**Weather**

Highs in the Mid 90's to upper 80's;  
Lows in the Mid 70's to upper 60's,  
Chance of rain Wed, Fri, Sun & Mon

**Hannibal, MO**

**St. Louis, MO**

**Cape Girardeau, MO**

**Cairo, IL**

**Web Information**

For additional River Training Structure information, see the link below:

<http://www.mvs.usace.army.mil/Missions/Navigation/Construction/Current.a>

For the most recent channel patrol and pre-dredge surveys, see the link below:

<http://www.mvs.usace.army.mil/Missions/Navigation/Surveys/ChannelPatrol.aspx>

The new electronic Navigation charts for the Upper Mississippi River are now available online for download or to order at the below link:

<http://www2.mvr.usace.army.mil/NIC2/mrcharts.cfm>

**More Status Reports**

[Click for older status reports](#)

**Key:**

- ◆ Anticipated Dredging Locations
- ☆ Groundings
- △ Dredge Potter
- ▽ Dredge Goetz

**Very Likely to be Problematic at Low Water**

**Could be Problematic at Low Water**

**Problem Resolved**

**Probable Dredge Areas**

River Mile	Problematic On:	Dredge ETA	Dredge Complete	Dredge

Please email comments or suggestions to [mvsnavstatus@usace.army.mil](mailto:mvsnavstatus@usace.army.mil)