## UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

## **ACCIDENT INVESTIGATION REPORT**

	OCCURRED DATE: 29-NOV-2007 TIME: 1410 HOURS  OPERATOR: Royal Production Company, Inc. REPRESENTATIVE: Grossman, Julie TELEPHONE: (281) 578-3388  CONTRACTOR: REPRESENTATIVE: TELEPHONE:	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE X OTHER Equipment Failure
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
	LEASE: G07846  AREA: MO LATITUDE: BLOCK: 914 LONGITUDE:  PLATFORM: RIG NAME:	PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. 17196 OTHER
	ACTIVITY: EXPLORATION(POE)  DEVELOPMENT/PRODUCTION (DOCD/POD)  TYPE:  HISTORIC INJURY  REQUIRED EVACUATION LTA (1-3 days)	8. CAUSE:  EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK
	TA (>3 days	UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury	9. WATER DEPTH: FT.
	FATALITY POLLUTION FIRE	10. DISTANCE FROM SHORE: MI.
	LWC HISTORIC BLOWOUT UNDERGROUND SURFACE	11. WIND DIRECTION: SPEED: M.P.H.  12. CURRENT DIRECTION:
	DEVERTER  SURFACE EQUIPMENT FAILURE OR PROCEDURES	SPEED: M.P.H.
	COLLISION ☐ HISTORIC ☐ >\$25K ☐ <=\$25K	13 SEA STATE: FT

MMS - FORM 2010 PAGE: 1 OF 3

EV2010R 23-JAN-2008

## 17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On November 29, 2007 at approximately 14:10, at Royal Production Company Inc.'s Lease OCS-G 07849, Mobile (MO) Block 914, an employee received 2nd degree burns, from hot water, on his arm, chest, abdomen and legs. The Injured Person (IP) was conducting repairs on a pump by the output pipe, when the expansion boot blew out causing hot water to engulf him. Pipeline Segment No. 17196. IP had 7 days of lost time and 36 days of modified duty. On January 11, 2008 IP was cleared to return to work without restrictions.

## Sequence of Events:

The injured party was tightening packing where the shaft goes through the pump by the output pipe when the expansion boot blew out causing severe hot liquid (water) to engulf the injured on arms, chest, abdomen and legs. The injured party then went back to the mechanic shop and sent a diver to retrieve the medic. Medic assessed burns to be 2nd degree burns. Injured is being put on the M/V Lafayette to be transported to Theodore, AL Martin Midstream Dock to be taken to the hospital.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Pressure on the pump when performing repairs.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Faulty expansion boot.

20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010 PAGE: 2 OF 3

EV2010R 23-JAN-2008

21. PROPERTY DAMAGED:

None None

ESTIMATED AMOUNT (TOTAL): \$

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The New Orleans District makes no recommendations to MMS.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
- 25. DATE OF ONSITE INVESTIGATION:
- 26. ONSITE TEAM MEMBERS:

  No Onsite Investigation /

  29. ACCIDENT INVESTIGATION PANEL FORMED:

  NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

NATURE OF DAMAGE:

Troy Trosclair

APPROVED

DATE: 18-JAN-2007

MMS - FORM 2010 PAGE: 3 OF 3

EV2010R 23-JAN-2008