UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

	OCCURRED DATE: 19-APR-2007 TIME: 1045 HOURS OPERATOR: Chevron U.S.A. Inc.	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS.
	REPRESENTATIVE: Noel George TELEPHONE: (504) 592-3000 CONTRACTOR: REPRESENTATIVE: Shawn Ryan (Energy Cranes TELEPHONE: (985) 246-9734	INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
4.	LEASE: 00392 AREA: GI LATITUDE: BLOCK: 37 LONGITUDE:	PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL
5.	PLATFORM: R RIG NAME:	PIPELINE SEGMENT NO. OTHER
6.	ACTIVITY: EXPLORATION(POE) DEVELOPMENT/PRODUCTION (DOCD/POD)	8. CAUSE:
7.	TYPE: HISTORIC INJURY REQUIRED EVACUATION LTA (1-3 days) LTA (>3 days RW/JT (1-3 days) X RW/JT (>3 days) 1	X HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury FATALITY	9. WATER DEPTH: 60 FT.
	POLLUTION FIRE	10. DISTANCE FROM SHORE: 6 MI.
	LWC HISTORIC BLOWOUT UNDERGROUND	11. WIND DIRECTION: SPEED: 12 M.P.H.
	SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12. CURRENT DIRECTION: SPEED: 5 M.P.H.
	COLLISION HISTORIC >\$25K <=\$25K	13. SEA STATE: 3 FT.

MMS - FORM 2010 PAGE: 1 OF 3

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

Person reported on 4/19/07 that he had a burning and tightening in the lower section of his abdomen while lifting a steel plate ½"X16"X4". He was lifting with the assistance of another employee, placing the plate into a scrap metal basket. He reported on 4/20/07 a.m. that he was still having symptoms. The employee was sent in to be evaluated by his company doctor. He was put on restricted duty.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Improper lifting procedures.
Possibly, he was not in good physical shape.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Awkward position.

20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010 PAGE: 2 OF 3

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None None

ESTIMATED AMOUNT (TOTAL):

Ġ

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The New Orleans District makes no recommendations to the Office of Safety Management.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
- 25. DATE OF ONSITE INVESTIGATION:

28-MAY-2007

26. ONSITE TEAM MEMBERS:

Phil McLean /

29. ACCIDENT INVESTIGATION

PANEL FORMED: NO

OCS REPORT:

27. OPERATOR REPORT ON FILE: YES

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: 04-JUN-2007

MMS - FORM 2010 PAGE: 3 OF 3

EV2010R