## UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

## **ACCIDENT INVESTIGATION REPORT**

| 1.         | OCCURRED  |                                    |
|------------|---|------------------------------------|
|            | DATE:   | STRUCTURAL DAMAGE                  |
|            | 17-SEP-2007 TIME: 0845 HOURS  | CRANE                              |
|            |   | OTHER LIFTING DEVICE               |
| 2.         | OPERATOR: Bois d'Arc Offshore Ltd.  | DAMAGED/DISABLED SAFETY SYS.       |
|            | REPRESENTATIVE: Toby Trosclair  | INCIDENT >\$25K                    |
|            | TELEPHONE: (985) 631-3278   | H2S/15MIN./20PPM                   |
|            | CONTRACTOR: EAGLE CONSULTANTS   | REQUIRED MUSTER                    |
|            | REPRESENTATIVE: Toby Trosclair  | SHUTDOWN FROM GAS RELEASE          |
|            | TELEPHONE: (985) 631-3278   | X OTHER Supply boat open manway    |
| _          |   |                                    |
| 3.         | OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR<br>ON SITE AT TIME OF INCIDENT: | 6. OPERATION:                      |
|            |   | X PRODUCTION                       |
|            |   | DRILLING                           |
| 4.         | LEASE: <b>G05541</b>  | WORKOVER                           |
|            | AREA: SS LATITUDE:  | COMPLETION                         |
|            | BLOCK: 92 LONGITUDE:  | HELICOPTER                         |
|            |   | MOTOR VESSEL                       |
| 5.         | PLATFORM: #8  | PIPELINE SEGMENT NO.               |
|            | RIG NAME:   | OTHER                              |
| _          | _   | O GAUGE:                           |
| 6.         | ACTIVITY: EXPLORATION(POE)  | 8. CAUSE:                          |
|            | X DEVELOPMENT/PRODUCTION  | ☐ EQUIPMENT FAILURE                |
| 7          | (DOCD/POD) TYPE:  | HUMAN ERROR                        |
| <i>'</i> • | TIEB.   | EXTERNAL DAMAGE                    |
|            | HISTORIC INJURY   | X SLIP/TRIP/FALL                   |
|            | X REQUIRED EVACUATION 0   | WEATHER RELATED                    |
|            | LTA (1-3 days)  | LEAK                               |
|            | $\overline{\mathbf{x}}$ LTA (>3 days 1  | UPSET H2O TREATING                 |
|            | RW/JT (1-3 days)  | OVERBOARD DRILLING FLUID           |
|            | RW/JT (>3 days)   | OTHER                              |
|            | Other Injury  | 9. WATER DEPTH: <b>66</b> FT.      |
|            | FATALITY  | 7. millio 22111                    |
|            | POLLUTION   | 10. DISTANCE FROM SHORE: 20 MI.    |
|            | FIRE  | 10. Bibliated from blicke 20 file. |
|            | EXPLOSION   | 11. WIND DIRECTION: N              |
|            | LWC   HISTORIC BLOWOUT  |                                    |
|            | UNDERGROUND   | SPEED: 1 M.P.H.                    |
|            | SURFACE   | 10 GUDDENE DEDEGETON               |
|            | DEVERTER  | 12. CURRENT DIRECTION: N           |
|            | SURFACE EQUIPMENT FAILURE OR PROCEDURES                                       | SPEED: 1 M.P.H.                    |
|            | COLLISION   HISTORIC   >\$25K   <=\$25K                                       | 12 CEA CEARE. 2 EF                 |
|            |   | 13. SEA STATE: <b>2</b> FT.        |

MMS - FORM 2010 PAGE: 1 OF 4

EV2010R 27-JUL-2010

## 17. INVESTIGATION FINDINGS:

He was walking on the deck of the supply boat when he fell in an open, non-barricaded manway. The injured party was transferred from a liftboat, which was jacked up next to the caisson, to a supply boat. The injured party was sent to shore for medical evaluation. He was seen by a doctor and was released to full duty with no serious injuries being found. A few days later, he returned to the doctor because he was still in pain. At that time, a MRI was performed and fractures were found that did not show up initially on x-rays. He is still under doctor's care and has not returned to work.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The injured party fell in an open, non-barricaded manway while walking across the deck on a supply boat.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

N/A

20. LIST THE ADDITIONAL INFORMATION:

A USCG jurisdictional event.

21. PROPERTY DAMAGED: NATURE OF DAMAGE:

None N/A

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

Due to the specific nature of this incident, the Houma District has no recommendations to report to the Regional Office of Safety Management.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

None

- 25. DATE OF ONSITE INVESTIGATION:
- 26. ONSITE TEAM MEMBERS:

  29. ACCIDENT INVESTIGATION
  PANEL FORMED:
  NO

OCS REPORT:

MMS - FORM 2010 PAGE: 2 OF 4

EV2010R 27-JUL-2010

30. DISTRICT SUPERVISOR:

Michael J. Saucier

APPROVED DATE: 14-NOV-2007

PAGE: 3 OF 4 MMS - FORM 2010

MMS - FORM 2010 PAGE: 4 OF 4

EV2010R \* \* \* \* \* \* \* \* PROPRIETARY \* \* \* \* \* \* 27-JUL-2010