UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION ACCIDENT INVESTIGATION REPORT							
	ONTRACTOR REPRE AT TIME OF INC	-	UPERVISOR	6.	OPERATION:		
 4. LEASE: AREA: BLOCK: 5. PLATFORM: RIG NAMI 	GI LATITU 78 LONGIT A				<pre>X PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT OTHER</pre>	NO .	
LTA X LTA RW/J	(DOCD/PO INJURY IRED EVACUATION (1-3 days) (>3 days T (1-3 days)	ENT/PRODUCI	TION	8.	CAUSE: EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING OTHER		
	T (>3 days) r Injury v			9.		85 FT.	
POLLUTI FIRE	ON			10.	DISTANCE FROM SHORE:	28	MI.
UNI	ON TORIC BLOWOUT PERGROUND FACE				WIND DIRECTION: SPEED:	M.P.H.	
DEV	ERTER FACE EQUIPMENT	FAILURE OR	PROCEDURES	12.	CURRENT DIRECTION: SPEED:	M.P.H.	
COLLISION	HISTORIC	□>\$25K	<=\$25K	13.	SEA STATE: FI		

EV2010R

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On September 26, 2007, at approximately 19:25, at Arena Offshore, LLC's OCS-G 12989, Grand Isle (GI) 78 A Platform, a rigger was injured when a hydraulic hose struck him across his safety glasses, scraping his nose and cutting his left eyelid while changing out two hydraulic hoses on a crane, as a result of human error. Injured Person (IP) initially received first aid after the incident and then was sent onshore to seek medical treatment on September 27, 2007. IP was treated by ENT Physician on September 28, 2007 and October 05, 2007, and was released to return to work.

Sequence of Events:

While changing out two hydraulic hoses on crane, the mechanic was pulling on one while rigger was guiding it out. It came out and hit the rigger across his safety glasses; scraping his nose and left a small cut on left eyelid. Provided first aid and let him rest for evening. Later he complained of headache and further evaluation indicated he may have broken his nose. IP was sent onshore for medical treatment. Injured party was treated by ENT Physician from 09-28-07 and 10-05-07, and released to return to work.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Human Error:

- 1) Inattention to the job being performed.
- 2) Lack of communication between mechanic and rigger.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

20. LIST THE ADDITIONAL INFORMATION:

None

NATURE OF DAMAGE:

ESTIMATED AMOUNT (TOTAL): \$
22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:
The New Orleans District makes no recommendations to MMS.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

25. DATE OF ONSITE INVESTIGATION:

- 26. ONSITE TEAM MEMBERS: No Onsite Investigation /
- 29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED DATE: 07-NOV-2007

MMS - FORM 2010

EV2010R