INTRODUCTION

This module provides general information about radiological survey instruments. Basic functions and limitations are discussed. Because there are many models of survey instruments available, this discussion provides only a general description of survey instrument types and uses. For participants wanting more detailed descriptions of specific devices and their functions, information on several commonly available instruments is included in the appendix to this module.

PURPOSE

The purpose of this module is to provide you with a general awareness and understanding of radiological survey instruments and how they can be used to survey for radiation exposure and contamination. Proper use of radiological survey instruments will provide you with more information on the hazards present at the scene.

MODULE OBJECTIVES

Upon completion of this module, you will be able to:

1. Identify two categories of radiological survey instruments.
2. State the proper application and limitation of contamination survey instruments.
3. State the proper application and limitation of radiation exposure survey instruments.
4. Identify commonly used dosimetry devices.

notes

notes

RADIOLOGICAL SURVEYS AND INSTRUMENTATION

The use of radiological survey instrumentation by responders at an incident scene is optional. The Emergency Response Guidebook does not specifically recommend the use of radiological survey instruments during the initial response phase of the incident. Use of these instruments will give you more detailed information about the radiological hazards present at the scene.

Radiation cannot be detected by our senses. By using radiological survey instruments, properly trained responders can easily and accurately detect radiation. There are two general categories of radiological survey instruments available. One category of instruments is designed to measure radiation, while the other is designed to measure contamination. Some instruments are designed to measure both radiation and contamination.

Basic Theory

Similar to the way a radio converts radio waves to sound, a radiological survey instrument converts radiation energy to a meter reading. In a radiological survey instrument, ionizing radiation interacts with material in the detector to produce ions. The detector collects these ions and sends them to the instrument which produces an audible and/or visual response. Some radiological survey instruments combine the detector and meter in one unit, while others may have the detector attached to the meter by a cable (*See examples below*).

There are many different models and types of radiological survey instruments with a variety of features and controls[1]. Because they have different operating characteristics, you should know how to operate those used in your jurisdiction.

Contamination Survey Instruments

Contamination survey instruments are very sensitive and measure the presence of radioactive material in terms of counts per minute (CPM). Instruments that measure effects in CPM are useful for detecting contamination on personnel and equipment. A limitation of contamination survey instruments is that they should not be used to measure radiation exposure. Contamination surveys should always be reported in CPM.

Application of Contamination Survey Instruments

The purpose of a contamination survey is to locate radioactive material in unwanted locations. Contamination surveys are useful for the following:

- Locating contamination on personnel and equipment
- Determining the effectiveness of decontamination
- Verifying contamination control boundaries
- Determining the extent and magnitude of a contaminated area

[1] Descriptions of some of the instruments commonly used by responders, including the CD V-700 and the CD V-715 Survey Meters, can be found in the appendix to this module.

notes

notes

Because the difference between measurements of background radiation and that produced by contamination may be slight, it is important to determine the background (naturally-occurring) radiation level prior to performing a survey. Determine background radiation levels by observing the meter reading in the cold zone. Contamination surveys should be preformed in areas with low background radiation. The higher the background radiation level, the harder it is to determine contamination levels.

Begin by following your local procedures or manufacturer's recommendations for instrument pre-operational checks and instrument calibration frequency.

- Verify that the instrument is on, set to the lowest scale, the audio can be heard, and there is visual response
- The probe/detector should be held within 1/2 inch of the surface being surveyed
- Move the probe slowly, approximately 1 to 2 inches per second
- If the count rate increases while surveying, pause for 5-10 seconds over the area to provide adequate time for instrument response

Become familiar with your jurisdiction's or state's guidelines for when an individual or object is considered contaminated. For example, some jurisdictions use twice background or 100 CPM above background as a positive indication of contamination.

Radiation Exposure Survey Instruments

Exposure rate survey instruments usually measure radiation in terms of milliroentgen per hour (mR/hr) or roentgen per hour (R/hr). These effects are typically recorded in the biological equivalent of mrem/hour or rem/hour or, if the instrument uses the SI units, micro or milli sieverts/hour. Instruments that measure effects in mR/hr or R/hr are most useful for measuring radiation fields at the event scene. A limitation of radiation exposure survey instruments is that they are generally not as sensitive as contamination survey instruments and may not efficiently detect some types of contamination.



Application of Radiation Exposure Survey Instruments

The purpose of a radiation exposure survey is to locate and measure sources of radiation. Radiation exposure surveys are useful for the following:

- Establishing control zone boundaries
- Controlling personnel exposure
- Assessing package integrity
- Locating sources of radiation

Follow your local procedures or manufacturer's recommendations on instrument pre-operational checks and instrument calibration frequency. Prior to performing a radiation survey, verify that the instrument is on, the range selector switch is on the lowest scale, the audio can be heard (if applicable), and a visual response registers on the meter.

notes

MERRTT
Radiological Survey Instruments and Dosimetry Devices

notes

Many radiation exposure rate survey instruments are designed to detect both beta and gamma radiation. These instruments typically employ some type of rotating or movable beta shield that can be opened to admit beta radiation (see photos below). With the detector shield closed, beta radiation is blocked out and only gamma radiation is detected. With the beta shield open, both beta and gamma radiation are detected. The beta dose contribution from a measurement can be determined by subtracting the reading taken with the beta shield closed from the reading taken with the beta shield open (open window reading – closed window reading).

When surveying for beta and gamma radiation, radiation measurements should be made by approaching the area or object to be surveyed with the detector extended in front of you and the beta shield, if applicable, in the open position. With the shield in the open position, the instrument will simultaneously detect gamma and beta radiation.

Periodically monitor in a 360 degree circle to ensure that you have not walked by a source of radiation. Monitor for radiation with the detector at waist level and periodically check above and below this level. When a source of radiation is discovered, survey as necessary to determine its approximate location.

When performing a radiation survey, it is useful to listen to the audio response so that even if you are temporarily distracted, the response to a radiation field can be heard.

The following table can be used to assist you in converting the SI units (sieverts) to the traditional units (millirem).

Reading in sieverts	Equals	Reading in mrem & rem
1 microsievert	=	0.1 millirem
1 millisievert	=	100 millirem
1 sievert	=	100 rem

notes

notes

READING THE METER FACE

Many of the newer survey instruments have a digital display and will automatically adjust the range from microrem to millirem to rem per hour or from counts per minute (CPM) to kilo counts per minute (kCPM). The traditional analog instruments can be more difficult to read than digital instruments. Often it requires that the user multiply the reading displayed on the meter face by a multiplier, depending on which scale the instrument range multiplier switch is set to. For example, in the illustration below, the reading on the meter face shows a reading of 200 CPM; since the range multiplier switch is set to X10, the 200 is multiplied by 10 so that the actual reading is 2,000 CPM.

200 CPM on the meter face times 10 on the range multiplier switch equals 2,000 CPM



As discussed earlier, contamination survey results are usually recorded in CPM and radiation survey results are usually recorded in mR/hr. For those instruments that display in both CPM and mR/hr, the user should determine which units to record their reading in based upon the type of survey (radiation or contamination) being performed. Contamination surveys are best performed with pancake style detectors and radiation surveys are best performed with side window GM or "hotdog" style detectors. An example of each type is shown below:

Pancake Style Probe

Hotdog Style Probe

M E R R T
Radiological Survey Instruments and Dosimetry Devices



In the case of the CD V-700 (pictured at right), the meter face reads in both CPM and mR/hr. When using this type of survey instrument with the standard side window GM or "hotdog" probe (as seen in the photo to the right), readings should be recorded in mR/hr when the probe window is closed and in CPM when the probe window is open.

With the Ludlum style instruments, readings should be recorded in CPM with the pancake style probe attached and in mR/hr with the hotdog probe attached. The graphics below illustrate these points.





notes

notes

DOSIMETRY DEVICES

Although not required at an incident scene, dosimetry devices are useful for keeping track of your total accumulated radiation dose. A dosimeter is like the odometer on your car. For example, where the odometer measures total miles traveled, the dosimeter measures the total amount of dose you have received. There are several different types of dosimeters available. Some commonly used examples are discussed here.

Self Reading Dosimeters



A self reading dosimeter (SRD) measures the radiation dose in roentgens (R) or milliroentgens (mR). Generally, SRDs only measure gamma and X-ray radiation.

SRDs are called by many names: direct reading dosimeter (DRD), pocket ion chamber (PIC), and pencil dosimeters are a few common names.

To read the dosimeter, hold it up to a light source and look through the eyepiece. You should always record the SRD reading before you enter a radiation field (hot zone). Periodically, (at 15 to 30 minute intervals) read your SRD while working in the hot zone and upon exit from the hot zone. If a higher-than-expected reading is indicated, or if the SRD reading is off-scale, you should:

- Notify others in the hot zone
- Have them check their SRDs
- Exit the hot zone immediately
- Follow local reporting procedures

If you are using a low range dosimeter (e.g., 0 to 200 mR), you should consider exiting the hot zone if the dosimeter reads greater than 75% of full scale. The reason for this is to prevent your dosimeter from going off scale; if your dosimeter goes off scale, it will no longer keep a record of the dose you received. A dosimeter can be recharged or "zeroed" after each use. Record the final reading upon leaving the hot zone. Exercise care when using a SRD, they are sensitive instruments. Rough handling, static electricity, or dropping a dosimeter may result in erroneous or off-scale readings.

Electronic Dosimeters

The electronic dosimeter serves the same basic function as the SRD, except that it has a digital readout that displays the total dose received by the wearer in milliroentgens (mR) or millirem (mrem). Electronic dosimeters are available from various manufacturers in a variety of sizes and shapes. There are many options available, depending on the required or desired response.

Many electronic dosimeters have an audible response that indicates the exposure rate through a series of chirping noises. The frequency of the chirping increases and decreases in relation to the dose rate. These "chirpers" provide the advantage of an audible warning when dose rates increase.

notes

notes

Thermoluminescent Dosimeters

Thermoluminescent dosimeters (TLDs) do not provide an "on-the-spot" indication of accumulated dose as the previously mentioned dosimeters do. Specialized equipment is needed to retrieve the radiological exposure data stored by the TLD. TLDs are not usually available for use by individual fire departments or local agencies. Specialized hazardous material response teams and state and federal radiological response organizations usually wear TLDs.

Check Your Understanding

1. Radiation itself (can/cannot) be detected by our senses (circle the correct answer).

2. Radiation (can/cannot) be measured easily and accurately (circle the correct answer).

3. Some radiological survey instruments are used to survey for _____, and others are used to detect and/or measure _____exposure.

4. If a radiological survey instrument measures effects in counts per minute (CPM), it is going to be most useful as a contamination survey instrument. True/False.

5. A limitation of contamination survey instruments is that they are not designed to measure _____ exposure.

6. Exposure rate survey instruments usually measure radiation in terms of _____ per hour or _____ per hour.

7. Some survey Instruments are designed to measure both contamination and radiation exposure. True/False.

8. The purpose of a contamination survey is to locate radioactive material in unwanted locations. True/False.

9. A self reading dosimeter (SRD) keeps track of accumulated (radiation/ contamination) dose while in a field of radiation. (Circle the correct answer).

M E R R T T




ANSWERS

1. cannot
2. can
3. contamination
   radiation
4. true
5. radiation
6. milliroentgen
   roentgen
7. true
8. true
9. radiation

Ludlum Instrument

Meter Reading	Range Selector	Probe Used	Results
			
	 x1000 FOR INTERNAL PROBE ONLY		
	 x1000 FOR INTERNAL PROBE ONLY		
			

Ludlum Instrument

Meter Reading	Range Selector	Probe Used	Results
			
			
			
			

CD V-700 Instrument

Meter Reading	Range Selector	Probe Window	Results
			
			
			
			

CD V-700 Instrument

Meter Reading	Range Selector	Probe Window	Results