


NOTE
When the river is above the Ordinary High Water elevation all navigators are urged to sail near the sailing line to prevent bank erasion.

NOTE: SEE OPPOSITE PAGE FOR CLEARANCE DATA.

(1) SUBMARINE CROSSING
(2) NEW MARTINSVILLE HIGHWAY BRIDGE

(A) MAGNOLIA YACHT CLUB
(B) MARTIN MARIETTA AGGREGATES
(C) ARROW CONCRETE
(D) DOCK SIDE INC.

# OHIO RIVER

500' 0 500' 1500'

SCALE 1"=1500'
REVISED: JANUARY 2002

CHART NO. 187