
3548
3546
3547
3550
2 Section mantrip
SCSR bottom cover No. 114792 (Shull)
SCSR top cover
SCSR top cover
SCSR top cover
mouthpiece plug
SCSR top cover
SCSR bottom cover No. 122599 (Kinser)
SCSR pouch
SCSR top cover
goggles
SCSR bottom cover No. 107521 (Plumley)
SCSR bottom cover No. 102662 (Vanover)
SCSR top cover
SCSR bottom cover No. 100069 (Crouse)
goggles
safety glasses
sweat jersey
3214
3535
goggles
lunch box
SCSR top cover
SCSR bottom cover No. 109376 (Baisden)
SCSR bottom cover No. 104946 (Hunt)
goggles
SCSR top cover
hammer
goggles
SCSR bottom cover No. 83549 (B. Mayhorn)
safety glasses
SCSR bottom cover No. 107363 (Hatfield)
SCSR bottom cover No. 104970 (E. Mayhorn)
SCSR top cover
goggles
SCSR top cover
SCSR bottom cover No. 100000 (Hensley)
goggles
SCSR top cover
3228
3227
SCSR top cover
SCSR bottom cover No. 122596 (Bragg)
North East Mains No. 1 Belt
curtain installed during rescue operations
curtain installed during rescue operations
3230
3224
3222
personnel door through which miners traveled to North East Mains belt entry
roof fall occurred after accident
3243
3233
3226
3254
3256
3223
belt structure not installed across roadway
0' 20' 40'
Note: Ventilation controls depicted as mapped during the investigation.
APPENDIX F
MINE MAP
ARACOMA ALMA MINE #1, MSHA ID No. 46-08801
ARACOMA COAL COMPANY, INC.
Affected Area of Mine
Detail of Area Surrounding 2 Section Mantrip
LEGEND
Primary Escapeway Reflective Tag
Roof Fall
Cribs
3456 Survey Station (SS) Location and Number
Roadway
Stopping
Hole in Ventilation Control Indicated by Slash
Stopping with Personnel Door
Check Curtain
Installed Conveyor Belt
Installed Belt Structure