BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT
1450				

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
3704	6-25-82	192	Repl. broken hinges on double gate of Compound fence
3623	10-20-82	313	Issue gravel for parking lot
9034	comp	1965	Install Key Tele. Sys.
3965		2373	Remove & replace Ref. Air Dryer and Air Compressor
2352	6-18-85	1248	FAB, (7) Work Bench Tables for Engine Maint
3084	5-3-85	982	Remove & Repl. underground vent. Oil Tank Bldg 1450
3559	Compl	543	Decontam. Rist. A/C 1-27-84
4334	1-23-85	1495	RPL Rear Grde & Posts of compound
4197	2-15-85	611	Rpl compressor in A/C sys—
4832	5-3-85	126	Rpr Block wall
1064	6-26-87	1,550	Fabricate & install 3 Compressed gas Cages
1065	6-26-87	1,550	" " " "
3965	4-24-86	2373	R/R Refrigerated Air Dryer / Air Compressor
0075	9-23-91	4139	INSTALL ELECTRIC SERVICE
3981	6-20-92	5979	Rplc Fuel Dispensing Pumps #4 & #5.
4188	12-30-92	3273	RPL (1) Fuel Dispensing Pump /RPR/Reinstall (1) Fuel Dispensing Pump
4920	3-24-94	2429	Rplc Commode Stalls / Urinal Screens
3951	11-1-96	6364	RPLC 2 A/C UNITS Purged 9-19-8?
3951	11-1-96	329	1ST AMD

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION