BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
LCH-4021					

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
1807	11-3-77	208	Install (1) Base boards Hot water radiator
1781	10-7-77	266	Furnish, install (1) elect. water cooler
1776	6-27-80	146	Make Repairs to Reefer & freezer
1706	2-5-80	39	Pour concrete slab
1018	1-10-83	9658	PAINT INTERIOR, REPAIR DOORS + TRIM
1809	3-22-83	467	TREAT FOR ROACHES
1805	3-4-88	63162	INSTALL (2) HEAT Pumps

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION

BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
LCH-4021					

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
JB7 819 101 105	8/26/67	169	Make repairs of one window screen, insulation on hot water storage tank replace three vapor proof globes and one switch, plaster 10 SF M SH 6-7
			Plaster , touch-up interior paint facia board to door canopy and window screens
AA223 0344 23XXT	9/17/71	312	Relocate compressor to walk-in reefer from inside storage room to outside of Bldg.
AA223 0351 2312T	9/24/71	194	Patch build-up roof 11 places a total of 16" x 40'
AA223 037823XXT	12/23/71	904	Repairs to roof and boxing over walks and four porches
AA223 1722 23XXT	8/25/72	224	Relocate exhaust fan switch and hook-up walk-in reefer

JOB ORDER NO	DATE COMPLETED	COST		DESCRIPTION