BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
S-TT-50					MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4754	2-28-72	445	Repair to TT-57- Include replacing built up roof
4397	11-22-71	O/E	Pull well pump & salvage mat
6775	9-8-70	932	Repair support Columns gates
4568	5-27-70	678	Pull + clean well pump
4533	5-12-70	772	Clean + repair deep well pump
3717	8-8-69	883	Pull + repair deep well pump
31142	9-24-68	782	Pull clean + install well pump
31303	10-30-68	620	Pull + repair well pump
31850	3-20-69	667	Repair deep well pump
31832	3-12-69	702	Repair deep well pump
CMONS-206	1-4-68	73	Repair damage to (2) screen door + lock
116-610-135	3-8-67	O/E	Remove repair + replace
116-610-121	1-9-67	1148	Pull, clean + reinstall deep well pump
2077	8-31-84	1491	Fab/Install Wall locker Stge + Paint

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION