BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
VL-104					

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
H 58 CM OSM 271	5/25/68	368	Install 200 A. Service and (5) 220 V for toasters.
HS7-198-653-014	5/19/66	929	VL 104 Add scullery to messhall
" "	8/3/66	160	Fabricate 2 Roof jacks to vent gas hotwater heaters.
[illegible]-589-239	6/21/67	378	Emergency repair drain line
OQ4-100-00	7/3/67	761	Replace secondary power lines near bldg.
ONJ-134	10/6/67	530	Paint Interior of bldg. 2 coats
625-102	8/5/66	35	Ad dendum to change three phase compressor to single phase on reefer
30812	8-9-68	805	repl Hot water heater
31672	2-21-69	—	rep water pump
31859	3-20-69	2613	rep window, door, and screen panels
3934	11-13-69	616	Issue paint for int & ext
2390	11-21-69	1136	Clear rec. r/w + dragline

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION