AS 539

BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4203	7-15-83	2841	Replace deteriorated plywood
3346	12-27-85 Comp	562	Replace Roof
3346	12-27-86	6158	Replace FLAT Built up Roof with A Frame
3224	Comp	3494	MAINT TO The Elect. DIST. SYSTem.
5259	3-1-85	161	Rpr. Potable water lines Bursted underneath Bldg.
4277	9-25-92	758	Repair Floor

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION