Ratio=400

L/D=4

# Mach Number along the Axis