FINAL SUMMARY OF MAP ACTIONS

Community: PIKE ROAD, TOWN OF Community No: 010433

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected when the revised FIRM becomes effective on February 5, 2014.

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below will be reflected on the revised FIRM. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below will not be reflected on the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will remain in effect until the revised FIRM becomes effective. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	04-04-3996A	04/23/2004	230 GLYNLAKES DRIVE	01101C0170G	01101C0244H
LOMA	05-04-1151A	06/01/2005	GLYNLAKES, LOT 4 -- 125 GLYNLAKES DRIVE	01101C0170G	01101C0244H
LOMA	06-04-B714A	02/28/2006	GLYNLAKES PLAT 5, LOT 23 -- 200 GLYNLAKES DRIVE	01101C0170G	01101C0244H
LOMA	09-04-0296A	11/20/2008	EMMETT C. FERRELL III NO. 1, PARCEL 1 -- 107 GLYNLAKES DRIVE	01101C0170G	01101C0244H
LOMR-F	10-04-1235A	12/18/2009	SECTION 21, T15N, R19E -- 137 GLYNLAKES DRIVE	01101C0170G	01101C0244H
LOMR-F	11-04-3803A	07/19/2011	GLYNLAKES SUBDIVISION, LOT 13 -- 143 GLYNLAKES DRIVE	01101C0170G	01101C0244H
LOMR-F	11-04-6652A	09/15/2011	GLYNLAKES PLAT NO. 7, LOT 22 -- 211 GLYNLAKES DRIVE	01101C0170G	01101C0244H
LOMR-F	13-04-4253A	05/13/2013	GLYNLAKES PLAT NO. 7, LOT 15 -- 155 GLYNLAKES DRIVE	01101C0170G	01101C0244H

FINAL SUMMARY OF MAP ACTIONS

Community: PIKE ROAD, TOWN OF Community No: 010433

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Final revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		