FINAL SUMMARY OF MAP ACTIONS

Community: CLINTON, CITY OF Community No: 180259

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected when the revised FIRM becomes effective on 02/05/2014.

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below will be reflected on the revised FIRM. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below will not be reflected on the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will remain in effect until the revised FIRM becomes effective. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	99-05-4822A	08/11/1999	301 S. 4TH STREET	1802599999A	18165C0294C
LOMA	01-05-2574A	06/27/2001	WILLIAM ARTHUR WHITCOMB'S ADDITION, BLOCK 1, LOT 10; 658 SOUTH 3RD STREET	180259 01B	18165C0294C
LOMA	04-05-B090A	01/12/2005	AMIS AND MARTIN'S ADDITION, LOT 31 -- 1003 SOUTH MAIN STREET	180259_01B	18165C0294C
LOMA	09-05-3972A	07/30/2009	WHITCOMB PENTREATH'S ADDITION, BLOCK 1, LOT 7 AND PORTION OF LOT 10 -- 320 SOUTH 7TH STREET	1802590001B	18165C0294C
LOMA	09-05-5895A	12/18/2009	325 SOUTH MAIN STREET	1802590001B	18165C0294C
LOMA	12-05-2825A	02/14/2012	PARCELS 1 AND 2 ---528 SOUTH MAIN STREET	1802590001B	18165C0294C

FINAL SUMMARY OF MAP ACTIONS

Community: CLINTON, CITY OF Community No: 180259

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Final revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
LOMA	04-05-A074A	10/13/2004	ARTHUR WHITCOMB'S ADDTN, BLOCK 1, LOT 7 -- 644 SOUTH 3RD STREET	1

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		