FINAL SUMMARY OF MAP ACTIONS

Community: DODGE COUNTY Community No: 550094

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected when the revised FIRM becomes effective on 02/05/2014.

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below will be reflected on the revised FIRM. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMR	11-05-8473P		FOX LAKE	55027C0176F 55027C0177F 55027C0178F 55027C0179F 55027C0181F 55027C0182F 55027C0183F 55027C0184F 55027C0191F	55027C0159G 55027C0176G 55027C0177G 55027C0178G 55027C0179G 55027C0181G 55027C0182G 55027C0183G 55027C0184G 55027C0191G 55027C0201G 55027C0203G

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below will not be reflected on the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will remain in effect until the revised FIRM becomes effective. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	10-05-6538A	09/14/2010	LOT 3 & 4, MAPLE POINT -- N10820 MAPLE POINT ROAD	55027C0179F	55027C0179G
LOMA	11-05-1134A	03/02/2011	N10604 CHEIF KUNO TRAIL	55027C0183F	55027C0183G
LOMA	11-05-1343A	03/08/2011	LOT 30, MAPLE BEACH -- N10886 MAPLE POINT	55027C0179F	55027C0179G
LOMA	11-05-4820A	05/19/2011	LOTS 13 & 14, FISHER PLAT OF SOUTH SHORE -- N10334 HOWARD DRIVE	55027C0179F	55027C0179G
LOMA	11-05-6691A	07/26/2011	LOT 1, CERTIFIED SURVEY MAP NO. 6040 -- N10852 MAPLE POINT	55027C0179F	55027C0179G

FINAL SUMMARY OF MAP ACTIONS

Community: DODGE COUNTY Community No: 550094

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	11-05-8274A	10/04/2011	N10837 MAPLE POINT ROAD	55027C0179F	55027C0179G
LOMA	10-05-7334A		Lot 1,2,3, John Koegel's Summer Resort Add. Subdivision - W10581 Blackhawk Trail	55027C0181F	55027C0181G

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Final revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		