

Agreed Order Signed August 6, 2013

Enterprise Crude Pipeline
Docket No. GUD 10207

Company ID 7856, Houston, Harris County, Texas
System ID 960922

Rule(s) violated:

<p>The operation and maintenance manual did not include procedures to provide safety when operating design limits are exceeded in the course of responding to, investigating, and/or correcting the cause of:</p> <ul style="list-style-type: none">a. unintended shutdowns or closed valves.b. abnormal increases or decreases in pressure or flow rate.c. loss of communication.d. operation of any safety device.e. a component malfunction.f. deviation from normal operation.g. personnel error that could cause a hazard. <p>Other: Control Room of Enterprise; Procedures did not define parameters for shutting down a pipeline due to volume losses</p>	<p>Requirement: 49 CFR 195</p>
--	--------------------------------

Date violations began: 1/27/2011

Date of Compliance: 11/29/2012

Penalty paid: \$50,000