X9B SAFETY CHECKLIST				N	BROOKHAVEN NATIONAL LABORATORY NATIONAL SYNCHROTRON LIGHT SOURCE
Rev: A	Effective:10/22/04		Page 1 of 1		Number: LS-SCL-0020
Reviewed by:	Thomas McDonald	Reviewed by	y:		Approved by: A. Ackerman

Original signatures on file.

The only official copy of this file is the one on-line in the NSLS Quality Assurance website. Before using a printed copy, verify that it is the most current version by checking the document effective date on the NSLS QA website.

THE FOLLOWING MUST BE CHECKED STARTING FROM THE SHIELD WALL ON THE X10 SIDE OF THE BEAMLINE

ALL EXCLUSION ZONES ARE BLACK FOLDED ALUMINUM BOXES.

□ 2. □ 3. □ 4. □ 5. □ 6. □ 7. □ 8. □ 9. □ 10	Valid Padlock Index, no padlocks open. Scatter shield covering Bremsstrahlung shield (BS1) as per photo 1. Exclusion Zone (EZ1) in place as per photo 1. Bremsstrahlung shield (BS2) as per photo 1. Scatter shield covering Ion pump 1as per photo 2. Exclusion Zone (EZ2) in place as per photo 2. Bremsstrahlung shield (BS3) as per photo 3. Exclusion Zone (EZ3) in place as per photo 3. Scatter shield on slits as per photo 4. Exclusion Zone (EZ4) in place as per photo 5. Scatter shield covering Ion pump 2 as per photo 5.
	Inside of X9A hutch
□ 12	Exclusion Zone (EZ5) in place.
	Downstream of X9A hutch
□ 14	Exclusion Zone (EZ6) in place as per photo 6. Bremsstrahlung shield (BS4) as per photo 6.
□ 16 □ 17	Scatter shield covering monochromator as per photo 7. Bremsstrahlung shield (BS5) as per photo 7. Vacuum Bellows 1 wrapped in lead as per photo 7. Vacuum Bellows 2 wrapped in lead as per photo 8.
□ 16 □ 17 □ 18	Bremsstrahlung shield (BS5) as per photo 7. Vacuum Bellows 1 wrapped in lead as per photo 7.