

Date: 16-June-08

## Engineering Technical Order

### Modification Note 112, Falling Ice Warning Sign

Modification Note 112 provided a Falling Ice Warning sign to 41 sites. Several sites have experienced problems with the adhesive mounted anchors. We recommend sites experiencing this anchor problem drill holes (use eye protection) in each corner of the sign and use UV rated tie wraps to secure the signs to the fence.

For the remaining 56 sites, we will provide the signs with predrilled holes and UV rated tie wraps in lieu of the adhesive mounted bracket.