

ARCS PROCEDURE: Author: P. Malone	CEILOMETER: CYCLING POWER TO CEILOMETER COMPUTER	PRO(CEI)-011.000 May 11, 1999 Page 1 of 1
--	--	---

Ceilometer: Cycling Power to Ceilometer Computer

I. Purpose:

To describe the procedure for cycling power on the Ceilometer computer in the I-Van.

II. Cautions and Hazards:

None.

III. Requirements:

None.

IV. Procedure:

A. Steps:

1. Exit out of the VC-View program by selecting File and then Quit.
2. Press the Start button on the lower left hand side of the screen.
3. Select Shutdown.
4. Select Restart the Computer.
5. Press OK.
6. The computer will reboot.
7. Power button: pull out connector on back of the computer.
 - Things to look for (if they are not present, you would want to reboot the system and note it in the Daily Rounds report):
 - a) Cursor goes from hourglass to arrow regularly.
 - b) Clock updates.
 - c) You see "No Errors" on the top.

V. References:

None.

VI. Attachments:

None.