

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 14

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 14

Facility Name: Seabrook 1 Docket (050- 00443)

Details	Department	Work Type	Docket/Report
Management and Supervision / IR			
40 - Individual Corrective Action LTA	G - Engineering	M - Maint / Repair	050-00443/2003-006
40 - Individual Corrective Action LTA	I - Instrumentation & Control	M - Maint / Repair	050-00443/2004-004
41 - Action not begun or untimely	E - Electrical	M - Maint / Repair	050-00443/2004-004
41 - Action not begun or untimely	G - Engineering	M - Maint / Repair	050-00443/2004-004
41 - Action not begun or untimely	G - Engineering	M - Maint / Repair	050-00443/2004-006
Number of Items for this Docket: 5			
Percent of Total for this Docket: 36			
Work Factors / IR			
83 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00443/2003-006
83 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00443/2003-006
83 - Work practice or craft skill LTA	Z - Other	Z - Other	050-00443/2004-004
83 - Work practice or craft skill LTA	Z - Other	Z - Other	050-00443/2004-004
83 - Work practice or craft skill LTA	Z - Other	Z - Other	050-00443/2004-004
86 - Work untimely	O - Operations	O - Control Room Ops	050-00443/2003-006
Number of Items for this Docket: 6			
Percent of Total for this Docket: 43			
Management and Supervision / LER			
40 - Individual Corrective Action LTA	G - Engineering	V - Troubleshooting	050-00443/2004-002-00
47 - Root Cause LTA	G - Engineering	V - Troubleshooting	050-00443/2004-002-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 14			
Training / LER			
02 - Training LTA	G - Engineering	V - Troubleshooting	050-00443/2004-002-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 7			
Total Items for this Docket: 14			
