

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

A B C CORP (Shipper)	Offered sodium hydrosulfite in packages not marked with a proper shipping name; failed to indicate quantity on shipping paper; offered HM in an unauthorized packaging; failed to provide hazard class on the shipping paper; failed to provide shipper's certification. [172.301(a), 172.202(c), 173.204(a), 172.202(a)(1), 172.202(a)(2), 172.204(d)(1), 173.217(a)] Case No. 93-64-SP-WE	\$9,465
A-1 FIRE EQUIPMENT CO INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 94-244-CR-SW	\$4,240
ABCO FIRE PROTECTION INC (Cylinder Retester)	Certified cylinders with equipment not calibrated to 1% accuracy; failed to maintain accurate records; marked cylinders with illegible month and year markings. [173.34(e)(3), 173.34(e)(5), 173.34(e)(6)] Case No. 94-262-CR-CE	\$7,600
ACCURATE BOX CARTON & CONTAINER CORP (Fiberboard Box Manufacturer)	Certified boxes as UN 4G without conducting design qualification tests; failed to properly mark boxes with name and address or registered symbol. [178.601(d), 178.503(a)(7)] Case No. 95-08-BM-WE	\$11,400
ACME BARREL CO INC (Drum Reconditioner)	Certified drums as DOT 17H without conducting periodic drop and hydrostatic tests; failed to mark open-head steel drums as required. [178.118-12(a), 173.28(o)(1)(ii), 173.28(m)(3)(iii)] Case No. 94-19-DR-CE	\$4,700
ADVANCE PACKAGING CORP (Package Certifier)	Certified packagings as UN standard without including the name and address or registered symbol of the approval agency; failed to include required information in the certification marking; failed to keep complete records of design qualification tests. [178.503(a)(8), 178.502(a)(2), 178.516(a), 178.601(k)(1)] Case No. 94-95-PC-CE	\$4,000
AEROJET-GENERAL CORP (Shipper)	Offered Class 1.3 and 1.4 explosives for transportation in exemption packagings after the exemption had expired. [173.62(a), 173.62(b), 173.151] Case No. 94-111-EXR	\$2,610
ALBANY WELDING SUPPLY CO INC (Cylinder Retester)	Filled specification cylinders and offered them for transportation when they were not retested within a five-year period. [173.34(a)(1)] Case No. 95-28-EXR	\$1,500
ALL CHEMICAL CORP (Shipper)	Offered an oxidizer in a packaging not properly certified. [173.212(a)] Case No. 94-193-SP-CE	\$3,250

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

ALL FIRE EQUIPMENT INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records. [173.34(e)(3), 173.34(e)(5)] Case No. 93-87-CR-CE	\$4,200
ALL FIRE TEST CO INC (Cylinder Retester)	Failed to perform a complete external visual examination. [173.34(e)(1)] Case No. 93-109-CR-CE	\$1,750
ALLIED HASTINGS BARREL & DRUM (Drum Reconditioner)	Failed to properly mark reconditioned drums. [173.28(o)(1)(iii)] Case No. 94-28-DR-CE	\$400
ALOHA FREIGHT FORWARDERS (Shipper)	Offered oxidizing substances, solid, n.o.s. in nonspecification packaging. [173.154(a)] Case No. 94-75-FF-WE	\$2,800
AMERICHEM CORP (Shipper)	Offered flammable liquid for transportation in DOT 57 portable tanks which had not been retested as required; failed to list a correct emergency response telephone number on shipping papers. [173.32(e)(2)-(4), 173.125(a)(1), 172.201(d), 172.604(b)] Case No. 93-246-SPT-CE	\$6,590
ARCADIAN CORP (Shipper)	Offered HM for transportation in exemption packaging after the exemption had expired. [173.154(a)(17), 173.243] Case No. 94-43-EXR	\$1,950
ASE INDUSTRIES (Cylinder Retester)	Failed to remark exemption aluminum cylinders as specification 3AL; failed to perform a complete visual external examination; failed to maintain accurate records of visual reinspection and retest. [173.23(c), 173.34(e)(1), 173.34(e)(5)] Case No. 95-18-CR-SW	\$4,960
ATLANTIC COAST FIRE EQUIPMENT (Cylinder Retester)	Certified cylinders without performing a complete visual examination; failed to maintain accurate records. [173.34(e)(1), 173.34(e)(5)] Case No. 95-79-CR-HQ	\$4,120
ATLANTIC FIRE EQUIPMENT COMPANY INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 93-234-CR-EA	\$3,600
ATOMIC FIREWORKS INC OF TENNESSEE (Shipper)	Offered an unapproved explosive device for transportation. [173.54(a)] Case No. 94-66-SE-HQ	\$4,000

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

AURORA TRI-STATE FIRE PROTECTION (Cylinder Retester)	Failed to condemn a cylinder when permanent expansion exceeded 10%; failed to remark exemption aluminum cylinders as specification 3AL; conducted hydrostatic testing without calibrating test equipment. [171.2(c), 173.34(e)(4), 173.23(c), 173.34(e)(3)] Case No. 94-250-CR-CE	\$6,075
AUTOMATIC FIRE SYSTEMS (Cylinder Retester)	Marked cylinders as meeting the requirements of the HMR without performing the hydrostatic test; failed to conduct a visual examination; failed to condemn a cylinder when permanent expansion exceeded 10%; failed to maintain accurate records; failed to remark an exemption aluminum cylinder as specification 3AL; failed to calculate wall stress before applying the plus mark. [173.34(e)(1), 173.34(e)(4), 173.34(e)(5), 173.23(c), 173.302(c)(3)] Case No. 93-200-CR-EA	\$12,295
B O C INC (Shipper)	Filled and offered non-liquefied compressed gas without maintaining daily records of pressure verification; failed to provide a proper shipping paper. [173.302(e), 172.202(a)] Case No. 95-149-SC-SW	\$5,345
B-LANN EQUIPMENT COMPANY INC (Cylinder Retester)	Performed hydrostatic testing with inaccurate equipment; conducted a 2nd retest at the same pressure instead of 10% or 100 psi higher; failed to remark exemption aluminum cylinders as 3AL; failed to maintain accurate records; failed to condemn cylinders made to DOT-E7235 when permanent expansion exceeded 5% of total expansion. [173.34(e)(3), 173.23(c), 173.34(e)(5), DOT-E 7235] Case No. 93-43-CR-EA	\$9,385
BADGER WELDING SUPPLIES INC (Cylinder Retester)	Certified cylinders as meeting the requirements of the HMR with equipment not calibrated to an accuracy of 1%; failed to calculate wall stress when marking a cylinder with the "+" sign; failed to maintain accurate records. [173.34(e)(3), 173.302(c)(3), 173.34(e)(5)] Case No. 93-264-CR-CE	\$7,500
BALAZS ANALYTICAL LABORATORY (Shipper)	Offered hydrofluoric acid for transportation in nonspecification packaging; failed to mark packaging containing hydrofluoric acid with a proper shipping name. [173.264(a), 172.301(a)] Case No. 93-53-SB-WE	\$1,900
BARRY WAYNE MACEY (Cylinder Retester)	Certified and marked cylinders as retested without performing retesting; failed to hold a current approval or a retester's identification number (RIN). [173.34(e)(1)(ii), 173.34(e)(1)(i)] Case No. 92-46-CR-HQ	\$7,200

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

BAXTER DIAGNOSTICS INC (Shipper)	Offered methanol in unauthorized nonspecification packaging. [173.119(b)] Case No. 94-90-SB-SW	\$3,240
BAXTER HEALTH CARE (Fiberboard Box Manufacturer/Shipper)	Certified fiberboard boxes as UN standard 4G without performing design qualification tests and maintaining records of tests; failed to mark UN 4G boxes with the correct year of manufacture. [178.601(d), 178.503(a)(6)] Case No. 94-234-BMS-CE	\$9,240
BAY CORRUGATED CONTAINER INC (Fiberboard Box Manufacturer)	Certified fiberboard boxes as DOT-12B40 that were constructed with fiberboard of insufficient strength and had inner flaps that failed to butt; failed to mark boxes with the name and address or registered symbol of manufacturer. [178.205-14(a), 178.205-18(a)] Case No. 95-02-BM-CE	\$7,000
BEASLEY FIRE EXTINGUISHER SERVICE (Cylinder Retester)	Failed to hold a current approval or RIN; failed to maintain adequate records of reinspection and retest. [173.34(e)(1)(i), 173.34(e)(5)] Case No. 93-164-CR-HQ	\$3,600
BEAUMONT FIRE EXTINGUISHER SERVICE (Cylinder Retester)	Certified cylinders with equipment not calibrated to 1% accuracy. [173.34(e)(3)] Case No. 94-187-CR-SW	\$3,650
BELL CONTAINER CORP (Fiberboard Box Manufacturer)	Certified fiberboard boxes as DOT 12B65 that were not constructed with fiberboard of sufficient strength. [178.205-16(a)] Case No. 95-119-BM-CE	\$4,600
BELL PACKAGING CORP (Fiberboard Box Manufacturer)	Certified fiberboard boxes as DOT12B65 when inner flaps did not meet and fill-in-pieces or pads were not included; failed to use fiberboard of sufficient strength. [178.205-16(a)] Case No. 94-261-BM-CE	\$4,960
BELL PACKAGING CORP (Fiberboard Box Manufacturer)	Certified fiberboard boxes as DOT-12B65 after 9/30/94 that were constructed with fiberboard that did not meet minimum test strength. [171.14(b)(5)(ii)] Case No. 95-106-BM-CE	\$7,190
BENNETT INDUSTRIES (Plastic Drum Manufacturer)	Certified plastic drums as UN1H1 without performing and keeping records for periodic drop, leakproofness, and hydrostatic tests; failed to mark year of manufacture in proper sequence; failed to conduct HM training. [178.601(e), 178.503(a), 172.704(d)] Case No. 94-260-PDM-CE	\$10,820

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

BERGEN BARRELL AND DRUM COMPANY (Plastic Drum Manufacturer)	Certified packagings as UN standard without marking name and address or registered symbol; failed to include required information in the certification marking; failed to mark proper country of manufacture on packaging; failed to keep test records. [178.503(a)(8), 178.502(a)(2)] Case No. 94-95-PC-CE	\$18,163
BEXAR FIRE & SAFETY EQUIPMENT COMPANY INC (Cylinder Retester)	Certified cylinders with equipment not calibrated to 1% accuracy; failed to increase test pressure by 10% or 100 psi on 2nd test; failed to maintain accurate records of reinspection and retest. [[173.34(e)(3), 173.34(e)(5)] Case No.94-184-CR-SW	\$9,600
BIG THREE LINCOLN ALASKA INC (Cylinder Retester)	Conducted hydrostatic testing with inaccurate equipment; failed to determine average minimum wall stress before marking cylinders with a '+'; failed to hold test pressure for at least 30 seconds; failed to use low stress stamps when marking DOT 3HT cylinders; failed to mark cylinders with the proper size markings; failed to check pressure after cool down of cylinders; failed to maintain records. [173.34(e)(3), 173.302(c)(3), 173.34(e)(3), 173.34(e)(13)(iv), 173.34(e)(6), 173.303(d)] Case No. 91-74-CR	\$5,750
BIO-LAB INC (Shipper)	Offered oxidizing substances, solid, N.O.S. for transportation in unauthorized nonspecification packaging. [173.154(a), 173.212(a)] Case No. 94-76-SB-WE	\$5,805
BIRKO CORP (Shipper)	Offered oxidizing substances, solid, in unauthorized packaging. [173.22(a)(2)] Case No. 94-171-SP-CE	\$3,600
BLACKHAWK GASES & SUPPLY COMPANY INC (Cylinder Retester)	Certified cylinders with equipment not calibrated to an accuracy of 1%; failed to increase test pressure by 100 psi or 10% for 2nd test; failed to maintain adequate records. [173.34(e)(3), 173.34(e)(5)] Case no. 93-269-CR-CE	\$6,460
BONAR PACKAGING INC (Plastic Bag Manufacturer)	Certified plastic film bags as UN 5H4 without maintaining design qualification and periodic test records. [178.601(k)] Case No. 94-157-BGM-SW	\$4,100
BOWMAN MELL AND CO INC (Shipper)	Offered paint, flammable liquid for transportation in nonspecification packaging and unauthorized DOT packaging. [173.128(a)] Case No. 92-144-SPB-EA	\$3,360
BOXES INC (Fiberboard Box Manufacturer)	Certified DOT-12B specification boxes after 10/01/94; failed to provide hazmat employee training. [171.14(b)(5), 172.702(a), 172.702(b)] Case No. 95-85-BM-CE	\$5,400

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

BRANDYWINE VALLEY FIRE & SAFETY (Cylinder Retester)	Failed to have an approval or a current RIN; performed retesting with inaccurate equipment; failed to remark aluminum exemption cylinders with DOT 3AL; failed to maintain adequate records of reinspection and retest. [173.34(e)(1)(i), 173.34(e)(3), 173.23(c), 173.34(e)(5)] Case No. 93-142-CR-EA	\$8,175
BRUIN ENGINEERED PARTS INC (Foreign Cylinder Manufacturer)	Manufactured, marked, and sold DOT 39 cylinders without completing the inspection process. [178.65-3(b), 173.300b] Case No. 90-90-FCM	\$9,396
BRULIN & CO INC (Shipper)	Offered corrosive liquid in nonspecification packaging; offered compound cleaning liquid in nonspecification packaging; failed to properly mark corrosive material with a proper shipping name. [173.245(a), 173.263(a), 173.301(a)] Case No. 93-99-SPB-CE	\$6,760
BURRIS CHEMICAL INC (Shipper)	Offered DOT specification 57 portable tanks without marking the most recent test date; offered HM in unauthorized nonspecification packaging. [173.32(e)(3), 173.163(a), 173.212] Case No. 94-55-SPT-HQ	\$5,228
BWI/IP INTERNATIONAL INC (Cylinder Manufacturer)	Represented and sold DOT-E 10757 exemption cylinders as meeting the requirements of the exemption without performing hydrostatic testing; failed to have testing verified by an approved independent inspection agency; failed to include the exemption number in the shipping description on shipping papers. [178.2(b), 178.65-3(b), 173.203(a)] Case No. 93-168-CM-HQ	\$6,820
CAJUN BAG & SUPPLY CO (Bag Manufacturer)	Represented, marked, and sold exemption bulk bags which were not capable of withstanding a four-foot drop test. [DOT-E 9144, Para. 7] Case No. 93-226-EX-CE	\$4,120
CALGENE CHEMICAL INC (Shipper)	Offered HM for transportation without being registered under RSPA's registration program. [107.608(a)] Case No. 95-70-REG-CE	\$250
CANBERRA CORP (Shipper)	Offering hydrochloric acid, solution, in nonspecification packaging. [173.263(a)] Case No. 93-98-SB-CE	\$3,240

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

CAPITAL CITY FIRE EXTINGUISHER SERVICE CO (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; exceeded 90% of test pressure prior to performing hydrostatic testing; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(3), 173.34(e)(5)] Case No. 93-57-CR-CE	\$5,100
CAPWELD INC (Cylinder Retester)	Certified cylinders with inaccurate equipment; failed to maintain accurate records; failed to calculate wall stress when marking cylinders with a '+'; failed to remark exemption DOT-E 6498 cylinders with specification 3AL. [173.34(e)(3), 173.34(e)(5), 171.2(c), 173.23(c)] Case No. 94-120-CR-SW	\$10,250
CARLISLE PLASTICS INC D/B/A BERCON PACKAGING (Plastic Bottle Manufacturer)	Manufactured, marked, and sold plastic bottles as DOT specification 2E without conducting periodic drop testing on the top edge or a weaker part; failed to conduct periodic cold drop tests; failed to mark the packaging with the manufacturer name and address or registered symbol. [178.24a-5(d)(1), 178.24a-5(c), 173.24(c)] Case No. 93-193-PBM-EA	\$7,500
CAROLINA SAFETY ASSOCIATES INC (Cylinder Retester)	Failed to condemn cylinders when the permanent expansion exceeded 10%; conducted hydrostatic testing with equipment which could not be verified as accurate to 1%; failed to maintain accurate records. [173.34(e)(4), 173.34(e)(3), 173.34(e)(5)] Case No. 93-197-CR-EA	\$7,530
CAROLINA SOLVENTS INC (Drum Reconditioner/Shipper)	Certified steel drums as DOT-17E without conducting leakage tests; offered methyl propyl ketone in unauthorized nonspecification packaging. [173.28(m)(2), 173.242(c), 173.119(b)] Case No. 94-138-DR-HQ	\$6,500
CHARLES GRATZ FIRE PROTECTION (Cylinder Retester)	Failed to have current approval and RIN; failed to remark exemption aluminum cylinders as DOT specification 3AL; failed to perform a complete visual external examination. [173.34(e)(1)(i), 173.23(c), 173.34(e)(1)] Case No. 93-155-CR-EA	\$3,100
CHEM-BRIGHT INDUSTRIES INC (Shipper)	Offered hydrochloric acid and hypochlorite solution in nonspecification packaging under the authority of an exemption that had expired. [173.263(a), 173.277(a)] Case No. 92-127-EXR	\$5,000
CHEMCENTRAL CORP (Shipper)	Offered acetone, a flammable liquid with a flash point below 20 degrees Fahrenheit, for transportation in unauthorized DOT packaging. [173.119(a)(3)] Case No. 93-47-SD-HQ	\$4,300

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

CHEMICAL COMMODITIES AGENCIES INC (Shipper)	Allowed an employee to perform a function subject to the HMR, when the employee had not received HM training. [172.702] Case No. 95-71-TRN-WE	\$1,200
CHICAGO STEEL CONTAINER CORP (Steel Drum Manufacturer)	Failed to pass four-foot drop test on DOT 17H drums; failed to conduct periodic drop and hydrostatic tests on DOT 17E drums; failed to conduct periodic drop and hydrostatic tests on DOT 17H drums; failed to conduct design qualification tests for UN 1A1 and UN1A2 drums. [178.118-12(a), 178.116-12(a)(1), 178.116-12(a)(2), 178.118-12(a)(1), 178.118-12(a)(2), 178.601(d)] Case No. 93-32-DM-CE	\$18,000
CHUCK'S FIRE & SAFETY CONTROL (Cylinder Retester)	Represented and marked cylinders as having been retested without holding a current RIN. [173.34(e)(1)(i), 173.34(e)(1)] Case No. 91-04-CR	\$3,000
CITY CHEMICAL CORP (Shipper)	Offered ethyl acetate, flammable liquid, in nonspecification packaging; offered tetrahydrofuran, flammable liquid, in unauthorized inner glass bottles in DOT 12B boxes; failed to mark packages with the UN ID number; failed to label packages as required; failed to indicate RQ in the proper sequence on a shipping paper. [173.119(b), 173.119(a)(7), 172.301(a), 172.400(a), 172.201(a)(4)] Case No. 92-92-SB-EA	\$4,000
CKS PACKAGING INC (Plastic Bottle Manufacturer)	Manufactured plastic bottles as DOT-2E without performing ambient and cold drop tests in outer packaging; manufactured plastic bottles as DOT-2U bottles without performing vibration tests in outer packaging. [178.24-7(a)(1), 178.24-7(a)(3)] Case No. 94-204-PBM-EA	\$8,800
CLAYTON CONTAINER COMPANY INC (Fiberboard Box Manufacturer)	Certified boxes as DOT-12B when inner flaps did not butt and fill-in pieces or pads were not included. [178.205-14(a)] Case No. 94-197-BM-EA	\$5,100
CLEVELAND CONTAINER CORP (Plastic Drum Manufacturer)	Manufactured, marked and sold plastic packagings as DOT specification 35 without drop testing 1 of every 10,000 produced; failed to perform design qualification tests; failed to apply required markings. [178.16-16(a), 178.601(d), 178.603(e), 178.601(k)(1), 172.2(f), 178.503(a)(6), 178.503(a)(7)] Case No. 94-34-PDM-CE	\$10,600



## Research and Special Programs Administration Penalty Actions Report (1994-1995)

CLOVER LEASING CO (Cylinder Retester)	Performed hydrostatic testing with inaccurate equipment; failed to maintain accurate records; failed to legibly mark cylinders; failed to increase pressure by 10% or 100 psi on 2nd test; failed to properly mark FRP cylinders; failed to properly affix its RIN to FRP cylinders. [173.34(e)(3), 173.34(e)(5), 173.34(c), 173.34(e)(3), 173.34(e)(1), DOT-E 7277, Para. 8f] Case No. 92-64-CR-CE	\$8,500
COFFEYVILLE RE- CON INC (Drum Reconditioner)	Certified, marked, and sold reconditioned steel drums as meeting the DOT17E specification, when they were not authorized for reuse. [173.28(m)] Case No. 94-92-DR-SW	\$4,650
COLLINS FIRE EXTINGUISHER INC (Cylinder Retester)	Certified cylinders without performing retests at the minimum test pressure. [173.34(e)] Case No. 95-167-CR-HQ	\$3,650
COLUMBUS FIRE & SAFETY EQUIPMENT CO INC (Cylinder Retester)	Failed to condemn cylinders when permanent expansion exceeded 10% of total expansion; conducted hydrostatic testing with equipment not calibrated to 1% accuracy; failed to maintain accurate records; failed to conduct employee training. [173.34(e)(4), 173.34(e)(3), 173.34(e)(5), 172.700] Case No. 94-210-CR-EA	\$10,000
CONSOLIDATED CONTAINER CORP (Drum Reconditioner)	Certified remanufactured steel drums as DOT 17H without conducting drop and hydrostatic testing. [178.116-12(a)] Case No. 94-60-DR-CE	\$4,650
CONSTAR PLASTICS INC (Plastic Bottle Manufacturer)	Represented plastic bottles as DOT specification 2E without conducting the required number of ambient drop tests; failed to conduct drop tests on top edge or weaker part; failed to conduct drop tests on DOT specification 2U plastic bottles. [178.24a-5(b), 178.24a-5(d)(1), 178.0-2(c), 178.24-7(a)(1), 178.24-7(a)(2), 178.0-2(c), 178.24-7(a)(3)] Case No. 93-116-PBM-EA	\$12,042
CONSTAR PLASTICS INC (Plastic Bottle Manufacturer)	Represented plastic bottles as DOT specification 2E without conducting the required number of ambient drop tests. [178.24a-5(b)] Case No. 93-202-PBM-EA	\$8,032
CONSTRUCTION TECHNOLOGY LABORATORIES INC (Package Certifier)	Certified steel drums to a UN standard without properly identifying the package's construction material. [178.502(a)(2)] Case No. 94-130-PC-CE	\$600

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

CONTAINER CORP OF AMERICA INC (Fiberboard Box Manufacturer)	Certified fiberboard boxes as DOT 12B when inner flaps did not butt and fill-in pieces or pads were not included; failed to properly mark boxes with the name and address or symbol of the manufacturer. [178.0-2, 178.205-14(a), 178.205-18(a)] Case No. 94-25-BM-CE	\$4,000
CONTAINER-QUINN TESTING LABORATORIES INC (Package Certifier)	Issued a UN package certification which failed to include the approval agency's name and ID code; issued a package certification which failed to include a separate 4-digit number for each certified package; issued approval certificates which failed to contain the letter 'S' for UN packages intended to contain inner packagings; failed to maintain complete records of design qualification tests. [107.404(a)(2), 107.404(c), 178.503(a)(5), 178.602(k)(1)] Case No. 94-82-PC-CE	\$3,840
CONTAINER-QUINN TESTING LABORATORIES INC (Package Certifier)	Certified fiberboard boxes as UN 4G without performing design qualification tests. [178.601(d)] Case No. 95-109-PC-CE	\$1,900
CORAL INTERNATIONAL INC (Shipper)	Offered hydrochloric acid solution in unauthorized nonspecification packaging. [173.263(a)] Case No. 94-118-SB-CE	\$3,500
CORRUGATED PAPER PRODUCTS INC (Fiberboard Box Manufacturer)	Certified boxes as DOT-12B with gross weight markings that exceeded the maximum authorized weight; failed to include fill-in pieces or pads when inner flaps did not butt. [178.205(16)(a)] Case No. 94-287-BM-CE	\$7,200
COSTA CHEMICAL CORP (Shipper)	Failed to include the technical name as part of the proper shipping name marking on the packaging. [172.301(c), 173.125(a), 172.202(a)(3), 172.203(k), 173.125(a)] Case No. 91-155-SB.	\$2,450
COTTER & COMPANY (Shipper)	Offered compound cleaning liquid, corrosive material, for transportation in nonspecification packagings. [173.245(a)] Case No. 93-91-SB-CE	\$3,225
COURTAULDS AEROSPACE (Fiberboard Box Manufacturer/Shipper)	Certified boxes as UN 4G without performing design qualification tests; failed to perform periodic retests; failed to keep complete records of design qualification tests. [178.601(d), 178.601(e), 178.601(d), 178.601(k)(1)] Case No. 95-91-BMS-SW	\$17,895

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

CRANSTON WELDING SUPPLY COMPANY INC (Cylinder Retester)	Certified cylinders without increasing test pressure by 100 psi or 10% when conducting 2nd test; conducted testing with equipment not calibrated to 1% accuracy. [173.34(e)(3), 173.34(e)(3)] Case No. 95-52-CR-EA	\$5,000
CROSS CONTAINER CORP (Fiberboard Box Manufacturer)	Represented, manufactured, marked, and sold fiberboard boxes as meeting the DOT 12B65 specification, when the boxes were of insufficient strength to meet that specification. [178.205-15(a), 178.205-16(a)] Case No. 93-156-BM-CE	\$3,400
CUSTOM DELIVERIES INC C/O LEASEWAY TRANSPORTATION CORP (Shipper)	Failed to properly mark, label, and package batteries, wet filled with acid, for transportation. [172.301(a), 172.400(a), 173.159(a)] Case No. 93-149-BAT-HQ	\$1,443
CUYAHOGA CHEMICAL COMPANY (Shipper)	Offered acetone, a flammable liquid with a flash point below 20 degrees Fahrenheit, in unauthorized DOT drums. [173.119(a)(3)] Case No. 91-97-SD	\$2,700
CYL-TEC INC (Cylinder Retester)	Performed hydrostatic retesting with equipment which was not accurate to within 1%. [173.34(e)(3)] Case No. 92-62-CR-CE	\$2,500
CYL-TEC INC (Shipper)	Failure to register with RSPA when offering HM of one hazard class in non-bulk packaging in excess of 5000 pounds. [107.608(a)]  Case No. 95-112-REG-CE	\$250
DAISY MANUFACTURING COMPANY INC (Shipper)	Offered a new unapproved explosive for transportation. [173.54(a), 173.56(b)(1)] Case No. 94-100-SE-SW.	\$4,000
DAMERON FIRE EQUIPMENT CO (Cylinder Retester)	Failed to hold a current approval and RIN; failed to maintain accurate records of reinspection and retest. [173.34(e)(1)(i), 173.34(e)(5)] Case No. 93-160-CR-HQ	\$2,700
DELTA DRUM INC (Plastic Drum Manufacturer)	Certified UN 1H1 drums without performing the required leakproofness testing during production and as part of periodic testing. [178.601(e), 178.604(a), 178.604(b)] Case No. 94-241-PDM-CE	\$4,000

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

DEPENDABLE CONSTRUCTION SUPPLY INC (Shipper)	Offered corrosive liquid n.o.s. for transportation in nonspecification packaging; failed to mark proper shipping name or ID number on the package; failed to mark "This Side Up or This End Up" on the packaging. [172.301(a), 173.245(a), 172.202(a)(1)-(3), 172.312(a)] Case No. 91-30-SB	\$4,000
DEPENDABLE FIRE EQUIPMENT CO INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; certified exemption aluminum cylinders without remarking them 3AL; failed to maintain accurate records of reinspection and retest; conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when the accuracy of the system could not be maintained due to equipment failure. [173.34(e)(3), 173.23(c), 173.34(e)(5), 173.34(e)(3)] Case No. 92-35-CR-EA	\$1,000
DETYANS SHIPYARD INC (Cylinder Retester)	Certified cylinders without increasing test pressure by 100 psi or 10% on 2nd test; failed to insure equipment was accurate to within 1%; failed to mark RIN in clockwise pattern; failed to maintain training records. [173.34(e)(3), 173.34(e)(3), 173.34(e)(6), 172.700] Case No. 94-132-CR-EA	\$7,900
DIGICOURSE INC (Fiberboard Box Manufacturer)	Certified package as UN4G without conducting design qualification tests. [178.603(a), 178.606(a)] Case No. 93-230-BM-CE	\$6,300
DOUGLAS PRODUCTS & PACKAGING CO INC (Shipper)	Offered poison B in nonspecification packagings; failed to properly label a HM package; failed to properly mark a HM package; failed to prepare shipping papers; failed to mark a package for proper container orientation. [173.357(a), 172.400(a), 172.301(a), 172.202(a)(3), 172.312(a)(2)] Case No. 93-69-SB-WE	\$10,300
DOWELL SCHLUMBERGER INC (Shipper)	Offered a corrosive material under the terms of an expired exemption DOT-E 3095 which resulted in the use an unauthorized nonspecification packaging. [173.245, 173.202] Case No. 94-203-EXR	\$5,000
DPC INDUSTRIES INC (Cylinder Retester)	Certified cylinders without increasing test pressure by 100 psi or 10% when conducting a 2nd test; performed hydrostatic retesting with inaccurate equipment; failed to insure markings were legible. [173.34(e)(3), 173.34(e)(3), 173.34(e)(6)] Case No. 94-192-CR-CE	\$7,350
DURALE PLASTICS INC (Fiberboard Box Manufacturer/Shipper)	Certified boxes as DOT-12B40 when inner flaps did not butt and fill-in pieces and pads were not included; failed to mark boxes with the name and address or registered symbol of the box manufacturer. [178.205-14(a), 178.205-18(a)(2)] Case No. 94-271-BMS-CE	\$3,680

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

DYMON INC (Shipper)	Offered compound cleaning liquid in unauthorized nonspecification packaging; provided additional information within the HM shipping description on a shipping paper. [173.203(a), 173.245(a), 172.101, 172.201(a)(4)] Case No. 93-134-SP-WE	\$3,200
E G & G IDAHO INC (Cylinder Retester)	Failed to remark exemption aluminum cylinders as DOT 3AL; failed to hold a current approval or RIN. [173.23(c), 173.34(e)(1)(i)] Case No. 93-55-CR-WE	\$4,000
E I DUPONT DE NEMOURS COMPANY (Shipper)	Offered HM under the terms of an expired exemption, DOT-E 10660, which resulted in improper labeling of the material. [172.402(a)(1)] Case No. 94-208-EXR	\$4,700
E P W DISTRIBUTION CENTER INC (Cylinder Retester)	Failed to hold current approval and RIN; failed to maintain accurate records. [173.34(e)(1)(i), 173.34(e)(5)] Case No. 93-03-CR-CE	\$2,410
EAGLE-PICHER INDUSTRIES INC (Shipper)	Offered methanol, a flammable liquid, in a DOT specification 12A box, a nonreusable packaging, which had been previously used. [173.119(b)] Case No. 94-89-SB-SW	\$3,400
EASTERN WELDING SUPPLY CO (Shipper)	Failed to submit a complete and accurate registration statement to RSPA. [107.608(a)] Case No. 94-127-SC-CE	\$250
ELGIN CORRUGATED BOX COMPANY (Fiberboard Box Manufacturer)	Manufactured, marked, and certified fiberboard boxes as DOT 12B when inner flaps did not butt and fill-in pieces or pads were not provided. [178.205-14] Case No. 93-237-BM-CE.	\$3,000
ENGINEERED MATERIALS SYSTEMS INC (Fiberboard Box Manufacturer/Shipper)	Certified boxes as meeting the UN 4G standard with an unauthorized duplicate symbol; failed to perform design qualification testing; failed to mark packages with correct year of manufacture; failed to conduct employee HM training. [178.2(b)(2), 178.503(a)(8), 178.601(d), 178.601(k)(1), 178.503(a)(6), 172.702, 172.704] Case No. 94-36-SMB-CE	\$8,450
ETHOX CHEMICALS INC (Shipper)	Offered corrosive liquids in unauthorized nonspecification packaging; failed to provide a proper shipping description on a shipping paper by using unauthorized abbreviations. [173.245, 173.203, 172.201(a)(3)] Case No. 94-190-SD-HQ	\$5,050

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

EXIDE CORP (Shipper)	Failed to provide training to HM employees. [172.702(b)] Case No. 95-82-TRN-HQ	\$1,200
EXPLOSIVES TECHNOLOGIES INTERNATIONAL INC (Shipper)	Offered a new explosive for transportation that was forbidden, because it had not been examined, classified, and approved. [173.86(b), 173.51(b)] Case No. 92-105-SE-HQ	\$5,000
FARMINGTON FIRE EQUIPMENT & SAFETY (Cylinder Retester)	Failed to determine average or minimum wall stress for cylinders being marked with '+' marks to indicate 10% overfill authorization; failed to maintain accurate records of reinspection and retest. [173.302(c)(3), 173.302(c)(5), 173.32(e)(5)] Case No. 93-27-CR-WE	\$3,900
FIBERGLASS HAWAII INC (Shipper)	Failed to mark packages of flammable liquid and organic peroxide with the proper shipping name and ID number; offered flammable liquid and organic peroxide in nonspecification packaging; failed to mark proper orientation on packages of HM; provided additional information within the HM shipping description on a shipping paper. [173.301(a), 173.119(a), 173.221(a), 172.312(a)(2), 172.201(a)(4)] Case No. 93-56-SB-WE	\$8,900
FIRE EXTINGUISHER SERVICE (Cylinder Retester)	Performed retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest; failed to remark exemption aluminum cylinders as 3AL; failed to mark cylinders with legible markings. [173.34(e)(3), 173.34(e)(5), 173.23(c), 173.34(c)] Case No. 91-83-CR	\$4,200
FIRE EXTINGUISHER SERVICE CENTER INC (Cylinder Retester)	Performed hydrostatic testing with inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5), 173.34(e)(1)(v)] Case No. 91-145-CR	\$4,900
FIRE FIGHTER SALES & SERVICE INC (Cylinder Retester)	Failed to increase test pressure by 100 psi or 10% when retesting the cylinder a second time. [173.34(e)(3)] Case No. 94-38-CR-HQ	\$2,000
FIRE SAFETY SALES & SERVICE INC (Cylinder Retester)	Certified DOT specification cylinders with equipment not calibrated to 1% accuracy. [173.34(e)(3)] Case No. 95-127-CR-SW	\$2,920

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

FIRELINE CORP (Cylinder Retester)	Failed to increase test pressure by 100 psi or 10% on second test, when the accuracy of the system could not be maintained due to equipment failure; failed to mark cylinders with RIN. [173.34(e)(3), 173.34(e)(6)] Case No. 94-40-CR-HQ	\$3,000
FISHER GLASS D/B/A STOCKTON FIRE EQUIPMENT CO (Cylinder Retester)	Conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 92-97-CR-WE	\$1,500
FLORIDA DRUM COMPANY INC (Plastic Drum Manufacturer)	Certified UN 1H1 and 3H1 plastic containers without conducting leakproofness tests. [178.604(e)] Case No. 95-66-PDM-SW	\$5,250
FLUKA CHEMICAL CORP (Shipper)	Offered poisonous liquid, corrosive, n.o.s. for transportation by water, when the exemption under which it was being offered did not authorize transportation by water. [173.3a(a)(3), 173.227] Case No. 93-92-SB-HQ	\$3,600
FRANK POPLA BARREL CO INC (Drum Reconditioner)	Failed to conduct on-line leakage test on drums marked DOT 17E; failed to mark drums with the proper DOT registration number. [173.28(m)(2), 173.28(m)(3)(ii)] Case No. 93-189-DR-EA	\$3,200
FRANK W KERR CHEMICAL COMPANY (Shipper)	Offered denatured alcohol in unauthorized nonspecification packaging; failed to describe a HM with the proper shipping name on a shipping paper; failed to list the shipping description in the proper sequence on the shipping paper; failed to sign the shipper's certification. [173.125(a), 172.202(a)(1), 172.202(b), 172.204(d)(1)] Case No. 91-151-SB	\$3,680
FRANK'S DIVE SHOP INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 91-152-CR	\$3,200
FREMONT INDUSTRIES INC (Shipper)	Offered chromic acid mixture dry, oxidizer, in an unauthorized DOT specification packaging. [173.164(a)] Case No. 93-120-SP-HQ	\$2,900

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

FRESH PRODUCT INC (Fiberboard Box Manufacturer)	Certified fiberboard boxes as UN4G without conducting the stacking test; failed to maintain complete design qualification test records; failed to mark boxes with the correct year of manufacture. [178.601(d), 178.602(d), 178.601(k)(1), 178.503(a)(7)] Case No. 94-35-BM-CE	\$6,500
FRESNO CARBONIC INC (Cylinder Retester)	Marked cylinders with the '+' sign without calculating wall stress; failed to maintain accurate records. [173.302(c)(5), 173.34(e)(5)] Case No. 93-127-CR-WE	\$3,800
G & W ELECTRIC COMPANY INC (Shipper)	Offered an unapproved explosive for transportation; failed to fully describe a HM on a shipping paper; failed to provide a monitored 24-hour emergency response telephone number on the shipping paper; failed to provide employees with HM training. [173.51(b), 172.200(a), 172.201(d), 172.604(a)(1), 172.704(a)(2)] Case No. 94-140-SE-CE	\$7,680
G C INDUSTRIES INC (Shipper)	Offered hydrogen sulfide in nonspecification packaging, under the terms of an exemption which had expired. [173.304] Case No. 92-02-EXR	\$3,298
G S PARSONS COMPANY (Cylinder Retester)	Failed to condemn a cylinder with a permanent expansion exceeding 10% of total expansion. [173.34(e)(4)] Case No. 93-04-CR-WE	\$4,788
GADSDEN FIRE EXTINGUISHER & CO2 SERVICE (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to conduct retests at minimum required test pressure; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e), 173.34(e)(5)] Case No. 91-62-CR	\$1,800
GAS TECH INC D/B/A ACETYLENE PRODUCTS CO (Cylinder Retester)	Marked cylinders with the '+' sign without calculating wall stress; marked cylinders as successfully retested before retests were conducted; failed to maintain accurate records. [173.302(c)(3), 173.302(c)(5), 173.34(e)(1)(ii), 173.34(e)(5)] Case No. 94-01-CR-CE	\$4,950
GAYNES TESTING LABORATORIES LTD (Package Certifier)	Certified a package to a higher gross mass than the weight at which it was tested; assigned an approval certificate and certification number to a package, when that certification number had already been assigned to a different package. [178.503(a)(4), 178.606(c)(1), 107.404(c), 171.2(f)(1)] Case No. 94-153-PC-CE	\$3,800



## Research and Special Programs Administration Penalty Actions Report (1994-1995)

GENERAL FIRE & SAFETY EQUIPMENT (Cylinder Retester)	Conducted hydrostatic testing with equipment not calibrated to an accuracy of 1%; failed to increase test pressure by 10% or 100psi, when the first test could not be maintained due to the failure of test equipment. [173.34(e)(3), 171.2(c)] Case No. 93-121-CR-CE	\$3,600
GENERAL FIRE AND SAFETY EQUIP OF DES MOINES INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records. [173.34(e)(3), 173.34(e)(5)] Case No. 93-52-CR-CE	\$3,300
GENERAL STEEL DRUM CORP (Steel Drum Manufacturer)	Failed to conduct drop and hydrostatic testing on drums marked DOT 17E and DOT 17H; failed to conduct design qualification testing on drums certified as UN1A1 and UN1A2 packages. [178.116-12(a), 178.118-8(c)(1)] Case No. 93-219-DM-EA	\$11,600
GETZ FIRE EQUIPMENT COMPANY INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records; conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; marked cylinders with a '+' sign without calculating wall stress. [173.34(e)(3), 173.34(e)(5), 173.34(e)(3), 173.302(c)] Case No. 92-130-CR-CE	\$5,625
GFEC INC (Cylinder Manufacturer)	Manufactured, marked, and sold cylinders after physical testing which included a yield strength determination in which the cross-head speed exceeded 1/8 inch per minute; provided a HM shipping description on a shipping paper that was out of sequence; failed to register with RSPA. [178.37-16(c)(4), 172.202(b), 107.608, 107.612] Case No. 94-67-CM-HQ	\$3,950
GOEX INTERNATIONAL INC (Shipper)	Offered class C explosives for transportation in unauthorized nonspecification packaging, under the terms of an exemption which had expired. [173.100(v)] Case No. 94-56-EXR	\$2,610
GOSS BROTHERS WELDING SUPPLY INC (Cylinder Retester)	Marked cylinders with a '+' sign without calculating wall stress; failed to maintain accurate records. [173.302(c)(3), 173.302(c)(5), 173.34(e)(5)] Case No. 93-38-CR-EA	\$4,460

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

GREAT WESTERN CHEMICAL COMPANY INC (Shipper)	Offered flammable liquid in unauthorized out-of-test DOT 57 portable tanks; offered hypochlorite solution in nonspecification packaging; failed to mark the proper shipping name and ID number on a package; offered oxidizer n.o.s. in nonspecification packaging; included additional information in the HM shipping description on a shipping paper; failed to indicate a HM shipping description in the proper sequence; failed to indicate the technical name of the material on the shipping paper. [173.32(e)(1)(ii), 173.277(a), 172.301(a), 173.154(a), 172.201(a)(4), 172.202(b), 172.203(k)] Case No. 92-19-SPTB	\$12,000
GREAT WESTERN CHEMICAL COMPANY INC (Shipper)	Offered sulfuric acid in unauthorized nonspecification packaging; failed to mark an exemption number in conjunction with the HM shipping description on a shipping paper. [173.242, DOT-E9052 para. (7)(h), 172.203(a)] Case No. 94-13-SPT-WE	\$10,495
GRECO WELDING SUPPLIES INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to condemn cylinders with permanent expansion exceeding 10% of total expansion; failed to maintain accurate records; failed to mark exemption cylinders with the RIN by stamping or labeling. [173.34(e)(3), 173.34(e)(4), 173.34(e)(5), 173.34(e)(6), DOT-E 7277] Case No. 92-94-CR-EA	\$11,400
GREERS SUPPLY COMPANY INC (Cylinder Retester)	Conducted hydrostatic testing with test equipment not accurate to one percent of test pressure and/or total expansion. [173.34(e)(3)] Case No. 93-126-CR-HQ	\$3,240
GREIF BROS CORP (Fiber Drum Manufacturer)	Manufactured, marked, and sold fiber drums as DOT-21C drums without conditioning drums 48 hours before testing; manufactured, marked and sold drums as meeting the UN 1G standard without conducting drop and stacking tests; failed to mark UN certification information in proper sequence. [178.224-2(a), 178.601(e), 178.503(a)] Case No. 94-21-FDM-CE	\$10,600
GREIF BROS CORP (Fiberboard Box Manufacturer)	Certified fiberboard boxes as DOT 12B, when inner flaps did not butt and fill-in pieces or pads were not included. [178.205-14(a), 178.0-2] Case No. 93-253-BM-CE	\$4,155
GREIF BROS CORP (Plastic Drum Manufacturer)	Manufactured, marked, and sold UN 1H1 drums without conducting and recording periodic drop, leakproofness, hydrostatic, and stacking tests. [178.603, 178.601(f)] Case No. 93-240-PDM-CE	\$10,400

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

GRIFFIN AND ASSOCIATES (Cylinder Retester)	Failed to condemn cylinders when permanent expansion exceeded 10% of total expansion; represented cylinders as tested without conducting the test; represented cylinders as meeting the requirements of the regulations while marking them with illegible markings. [173.34(e)(4), 173.34(e)(1)(ii), 173.34(c), 173.34(e)(6)] Case No. 93-137-CR-EA	\$5,500
GROW GROUP INC (Shipper)	Offered trichloroisocyanuric acid dry, oxidizer, in nonspecification packaging; failed to sign the shipper's certification on the shipping paper. [173.217(a), 173.212(a), 172.204(d)] Case No. 93-166-SB-EA	\$9,600
H B FULLER COMPANY INC (Shipper)	Offered potassium permanganate for transportation in unauthorized nonspecification packaging. [173.154(a)] Case No. 94-164-SB-CE	\$4,950
HALLIBURTON COMPANY INC (Shipper)	Offered an unapproved explosive for transportation. [173.56(b)] Case No. 94-112-SE-HQ	\$15,400
HAMPTON BAY DIVERS D/B/A PECONIC SCUBA (Cylinder Retester)	Failed to have current RIN; performed retesting with inaccurate equipment; failed to remark exemption aluminum cylinders as DOT specification 3AL; failed to maintain accurate records. [173.34(e)(1)(i), 173.34(e)(3), 173.23(c), 173.34(e)(5)] Case No. 93-14-CR-EA	\$5,000
HARCROS CHEMICALS INC (Cylinder Retester)	Conducted testing with equipment not calibrated to one percent accuracy; offered butyl acetate, a flammable liquid, without a signed shipper's certification on the shipping paper. [173.34(e)(3), 172.204(d)] Case No. 93-256-CR-EA	\$7,840
HARCROS CHEMICALS INC (Shipper)	Offered HM under exemption without noting the exemption on the shipping paper; failed to have a signed shipper's certification on the shipping paper; certified ton tanks as retested without conducting the tests. [172.203(a), 172.204(d), 173.31(d)(3)] Case No. 94-172-STT-SW	\$13,300
HARRISON'S POOL EQUIPMENT INC (Shipper)	Failed to indicate the proper shipping name on the shipping paper. [172.202(a)(1)] Case No. 93-67-SB-WE	\$1,300

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

HASA INC (Shipper)	Offered hypochlorite solution, a corrosive material, in DOT-E 9052 portable tanks which had not been hydrostatically retested in accordance with the exemption; failed to list the proper exemption number on the shipping paper. [173.32(e)(1)(ii), 173.32(f), DOT-E 9052 para. 7.h., 172.203(a)] Case No. 93-254-SPT-WE	\$4,911
HEDWIN CORP (Plastic Pail Manufacturer)	Certified plastic drums as UN1H1 without maintaining records of periodic retest at each location where those drums were manufactured. [178.601(k)(3), 178.601(k)(1)] Case No. 94-258-PPM-CE	\$3,260
HITECH HOLDINGS INC (Shipper)	Offered explosive substances, classed as explosive A, in unauthorized nonspecification packaging. [173.64(a)] Case No. 93-233-SB-CE	\$2,250
HODGDON POWDER COMPANY INC (Shipper)	Offered an unapproved explosive for transportation; offered propellant explosive in previously used packaging without removing or obliterating the old markings. [173.86(b), 173.28(d)] Case No. 93-122-SE-CE	\$8,000
HOLSTON GASES INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to remark exemption aluminum cylinders as DOT 3AL. [173.34(e)(3), 173.23(c)] Case No. 93-162-CR-HQ	\$4,250
HOOK'S CLEAN CARE INC (Shipper)	Offered hydrochloric acid in unauthorized nonspecification packaging; provided a shipping paper that incorrectly identified the hazard class and volume of the material. [173.263(a), 172.202(a)(2)] Case No. 94-29-SB-CE	\$4,000
HOOKS CLEAN CARE INC (Cylinder Retester)	Certified cylinders with equipment not calibrated to 1% accuracy. [173.34(e)(4)] Case No. 94-107-CR-CE	\$2,500
HOOVER GROUP INC (Plastic Tank Manufacturer)	Manufactured, marked, and sold plastic portable tanks as meeting the requirements of DOT-E 9440, when the tanks could not withstand drop test requirements. [178.19-7(a), DOT-E 9440 para. 7.c.] Case No. 94-58-PTM-CE	\$5,480
HOPRICH COMPANY INC (Cylinder Retester)	Marked cylinders with a "+" mark without calculating average wall stress. [173.302(c)(3), 173.302(c)(5)] Case No. 94-128-CR-CE	\$3,655

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

HOUGHTON CHEMICAL CORP (Shipper)	Offered flammable liquid in a specification DOT 57 portable tank that had not been properly retested. [173.125(a)(1), 173.242(c)] Case No. 94-93-SPT-HQ	\$3,440
HOUSTON DISTRIBUTING INC (Shipper)	Failed to mark the HM ID number on drums; offered potassium permanganate in nonspecification packaging; provided additional information within the HM shipping description on a shipping paper; offered chromic acid solid in nonspecification packaging; failed to mark the proper shipping name and ID number on packages containing calcium hypochlorite. [172.301(a), 173.154(a), 172.201(a)(4), 173.164(a), 172.201(a)(4), 172.301(a)] Case No. 92-61-SD-HQ	\$5,500
HOWARD TERNES PACKAGING COMPANY (Shipper)	Offered an explosive for transportation under the terms of an exemption that had expired. [172.202(a), 172.301(a), 172.400(a), 173.62] Case No. 95-60-EXR	\$1,750
HUMMEL CROTON INC (Shipper)	Offered flammable solid in unauthorized nonspecification packaging; failed to identify a reportable quantity of HM by marking the letters RQ after the shipping description on the shipping paper. [173.189(a), 173.213(a), 172.203(c)(2)] Case No. 93-174-SD-WE	\$2,000
HUNTER CHEMICAL & FORMULATING CO INC (Shipper)	Offered corrosive liquid in unauthorized nonspecification packaging; failed to properly mark the packages; failed to provide HM training to employees; failed to indicate proper shipping name and ID number on shipping papers. [173.245(a), 172.301(a), 172.702, 172.202(a)] Case No. 94-232-SB-EA	\$11,440
I Q PRODUCTS COMPANY INC (Shipper)	Failed to indicate the proper shipping name and hazard class on a shipping paper; failed to provide HM training. [172.202(a), 172.704] Case No. 95-80-TRN-HQ	\$1,700
IDEAL CHEMICAL & SUPPLY COMPANY INC (Shipper)	Offered sodium hydroxide for transportation in exemption portable tanks that had not been retested as required. [173.32(e)(1)(ii), 173.32(f), DOT-E 9440, para, 7.g.] Case No. 95-53-SPT-SW	\$3,640
ILLINI FIRE EQUIPMENT CO (Cylinder Retester)	Certified cylinders with equipment not calibrated to 1% accuracy; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 93-249-CR-CE	\$4,825
IMC FERTILIZER GROUP INC (Shipper)	Failed to set brakes and block wheels on all rail tank cars while unloading HM after the expiration of an exemption. [174.67(a)(2)] Case No. 93-61-EXR	\$2,100

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

IND WELDING SUPPLY OF HATTIESBURG INC D/B/A NORDAN SMITH (Cyl Retester)	Certified cylinders with equipment not calibrated to 1% accuracy; failed to mark cylinders in a legible manner; failed to cover labels on a FRP cylinder with an epoxy coating. [173.34(e)(3), 173.34(e)(1)(ii), DOT-E 7277 para. 8.f.] Case No. 94-121-CR-SW	\$4,650
INDIANA OXYGEN COMPANY INC (Cylinder Retester)	Certified cylinders with equipment that was not calibrated to 1% accuracy; failed to determine the minimum or average wall stress for cylinders marked with a "+" mark to indicate authorization for 10% overfill. [173.34(e)(3), 173.302(c)] Case No. 93-96-CR-CE	\$5,700
INDUSTRIAL CHEMICALS CORP (Shipper)	Offered flammable liquids in unauthorized DOT specification packagings; failed to indicate the technical name of the HM on the shipping paper. [173.119, 172.203(k)] Case No. 93-117-SP-WE	\$5,000
INNERSPACE DIVE SHOP (MR JOHN MARSHALL) (Cylinder Retester)	Certified cylinders without holding a current approval or RIN. [173.34(e)(1)(i)] Case No. 94-179-CR-HQ	\$2,700
INSTA-FOAM PRODUCTS INC (Shipper)	Offered compressed gas for transportation in nonspecification packaging under the terms of an exemption that had expired. [173.315(a)] Case No. 93-111-EXR	\$2,000
INTERCONTINENTA L CHEMICAL CORP (Shipper)	Offered corrosive liquid in unauthorized nonspecification packaging. [173.245, 173.202(a)] Case No. 94-70-SB-CE	\$4,160
IOWA INTERSTATE RAILROAD (Shipper)	Offered and transported railroad track torpedoes, class B explosives, and railway fusees, flammable solid, in nonspecification packaging under the terms of an exemption which had expired. [173.154a, 173.91(f)] Case No. 91-93-EXR	\$1,350
ISO-SCIENCES LABORATORIES INC (Shipper)	Offered radioactive materials for transportation in a DOT 7A Type A package without having documentation of tests and an engineering evaluation for that package. [173.415(a)] Case No. 94-272-RMS-HQ	\$3,240
J G & J INC D/B/A ALPENA FIRE EQUIPMENT SALES & SERVICE (Cylinder Retester)	Certified cylinders with equipment not calibrated to 1% accuracy; failed to maintain accurate records of visual reinspection. [173.34(e)(3), 173.34(e)(5)] Case No. 94-249-CR-CE	\$3,320

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

J N JOHNSON SALES & SERVICE INC (Cylinder Retester)	Certified cylinders with equipment not calibrated to 1% accuracy; failed to conduct employee HM training. [173.34(e)(3), 172.704(a)(1)] Case No. 94-211-CR-CE	\$5,040
JACKSONVILLE WELDING SUPPLY INC (Cylinder Retester)	Certified cylinders with equipment not calibrated to 1% accuracy. [173.34(e)(3)] Case No. 95-173-CR-SW	\$3,650
JEFFERSON SMURFIT AND CONTAINER CORP OF AMERICA (Package Certifier)	Certified fiberboard boxes as UN 4G when boxes did not pass design qualification tests; issued one approval certificate for two different package designs; failed to mark UN4G box with name and address or registered symbol of package certifier. [178.601(d), 178.603(a), 107.404(c), 107.404(a)(3), 178.503(a)(8)] Case No. 94-156-PC-CE	\$4,000
JEFFERSON SMURFIT CORP (Fiberboard Box Manufacturer)	Certified boxes as DOT 12B when inner flaps did not butt and fill-in pieces or pads were not included. [178.205-14(a), 178.205-14(b)] Case No. 94-22-BM-CE	\$3,000
JONES CHEMICALS INC (Cylinder Retester/Shipper)	Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of visual reinspection; certified a 106A500X ton tank without performing the required tests. [173.34(e)(3), 173.34(e)(5), 173.31(d)(3)] Case No. 94-229-CRS-SW	\$6,700
JORGENSEN & COMPANY (Cylinder Retester)	Failed to calculate wall stress when marking a cylinder with a "+" plus sign. [173.302(c)] Case No. 94-02-CR-WE	\$3,600
KEN-MAR FIRE EXTINGUISHER COMPANY INC (Cylinder Retester)	Performed retesting with inaccurate equipment; marked cylinders with "+" mark without determining wall stress. [173.34(e)(3), 173.302(c)(3), 173.302(c)(5)] Case No. 93-17-CR-EA	\$5,800
KENNEL VACCINE SUPPLY INC (Shipper)	Offered flammable liquid in unauthorized nonspecification packaging; affixed warning label to the package that did not comply with size requirements. [173.125(a), 173.202(b), 172.407(c)] Case No. 93-267-SB-CE	\$3,023

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

KESCO INC (Shipper)	Offered an unapproved explosive for transportation; failed to mark the package with the proper ID number of the material; failed to mark the approval number on the package; failed to include the packing group and ID number on shipping paper. [173.56(b), 172.301(a), 173.320(a), 172.202(a), 172.202(a)(3)] Case No. 93-274-SE-EA	\$11,080
KIRCHNER FIRE EXTINGUISHERS INC (Cylinder Retester)	Retested a cylinder when test pressure and specification marks could not be determined due to illegible markings; failed to maintain accurate records. [173.34(e)(1)(ii), 173.34(c), 173.34(e)(5)] Case No. 92-125-CR-CE	\$3,300
KOCH INDUSTRIES INC (Shipper)	Offered flammable liquid for transportation in nonspecification packagings under the terms of an exemption that had expired. [173.119(a)] Case No. 94-145-EXR.	\$2,900
KUTOL PRODUCTS COMPANY INC (Shipper)	Offered ethanol solutions, flammable liquid, in unauthorized packaging. [173.125(a), 173.202(a)] Case No. 94-49-SB-CE	\$2,900
L H KELLOGG CHEMICAL CO INC D/B/A/ KELCO SUPPLY (Shipper)	Offered methanol in nonspecification packaging. [173.119(b)] Case No. 95-164-SB-CE	\$5,540
LANTIS PRODUCTIONS INC (Shipper)	Offered for transportation and transported an unapproved explosive device. [173.51(b), 173.86(b)] Case No. 91-106-SE	\$5,000
LAVERTY SUPPLY INC (Shipper)	Offered and transported blasting agents in nonspecification bulk packagings under the terms of an exemption that had expired. [173.114a(i)] Case No. 91-92-EXR	\$1,200
LEWISBURG CONTAINER CO INC (Fiberboard Box Manufacturer)	Manufactured, marked, and sold fiberboard boxes as meeting the DOT 12B specification which were not of sufficient strength; manufactured, marked and sold fiberboard boxes as meeting the DOT 12B specification when inner flaps did not butt and fill-in pieces or pads were not provided. [178.205-14(b), 178.205-16(a)] Case No. 93-261-BM-EA.	\$4,100
LILLY INDUSTRIES INC (Fiberboard Box Manufacturer/Shipper)	Certified boxes as UN 4G without conducting design qualification testing; failed to mark boxes properly. [178.601(d), 178.503(a)(5)(ii)] Case No. 94-236-BMS-CE	\$7,500



## Research and Special Programs Administration Penalty Actions Report (1994-1995)

LILYBLAD PETROLEUM INC (Shipper)	Offered gasoline, flammable liquid, in an unauthorized DOT packaging; failed to mark the technical name on the package; included additional unauthorized information in the shipping description on a shipping paper; failed to include the technical name in the shipping description. [173.119(a)(3), 172.301(c), 172.201(a)(4), 172.203(k)] Case No. 92-122-SD-WE	\$7,000
LINCOLN BIG THREE INC (Cylinder Retester)	Failed to condemn a cylinder with permanent expansion exceeding 10% of total expansion. [173.34(e)(4)] Case No. 93-213-CR-HQ.	\$4,500
LINCOLN WELDING SUPPLY INC (Cylinder Retester)	Performed hydrostatic testing with inaccurate equipment. [173.34(e)(3)] Case No. 94-243-CR-SW	\$3,440
LINWELD INC (Cylinder Retester)	Failed to determine the minimum or average wall stress for cylinders marked with a "+" mark to indicate authorization for 10% overfill. [173.302(c)(3), 173.302(c)(5)] Case No. 93-124-CR-CE.	\$3,050
LINWELD INC (Cylinder Retester)	Failed to condemn cylinders with permanent expansions exceeding 10% of total expansion; failed to provide employee function specific HM training. [173.34(e)(4), 172.702(b), 172.704(a)(2)] Case No. 94-53-CR-CE	\$7,125
LIQUID AIR CORP (Cylinder Retester)	Conducted a second retest at the same pressure rather than 10% or 100 psi higher, whichever is lower, when accuracy of the system cannot be maintained due to equipment failure. [173.34(e)(3)] Case No. 93-145-CR-WE.	\$3,870
LIQUID AIR CORP (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment. [173.34(e)(3)] Case No. 93-273-CR-WE	\$6,020
LIQUID CONTAINER LP (Plastic Bottle Manufacturer)	Certified DOT 2E bottles without performing required drop tests; failed to conduct required number of 3-per-1000 ambient drop tests on DOT 2E bottles. [178.24a-5(d)(1), 178.24a-5(b)] Case No. 94-78-PBM-CE	\$8,240
LITHO PHOTO INC (Shipper)	Offered sodium hydroxide in nonspecification packaging; failed to mark packages with the proper shipping name and ID number; failed to provide a shipping paper for sodium hydroxide; failed to include orientation marks on package. [172.301(a), 173.249, 172.202(a)(1), 173.312(a)(2)] Case No. 93-65-SB-WE	\$2,500

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

LND INCORPORATED (Shipper)	Offering HM in unauthorized packaging under the terms of an exemption which had expired. [173.302] Case No. 94-46-EXR	\$2,610
LONDON CHEMICAL COMPANY INC (Shipper)	Offered oxidizer for transportation in nonspecification packaging. [173.154(a)(12)] Case No. 93-90-SB-CE	\$3,825
LONG ISLAND FIRE PREVENTION INC (Cylinder Retester)	Performed hydrostatic testing with inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 93-15-CR-EA.	\$2,425
LOVE BOX COMPANY INC (Fiberboard Box Manufacturer)	Failed to conduct periodic retests, including drop and stack tests on fiberboard boxes marked as UN 4G; failed to maintain test records. [178.601(e), 178.601(k)(2), 178.603, 178.606] Case No. 94-109-BM-CE	\$4,680
LOVE BOX COMPANY INC (Fiberboard Box Manufacturer)	Failed to conduct design qualification tests, and maintain records of the tests on boxes marked UN4G; failed to mark UN4G with proper name and address or symbol. [178.601(d), 178.601(k)(1), 178.503(a)(8)] Case No. 94-31-BM-CE	\$7,320
LOVE BOX COMPANY INC (Fiberboard Box Manufacturer)	Certified boxes as DOT-12B when inner flaps did not butt and fill-in-pieces or pads were not provided. [178.205-14(a)] Case No. 95-103-BM-CE	\$3,600
LUND FIRE PRODUCTS COMPANY INC (Cylinder Retester)	Failed to hold current approval or RIN; performed hydrostatic retesting with inaccurate equipment; conducted a second test at the same pressure instead of 10% or 100 psi higher, whichever is lower, when the accuracy of the system could not be maintained due to equipment failure; failed to remark exemption aluminum cylinders as DOT 3AL; failed to properly mark RIN on cylinders; failed to include evidence of visual inspection on records. [173.34(e)(1)(i), 173.34(e)(3), 173.34(e)(3), 173.23(c), 173.34(e)(6), 173.34(e)(1)(ii), 173.34(e)(5)] Case No. 93-12-CR-EA.	\$7,000
LYNCH'S FIRE PROTECTION INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure. [173.34(e)(3), 173.34(e)(3)] Case No. 93-138-CR-CE	\$4,815

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

M & S FIRE AND SAFETY EQUIPMENT CO INC (Cylinder Retester)	Performed hydrostatic retesting on DOT cylinders with inaccurate equipment. [173.34(e)(3)] Case No. 94-154-CR-CE	\$3,900
MADISON RECHARGING SERVICE INC (Cylinder Retester)	Failed to hold an approval or current RIN (RIN); failed to condemn cylinders with permanent expansion exceeding 10% of total expansion. [173.34(e)(1)(i), 173.34(e)(4)] Case No. 93-263-CR-CE	\$7,225
MAINE OXY-ACETYLENE SUPPLY COMPANY INC (Cylinder Retester)	Failed to condemn cylinders with permanent expansion exceeding 10% of total expansion; failed to maintain test pressure for 30 seconds to secure complete expansion of the cylinder; performed hydrostatic retesting with inaccurate equipment; failed to determine the minimum or average wall stress for cylinders marked with "+" to indicate authorization of 10% overfill; failed to remark exemption aluminum cylinders 3AL; failed to maintain accurate records of reinspection and retest. [173.34(e)(4), 173.34(e)(3), 173.34(e)(3), 173.302(c)(3), 173.302(c)(5) 173.23(c), 173.34(e)(5)]  Case No. 93-80-CR-EA	\$16,110
MALLINCKRODT MEDICAL INC (Shipper)	Failed to provide employee HM training. [172.702] Case No. 95-140-TRN-HQ	\$2,400
MARATHON CARBONIC DIVISION OF GENERAL PARTS INC (Cylinder Retester)	Certified cylinders with inaccurate equipment; failed to hold test pressure for at least 30 seconds to secure complete expansion of the cylinder. [173.34(e)(3), 173.34(e)(3)] Case No. 94-87-CR-CE	\$6,640
MARK PACKAGING INC (Fiberboard Box Manufacturer)	Certified boxes as DOT-12B when inner flaps did not butt and fill-in pieces or pads were not included; certified boxes as DOT12B which were constructed of fiberboard of insufficient strength; failed to mark boxes with name and address or registered symbol. [178.205-14, 178.205-18(a)(2)] Case No. 94-282-BM-CE	\$6,150

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

MARTEL L GUAY & SONS INC (Cylinder Retester)	Failed to condemn DOT-E 7277 cylinders when permanent expansion exceeded maximum allowable limits; failed to conduct a complete visual examination; conducted testing with equipment not calibrated to 1% accuracy; failed to maintain accurate records of reinspection and retest. [173.34(e)(4), 173.34(e)(1), 173.34(e)(3), 173.34(e)(5)] Case No. 93-115-CR-EA	\$11,750
MARYLAND FIRE EQUIPMENT CORP (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment. [173.34(e)(3)] Case No. 93-112-CR-HQ.	\$3,600
MARYLAND STATE MANUFACTURING COMPANY INC (Shipper)	Offered unapproved explosive devices for transportation. [173.86(b), 173.86(b), 173.86(j)(3)] Case No. 92-76-SE-HQ	\$6,000
MASTER INDUSTRIES INC (Fiber Drum Manufacturer)	Failed to mark UN1G package with the address of the manufacturer or registered symbol; failed to train HM employees. [178.503(a)(8), 172.702(a)] Case No. 95-117-FDM-CE	\$2,030
MASTER PROTECTION CORP (Cylinder Retester)	Conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 94-06-CR-WE	\$8,625
MATHESON GAS PRODUCTS INC (Cylinder Retester)	Certified cylinders without performing test at minimum test pressure; failed to maintain accurate records of reinspection; failed to maintain a record of average daily compression for filling helium; failed to include the proper shipping name on a shipping paper for class 2.1 material. [173.34(e), 173.34(e)(10), 173.302(e), 172.202(a)(1)] Case No. 94-242-CR-SW	\$11,450
MAX BURTON ENTERPRISES INC (Shipper)	Offered butane in nonspecification packagings; failed to provide the HM shipping description first, in contrasting color, or in conjunction with an "X" in an HM column on the shipping paper; failed to include the proper shipping name on the shipping paper; failed to provide a 24-hour emergency response telephone number on the shipping paper. [173.304(d)(3), 172.201(a)(1), 172.202(a), 172.604(a)] Case No. 93-123-SC-WE	\$5,400

## Research and Special Programs Administration

### Penalty Actions Report (1994-1995)

MCCANN BARREL COMPANY INC (Drum Reconditioner)	Failed to conduct periodic drop and hydrostatic tests on remanufactured DOT 17E drums. [178.116-12(a)] Case No. 94-50-DR-CE	\$4,635
MCCOOK DRUM AND BARREL COMPANY INC (Drum Reconditioner)	Failed to conduct periodic drop and hydrostatic tests on remanufactured DOT 17E drums; failed to properly mark reconditioned DOT17H drums. [178.116-12(a)(1), 173.28(m)(3)] Case No. 94-27-DR-CE	\$5,485
MESSER GRESHEIM INDUSTRIES INC D/B/A MG INDUSTRIES (Cylinder Retester)	Failed to determine the minimum or average wall stress for cylinders marked with "+" mark to indicate authorization for 10% overfill. [171.2(c)] Case No. 93-150-CR-HQ	\$2,500
MEYER STEEL DRUM INC (Drum Manufacturer)	Failed to conduct periodic drop and hydrostatic tests on drums marked DOT 17E and DOT 17H; failed to conduct design qualification tests for UN1A1 and UN1A2 drums; failed to conduct on-line leakage tests for DOT17E and 17H drums; failed to properly mark UN1A1 and 1A2 drums. [178.116-12(a)(1), 178.116-12(a)(2), 178.118-12(a)(1), 178.118-12(a)(2), 178.601(d), 178.116-13(a), 178.118-13(a), 178.503(a)(6), 178.503(a)(8)] Case No. 93-33-DM-CE	\$9,000
MEYER STEEL DRUM INC (Drum Reconditioner)	Certified nonspecification steel drums as reconditioned DOT17E/17H; failed to test DOT 17C drums to a minimum air pressure of 15 psi. [173.28(o), 173.28(m)(2)] Case No. 94-03-DR-CE	\$4,500
MID-AMERICA STEEL DRUM COMPANY INC (Drum Reconditioner)	Failed to conduct periodic drop and hydrostatic tests on remanufactured DOT 17H drums. [178.118-12(a)] Case No. 94-51-DR-CE	\$2,500
MIDLAND CONTAINER CORP (Fiberboard Box Manufacturer)	Certified fiberboard boxes as DOT12B when inner flaps did not butt and fill-in pieces or pads were not included; certified boxes as DOT 12B when constructed of fiberboard of insufficient strength; failed to conduct design qualification tests and maintain records of the tests on UN4G packages; failed to conduct training for HM employees. [178.205-14(a), 178.205-16(a), 178.601(d), 172.702] Case No. 94-79-BM-CE	\$9,600
MILWAUKEE SOLVENTS & CHEMICALS CORP (Shipper)	Offered hexane, a flammable liquid with a flash point below 20 degrees Fahrenheit, in unauthorized DOT packaging. [173.119(a)(3)] Case No. 90-157-SD	\$1,800

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

MINERAL RESEARCH & DEVELOPMENT CORP (Shipper)	Offered zinc chloride solution, corrosive, in nonspecification packaging; failed to mark package with proper shipping name and ID number. [172.301(a), 173.245(a)] Case No. 93-05-SP-HQ	\$4,800
MINNESOTA MINING & MANUFACTURING COMPANY (Box Manufacturer/Shipper)	Certified boxes as UN 4G without conditioning them before conducting design qualification tests; failed to maintain records of periodic testing. [178.601(d), 178.602(d), 178.601(e), 178.601(k)(2)] Case No. 94-161-BM-CE	\$8,880
MINNTECH CORP (Shipper)	Offered HM without marking the proper shipping name and ID number on the package; offered oxidizer, corrosive liquid nos in DOT specification packaging not authorized for air transportation and in nonspecification inner packages; failed to include the proper shipping description on the shipping paper; failed to provide a shipper's certification on a shipping paper. [172.301(a), 173.245(a)(12), 172.202(a)(1)-(3), 172.204(a)] Case No. 92-83-SB	\$6,000
MINNTECH CORP (Shipper)	Failed to register with RSPA after offering for transportation 5,000 lbs or more of HM of 1 hazard class in non-bulk packaging in a single shipment requiring placarding. [107.601(e)] Case No. 95-158-REG-CE	\$315
MOORE DRUMS INC (Drum Reconditioner)	Failed to conduct required drop and hydrostatic tests on remanufactured steel drums marked DOT 17H. [178.118-12(a)] Case No. 94-54-DR-HQ	\$3,800
MORTON INTERNATIONAL INC (Fiberboard Box Manufacturer/Shipper)	Certified fiberboard boxes as UN 4G without conducting design qualification tests; failed to conduct periodic retests on UN 4G packages. [178.601(d), 178.601(e)] Case No. 94-104-BMS-CE	\$11,000
MORTON INTERNATIONAL INC (Shipper)	Offered boxes of Class C power devices in nonspecification packaging; failed to properly described HM on the shipping papers. [173.102, 172.202(a)(1), 172.202(a)(2)] Case No. 90-82-SB	\$1,500
MYERS CONTAINER CORP (Drum Manufacturer)	Manufactured, marked, certified, and sold drums as meeting the UN1A2/Y1.4/260 standard without performing design qualification tests. [178.601(d)] Case No. 93-225-DM-WE	\$7,900
MYERS CONTAINER CORP (Drum Reconditioner)	Failed to conduct periodic drop and hydrostatic tests on remanufactured DOT 17H drums. [178.118-12(a)] Case No. 93-182-DR-WE	\$3,440

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

NATIONAL FIRE EXTINGUISHER CO INC (Cylinder Retester)	Performed retesting with inaccurate equipment; failed to remark aluminum exemption cylinders as DOT 3AL; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.23(c), 173.34(e)(5)] Case No. 93-151-CR-EA	\$5,425
NATIONAL FIRE PROTECTION COMPANY (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to perform external visual inspection; failed to remark exemption aluminum cylinders as 3AL. [173.34(e)(3), 173.34(e)(1), 173.23(c)] Case No. 93-198-CR-EA	\$7,450
NATIONAL WELDERS SUPPLY COMPANY INC (Cylinder Retester/Shipper)	Conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to determine the minimum or average wall stress for cylinders marked with "+" mark to indicate authorization for 10% overfill; offered oxygen/nitrogen without verifying daily compression. [173.34(e)(3), 173.302(c)(3), 173.302(e)] Case No. 93-196-CR-EA	\$6,900
NFC CO INC D/B/A/ SUBURBAN CARBONIC INC (Shipper)	Failed to register with RSPA after offering in excess of 5,000 pounds of HM of the same hazard class in non-bulk packaging in a single shipment requiring placarding. [107.601(e)] Case No. 95-110-REG-CE	\$1,000
NILES CHEMICAL PAINT COMPANY (Box Manufacturer/Shipper)	Certified boxes as UN 4G when periodic drop and stacking tests were not conducted and records were not maintained; failed to mark UN 4G boxes with the date of manufacture. [178.601(e), 178.601(k)(2), 178.503(a)(6)] Case No. 94-259-BMS-CE	\$6,510
NORAC COMPANY THE INC (Shipper)	Offered organic peroxide in unauthorized packagings. [173.225(d)(2), 173.22(a)(2)] Case No. 93-251-SP-CE	\$4,120
NORTHEAST AIRGAS INC (Cylinder Retester)	Certified cylinders as retested without holding an approval or current RIN; failed to maintain accurate records of reinspection and retest; performed hydrostatic retesting with inaccurate equipment. [173.34(e)(1)(i), 173.34(e)(5), 173.34(e)(3)] Case No. 93-186-CR-EA	\$5,500
NORTHEAST BOX COMPANY (Fiberboard Box Manufacturer)	Certified boxes as DOT 12H when the minimum strength requirement was not met; failed to perform required testing on boxes marked DOT 12H. [178.209-11(a), 178.209-14, 178.209-15, 178.209-16] Case No. 93-191-BM-EA.	\$6,900

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

NOSTALGIA PYROTECHNICS (Shipper)	Offered new explosive which had not been examined, classed, and approved for transportation; offered Class B and C explosives in nonspecification packaging; offered a leaking explosive for transportation. [173.51(b), 173.86(b), 173.91, 173.108, 173.51(e)] Case No. 92-68-SE-CE	\$9,360
NUCLETRON CORP (Shipper)	Provided an emergency response phone number for which the answering person was not knowledgeable regarding the material being offered. [172.604(a)(3)] Case No. 94-74-RMS-HQ.	\$3,600
O'TOOLE AND NAPIER COURIERS INC (Shipper)	Accepted radioactive materials for transportation, when separation distances could not be met by driver; failed to maintain training records for HM employees; failed to provide emergency response information; failed to affix the proper hazard class label to the package. [177.842(b), 172.702(b), 172.602(c), 172.400] Case No. 94-98-RMS-HQ	\$11,750
OFFICIAL FIRE EQUIPMENT INC (Cylinder Retester)	Failed to condemn cylinders with permanent expansion exceeding 10% of total expansion; conducted a second retest at the same pressure instead of 10% or 100 psi, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to maintain accurate records or reinspection and retest. [173.34(e)(4), 173.34(e)(3), 173.34(e)(5)] Case No. 93-79-CR-EA	\$7,560
P B & S CHEMICAL COMPANY INC (Cylinder Retester)	Failed to conduct hydrostatic retesting at minimum test pressure. [173.34(e)] Case No. 94-115-CR-CE	\$2,420
P B & S CHEMICAL COMPANY INC (Shipper)	Offered flammable liquid in out-of-test DOT 57 portable tanks; offered oxidizing material in nonspecification packaging; failed to identify a hazardous substance on the shipping paper with the letters RQ; failed to include the proper shipping name on the shipping paper. [173.32(e)(1)(ii), 173.154(a)(9), 172.203(c)(2), 172.200(a)] Case No. 93-157-SPTD-CE	\$6,800
PACIFIC FIRE PROTECTION INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment. [173.34(e)(3)] Case No. 93-220-CR-WE	\$3,655
PACIFIC SCIENCES CORP (Shipper)	Offered ammonium hydroxide for transportation in nonspecification packaging. [173.245(a)] Case No. 92-102-SB-WE	\$2,200



## Research and Special Programs Administration Penalty Actions Report (1994-1995)

PAN-AM PLASTICS CORP (Plastic Bottle Manufacturer)	Failed to conduct periodic vibration testing on bottles marked DOT 2U; failed to properly mark DOT 2U bottles. [178.24-7(a)(3), 178.24-5(a)] Case No. 91-55-PLM	\$2,700
PARAGON PACKAGING INC (Plastic Bottle Manufacturer)	Failed to conduct cold drop testing on DOT 2E bottles; failed to properly mark DOT 2E bottles. [178.24a-5(d)(2), 178.24a-5(c), 178.24a-6(a)] Case No. 91-138-PBM	\$2,500
PARKS CORP (Shipper)	Offered acetone, naphtha, and denatured alcohol in quantities which exceeded the gross weight limit of the packaging; offered paint related material without marking the proper shipping name and ID number on the package. [173.119(a)(7), 178.205-16(a), 172.301(a)] Case No. 92-57-SB-HQ	\$5,500
PENN PLASTIC INCORPORATED (Plastic Bottle Manufacturer)	Failed to conduct cold drop tests on DOT 2E bottles; failed to conduct drop tests on bottles marked DOT 2U in the outer specification packaging; Failed to conduct ambient drop tests on DOT 2E bottles from the required height; failed to mark DOT 2E bottles with the minimum wall thickness. [178.24a-5(c), 178.0-2(c), 178.24a-5(d)(1), 178.24a-6(a)(1)] Case No. 94-77-PBM-EA	\$1,000
PERFORMANCE COATINGS INC (Shipper)	Offered flammable liquid in nonspecification packaging. [173.119(b), 173.202(a)] Case No. 93-247-SB-CE	\$3,450
PHOENIX FIRE & SAFETY EQUIPMENT (Cylinder Retester)	Failed to hold an approval or current RIN. [173.34(e)(1)(i)] Case No. 93-169-CR-WE	\$2,500
PIPE RECOVERY SYSTEMS INC (Cylinder Manufacturer)	Manufactured, represented, certified and sold cylinders as meeting the terms of an exemption, which were not manufactured in accordance with the requirements of the exemption. [DOT-E 7774 para. 7.a.] Case No. 94-178-CM-HQ	\$4,960
PLASTIPAK PACKAGING INC (Plastic Bottle Manufacturer)	Failed to conduct periodic ambient and cold drop tests on exemption plastic bottles in the outer package. [178.19-7, DOT-E 6614 para. 7.a.iii.] Case No. 94-16-PBM-CE	\$4,300

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

PLYMOUTH PACKAGING INC (Fiberboard Box Manufacturer)	Certified boxes as DOT 12B when inner flaps did not butt and fill- in pieces or pads were not included. [178.205-14] Case No. 93-211-BM-CE.	\$6,000
PRATT & LAMBERT INC (Shipper)	Offered paint for transportation in unauthorized nonspecification packaging. [173.242(c)] Case No. 94-105-SPT-CE	\$3,700
PRESSURE PRODUCTS INTERNATIONAL (Cylinder Manufacturer)	Manufactured, marked, certified, and sold cylinders as meeting DOT specifications, when required test reports were not reviewed and signed by an independent inspection agency. [178.45-3, 178.45-17(e)] Case No. 93-104-CM-HQ	\$1,163
PRESTON TRUCKING COMPANY INC (Nonvessel Operating Common Carrier)	Accepted poisonous liquid, corrosive, n.o.s. for water-borne transportation when the exemption under which it was being transported did not authorize transportation by water. [173.3(a)(3), 173.227] Case No. 93-93-NVO-HQ	\$2,700
PRILLAMAN CHEMICAL CORP (Cylinder Retester)	Failed to condemn a cylinder with a permanent expansion exceeding 10% of total expansion; conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to mark the RIN in square pattern; failed to test DOT cylinders to the minimum test pressure. [173.34(e)(4), 173.34(e)(3), 173.34(e)(1)(ii), 173.32(f)] Case No. 94-99-CR-EA	\$16,000
PURITAN-BENNET CORP (Cylinder Retester)	Conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when the accuracy of the system could not be maintained due to equipment failure; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 93-223-CR-EA	\$4,115
QUEEN CITY FIRE EQUIPMENT INC (Cylinder Retester)	Marked a DOT 3HT cylinder without using low stress steel stamps; failed to mark DOT-E 7277 cylinders with the proper date and RIN; failed to maintain records of employee's HM training. [173.34(e)(13)(iv), 173.34(e)(6), 172.702(a)] Case No. 94-238-CR-EA	\$6,480
QUINCY FIRE HEATING COMPANY (Cylinder Retester)	Failed to hold an approval or current RIN; failed to maintain records of reinspection and retest. [173.34(e)(1)(i), 173.34(e)(5)] Case No. 90-25-CR	\$2,500

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

RED BALL OXYGEN COMPANY INC (Cylinder Retester/Shipper)	Performed hydrostatic retesting on inaccurate equipment; failed to mark DOT 3HT cylinders with low stress steel stamps; failed to record and maintain a 30-day verification of container pressure. [173.34(e)(3), 173.34(e)(13)(iv), 173.303(d)] Case No. 95-43-CRS-SW	\$7,700
REESE MEDICAL OXYGEN SUPPLY INC (Cylinder Retester)	Marked and certified cylinders as retested without actually performing the tests; failed to have a current approval and RIN. [173.34(e)(1)(ii), 173.34(e)(1)(i)] Case No. 92-36-CR-HQ	\$10,000
RELIABLE CONTAINER INC (Fiberboard Box Manufacturer)	Certified packages as UN4G without conducting design qualification tests; certified fiberboard boxes as DOT 12A without conducting the required drop tests; failed to properly mark DOT 12A fiberboard boxes; failed to provide training for HM employees. [178.603, 178.210-10(a), 178.210-12(a)(1), 172.702(a)] Case No. 94-116-BM-CE	\$10,000
REMEL LIMITED PARTNERSHIP D/B/A/ REMEL (Box Manufacturer/Shipper)	Failed to mark UN packages with the proper UN certification number. [178.2(b), 178.2(d), 178.3(b)(3)] Case No. 94-102-BMS-CE	\$800
RHEE BROS INC (Shipper)	Offered HM for transportation without a HM shipping paper; failed to mark the outer package with the proper shipping name and ID number; failed to provide training to HM employees. [172.200(a), 172.301(a)(1), 172.702(b)] Case No. 94-217-SC-HQ	\$8,425
RICE WELDING SUPPLY COMPANY INC (Cylinder Retester)	Failed to determine average or maximum wall stress for cylinders being marked with a "+" sign to indicate 10% overfill authorization; failed to properly mark cylinders with the RIN. [173.302(c)(3), 173.34(e)(1)(ii), 173.34(e)(6)] Case No. 94-136-CR-SW	\$5,800
RING CAN CORP (Plastic Bottle Manufacturer)	Failed to conduct ambient and cold drop tests on DOT 2U plastic containers inside prescribed outer containers. [178.24-7(a)(1), 178.24-7(a)(2)] Case No. 94-94-PLM-CE	\$6,400
RIVIANA FOODS D/B/A RVR PACKAGE TESTING CENTER (Package Certifier)	Certified UN standard fiberboard boxes with a four-digit certification number which had already been assigned to a different packaging. [171.2(e), SA-890504]. Case No. 93-183-PC-CE.	\$1,200

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

RIVIANA FOODS D/B/A RVR PACKAGE TESTING CENTER (Package Certifier)	Certified boxes as UN4GV when proper design qualification tests were not performed. [178.503(a)(2)] Case No. 95-96-PC-CE	\$3,500
ROBERTS CHEMICAL COMPANY INC (Shipper)	Offered sodium cyanide in UN standard packaging which did not meet the packaging criteria for the material being shipped; failed to legibly sign the shipper's certification on a shipping paper. [173.211, 172.204(d)] Case No. 95-51-SP-EA	\$3,500
ROUSSEL BIO CORP D/B/A/ FORD'S CHEMICAL INC (Shipper)	Offered poison B in nonspecification packaging; failed to mark package with upward orientation arrows; offered flammable liquid in nonspecification packaging; failed to establish that boxes marked DOT 12A met test requirements. [173.346(a), 172.312(a)(2), 173.119(b), 173.346(a)(26)] Case No. 92-101-SB-WE	\$9,500
ROYAL CARBO CORP (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to perform complete internal and external inspection; failed to maintain accurate records of retest and reinspection; failed to remark exemption aluminum cylinders as DOT 3AL. [173.34(e)(3), 173.34(e)(1), 173.34(e)(5), 173.23(c)] Case No. 92-124-CR-EA	\$7,150
ROYAL CONTINENTAL BOX CO D/B/A ABC SHIPPING SUPPLY (Box Manufacturer)	Certified boxes as UN4M without performing design qualification tests; failed to properly mark packages to indicate construction material; failed to mark year of manufacture. [178.601(d), 178.503(a)(2)] Case No. 94-73-BM-CE	\$6,720
RUSSELL-STANLEY CORP (Plastic Drum Manufacturer)	Failed to maintain test records for drums marked DOT 34; failed to conduct the production leakproofness tests on UN1H1 drums. [178.19-7(d), 178.604(e)] Case No. 94-18-DM-EA	\$4,000
RUSSELL-STANLEY CORP (Steel Drum Manufacturer)	Failed to conduct periodic drop and hydrostatic tests on drums marked 5B, 17H, 17C; failed to conduct design qualification tests on drums marked UN 1A1 and 1A2; certified an open head drum as a UN1A1. [178.82-13(a)(1), 178.82-13(a)(2), 178.118-12(a)(1), 178.118-12(a)(2), 178.115-12(a)(1), 178.115-12(a)(2), 178.603, 604, 178.605, 178.606, 178.503(a)(2), 178.504(a)(2)] Case No. 93-10-DM-CE	\$18,850

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

SAFEGUARD FIRE AND SAFETY EQUIPMENT COMPANY INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to test cylinders to minimum test pressure; failed to hold an approval or current RIN. [173.34(e)(1), 173.34(e), 173.34(e)(1)(i)] Case No. 94-12-CR-EA	\$6,000
SAVAGE INDUSTRIES INC (Shipper)	Offered explosives for transportation under the terms of an exemption that had expired. [173.62(a)] Case No. 94-273-EXR	\$2,900
SAVOLITE CORP (Shipper)	Provided unauthorized additional information in the basic HM shipping descriptions on shipping papers; offered flammable liquid in unauthorized DOT specification packaging; offered hypochlorite solution in nonspecification packaging. [172.201(a)(4), 173.119(c), 173.203(a)] Case No. 94-14-SP-WE	\$6,900
SCHUTZ CONTAINER SYSTEMS INC (Plastic Drum Manufacturer)	Certified plastic drums as UN1H1 without performing leakproofness tests. [178.604] Case No. 95-27-PDM-CE	\$3,700
SCHWEIZER FIRE PROTECTION COMPANY INC (Cylinder Retester)	Failed to condemn cylinders with permanent expansion exceeding 10% of total expansion. [173.34(e)(4)] Case No. 93-201-CR-EA	\$3,000
SCOTT SPECIALTY GASES INC (Cylinder Manufacturer/Shipper)	Certified cylinders as DOT-39 and DOT-E 8990, when the cylinders did not meet those requirements; failed to include the exemption number on the shipping paper; failed to provide training to HM employees. [178.65-14(b), 172.203(a), 172.702(a), 172.702(b)] Case No. 95-35-CM-HQ	\$7,350
SCOTT SPECIALTY GASES INC (Shipper)	Offered compressed gas under the terms of an expired exemption. [DOT-E 7835, 177.848] Case No. 94-146-EXR	\$1,600
SCRANTON COOPERAGE INC (Drum Reconditioner)	Certified intermediate bulk containers without performing equalification tests at minimum test pressure. [173.32(f), DOT-E 9051] Case No. 94-85-DR-EA	\$4,000

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

SEAMLESS CYLINDER INTERNATIONAL INC (Cylinder Manufacturer)	Certified 4B cylinders without conducting the hydrostatic, flattening, and physical tests. [178.50-14, 178.50-15, 178.50-16] Case No. 93-89-FCM-HQ	\$6,400
SHEEHAN'S BOISE INC (Cylinder Retester)	Performed hydrostatic retesting on inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.34(e)(5)] Case No. 93-244-CR-WE	\$4,000
SHELL OIL COMPANY D/B/A SHELL CHEMICAL CO (Box Manufacturer/Shipper)	Represented and marked fiberboard boxes as meeting UN4G without conducting design qualification tests. [178.601(d), 178.2(b)] Case No. 93-207-SBM-CE	\$6,000
SHELTON FIREWORKS INC (Shipper)	Failed to register with RSPA when offering in excess of 5,000 pounds of HM of the same hazard class in non-bulk packaging in a single shipment requiring placarding. [107.601(e)] Case No. 93-16-SE-CE	\$250
SIERRA MONITOR CORP (Cylinder Manufacturer)	Failed to maintain inspectors reports for three years on cylinders marked DOT 39; failed to provide 24-hour emergency response telephone number on shipping paper. [178.65-15(a), 172.604(a)] Case No. 93-235-CM-HQ	\$4,100
SLO AIR PRODUCTS INC (Cylinder Manufacturer)	Certified and offered cylinders as meeting DOT-E 6563 that were not manufactured in accordance with the exemption. [DOT-E 6563, Para. 7] Case No. 92-56-EX-HQ	\$3,000
SMURFIT PACKAGING CORP (Fiber Drum Manufacturer)	Manufactured, marked, certified, and sold drums as specification DOT-21C fiber drums after October 1, 1994. [171.14(a)(6)] Case No. 95-120-FDM-CE	\$1,600
SMURFIT PLASTIC PACKAGING INC (Plastic Drum Manufacturer)	Manufactured, marked and certified nonspecification polyethylene containers as meeting the requirements of an expired exemption. [171.2(c), DOT-E 8780] Case No. 93-140-EX-EA	\$2,900

## Research and Special Programs Administration

### Penalty Actions Report (1994-1995)

SOMMERFIELD WELDERS SUPPLY COMPANY INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure; failed to remark exemption aluminum cylinders as DOT 3AL. [173.34(e)(3), 173.34(e)(5), 173.23(c)] Case No. 93-139-CR-CE	\$8,000
SONOCO PRODUCTS CO D/B/A SONOCO PLASTICS DRUM (Plastic Drum Manufacturer)	Certified drums as UN 1H1 without performing periodic testing; failed to perform production leakproofness tests at the required test pressure. [178.601(e), 178.604(b)(1), 178.604(e)(2)] Case No. 94-32-PDM-HQ	\$5,175
SOUTH SHORE FIRE & SAFETY (Cylinder Retester)	Failed to retest cylinders at a minimum test pressure; performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest; failed to condemn cylinders with permanent expansion exceeding 10% of total expansion; failed to meet the terms of DOT-E 7235. [173.34(e), 173.34(e)(3), 173.34(e)(5), 173.34(e)(4), DOT-E 7235] Case No. 93-113-CR-EA	\$18,300
SOUTHWESTERN WELDING SUPPLY COMPANY INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to condemn cylinders with permanent expansion exceeding 10% of total expansion; failed to maintain accurate records of reinspection and retest; charged and offered cylinders without verifying pressure. [173.34(e)(3), 173.34(e)(4), 173.34(e)(5), 173.302(e)] Case No. 95-159-CR-SW	\$13,365
SPACE AGE MANUFACTURING COMPANY INC (Shipper)	Offered an unapproved explosive device for transportation. [173.56(b)] Case No. 94-37-SE-HQ	\$7,000
SPARTAN CHEMICAL COMPANY INC (Shipper)	Offered sodium hydroxide in nonspecification packaging; offered corrosive liquid in nonspecification packaging. [173.245(a), 173.249(a)] Case No. 94-48-SB-CE	\$4,500
SPARTENBURG STEEL PRODUCTS INC (Steel Drum Manufacturer)	Failed to retain periodic test samples for DOT 5C; failed to conduct design qualification testing on the required number of UN1A1 drums; manufactured DOT 5C drums without the required rolling hoops; marked DOT 5C drums with an incorrect gauge marking. [178.83-13(a), 178.601(c)(1), 178.83-7(a), 178.83-11(a)(4)] Case No. 93-227-DM-EA	\$12,500

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

SPECTROWAX CORP (Shipper)	Offered compound cleaning liquid in nonspecification packaging; failed to mark the proper shipping name and ID number on the package; failed to sign the shipper's certification on the shipping paper. [173.245(a), 173.203(a), 172.301(a), 172.204(d)] Case No. 93-188-SB-EA	\$6,600
STANDARD COATING CORP (Shipper)	Offered flammable liquids in unauthorized DOT packaging; offered a flammable liquid with a flash point above 73 degrees Fahrenheit in nonspecification packaging without marking the package with an indication of the flash point; provided additional unauthorized information in the HM shipping description on a shipping paper. [173.119(b), 173.118(b), 172.201(a)(4)] Case No. 93-09-SP-EA	\$5,600
STARLIGHT NAIL SUPPLIES INC (Shipper)	Offered acetone, flammable liquid, in nonspecification packaging; failed to mark packages with the proper shipping name and ID number. [173.119(a), 172.301(a)] Case No. 93-272-SB-WE	\$5,400
STATE LINE FIRE & SAFETY INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest; failed to condemn cylinders with permanent expansion exceeding 5% and 10 % of total expansion. [173.34(e)(3), 173.34(e)(5), 173.34(e)(4)] Case No. 93-114-CR-EA	\$10,600
STEELCRETE COMPANY INC (Plastic Bottle Manufacturer)	Failed to conduct drop tests in outside containers on exemption plastic bottles every four months after start of production; failed to drop test exemption bottles every two hours or every 2,500 bottles; failed to include the exemption number on the shipping paper. [178.19-7, DOT-E 6614 para. 7.a., 172.203(a)] Case No. 94-15-PBM-CE	\$12,530
SUMMIT SCREEN INKS C/O FLINT INK CORP (Box Manufacturer/Shipper)	Failed to conduct periodic requalification tests and maintain records on boxes marked UN 4G; marked UN 4G boxes with the incorrect year of manufacture. [178.601(k)(2), 178.601(e), 178.503(a)(6)] Case No. 94-106-BMS-CE	\$5,700
SUPERIOR WELDING SUPPLY COMPANY INC (Cylinder Retester)	Performed hydrostatic retests on inaccurate equipment. [173.34(e)(3)] Case No. 94-108-CR-CE	\$4,000
SUSPA INC (Shipper)	Offered HM for transportation under the terms of an expired exemption. [173.306(f)(2)(iii)] Case No. 95-72-EXR	\$2,900



## Research and Special Programs Administration Penalty Actions Report (1994-1995)

SYFLO COMPANY (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment; failed to determine the minimum or average wall stress for cylinders marked with "+" mark to indicate authorization for 10% overfill; marked RIN in the improper sequence; failed to maintain accurate records of reinspection and retest. [173.34(e)(3), 173.302(c)(3), 173.34(e)(6), 173.34(e)(6)] Case No. 93-45-CR-CE	\$6,580
SYNDER INDUSTRIES INC (Portable Tank/Drum Manufacturer)	Certified plastic DOT-E 10918 exemption portable tanks when periodic drop tests were not conducted; failed to conduct design qualification tests and periodic requalification tests on various UN 1H1 drums; failed to maintain records of design qualification tests; failed to train to HM employees. [DOT-E 10918 para. 7.b., 178.601(d), 178.603(a), 178.601(k)(1), 178.601(k)(2), 172.702(b)] Case No. 94-223-PTDM-CE	\$10,550
SYSTRON-DONNER CORP (Exemption Cylinder Manufacturer/Shipper)	Manufactured DOT-E 7477 cylinders with unauthorized parts; offered bromotrifluoromethane for transportation in unauthorized cylinders; failed to maintain reports on DOT-E 7477 cylinders; failed to indicate the exemption number on the shipping paper; failed to describe a HM with its proper shipping name on a shipping paper. [Exemption DOT-E 7477, para. 7.a.4., 173.304(a), Exemption DOT-E 7477, para. 8.e., 172.203(a), 172.202(a), 173.306(c)] Case No. 93-36-ECM-HQ	\$10,540
T H COCHRANE LABORATORIES INC (Independent Inspection Agency)	Certified and marked DOT-E 7277 cylinders with additional information affecting the required service pressure markings. [173.34(c)(1)] Case No. 94-142-IIA-HQ	\$2,500
TAYLOR'S FIRE CONTROL (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment. [173.34(e)(3)] Case No. 93-106-CR-HQ	\$2,900
TEXBERRY CONTAINER CORP (Plastic Bottle Manufacturer)	Failed to perform periodic ambient, cold drop, and vibration testing on DOT 2U containers in prescribed outer packagings; failed to mark rated capacity on DOT 2U containers. [178.24-7(a)(1)-(3), 178.24-5(a)(4)] Case No. 93-13-PLM-CE	\$7,960

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

THATCHER COMPANY INC (Shipper)	Offered compound cleaning liquid in nonspecification packaging; failed to include the proper shipping name on the shipping paper; offered a corrosive liquid in nonspecification packaging; failed to mark the technical name of a HM on the package. [173.249, 172.202(a)(1)-(3), 173.245(a), 172.301(c), 172.203(k)(3)] Case No. 93-173-SP-WE	\$7,100
THE NDL ORGANIZATION INC (Shipper)	Failed to mark packages of radioactive materials with the proper shipping name. [173.301(a)] Case No. 94-97-RMS-HQ	\$800
THEOCHEM LABORATORIES (Shipper)	Offered compound cleaning liquid, corrosive material, in nonspecification packaging. [173.256] Case No. 93-07-SP-HQ	\$2,850
THEOCHEM LABORATORIES INC (Shipper)	Offered compound cleaning liquid in nonspecification packaging; failed to sign shipper's certification on shipping paper. [173.256, 172.204(d)(1)] Case No. 91-144-SB	\$3,200
THEOCHEM LABORATORIES INC (Shipper)	Offered flammable liquid in nonspecification packaging; offered a corrosive, poisonous material without removing the hazard class from subsidiary hazard label. [173.119(b), 172.402(b)] Case No. 94-231-SP-EA	\$5,520
TIOGA COATINGS CORP (Shipper)	Offered paint in nonspecification and out-of-test DOT 57 portable tanks. [173.128(a)(3), 173.242(c)] Case No. 94-71-SPT-CE	\$2,250
TOMCO CHEMICALS (Shipper)	Offered acetone and acetic acid in nonspecification packaging; failed to provide employee HM training; failed to include a 24-hour emergency response telephone number on the shipping paper; included additional unauthorized information before the basic HM shipping description on the shipping paper; failed to sign the shipper's certification. [173.119(a), 172.702(b), 172.604(a)(2), 172.201(a)(4), 172.204(d)] Case No. 95-135-SBP-SW	\$8,170
TRAK AUTO CORP (Shipper)	Offered batteries, wet, filled with acid, without labeling, marking, and in nonspecification packaging. [172.301(a), 172.400(a), 173.159(a)] Case No. 93-147-BAT-HQ	\$7,000

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

TRANS GULF INDUSTRIES INC (Shipper)	Offered xylene in unauthorized DOT packaging; included additional unauthorized information in the HM shipping description on a shipping paper; failed to provide a 24-hour emergency response telephone number on a shipping paper. [173.119(c), 173.119(d), 172.201(a)(4), 172.201(d)] Case No. 92-129-SP-WE	\$3,200
TRI CONTAINERS INC (Steel Drum Manufacturer)	Failed to conduct drop and hydrostatic tests on drums marked DOT 17E and 17H; failed to conduct the proper on-line leakage test; failed to mark drums with proper gauge markings; failed to mark drums with the name and address or registered symbol of the manufacturer. [178.116-12(a)(1), 178.116-12(a)(2), 178.118-12(a)(1), 178.118-12(a)(2), 178.116-13, 178.116-10(a)(4), 178.116-10(a)(3), 178.116-6] Case No. 90-109-DM	\$9,100
UNION CAMP CORP (Bag Manufacturer)	Manufactured, marked, certified, and sold bags as meeting the UN 5M2 standard without conducting design qualification tests; failed to properly mark UN 5M2 bags with the correct performance standard. [178.601, 178.503(a)(3)] Case No. 94-84-BGM-EA	\$7,600
UNITED INDUSTRIES INC (Cylinder Retester)	Failed to perform hydrostatic retest at minimum test pressure; failed to properly mark RIN on cylinders; performed hydrostatic retesting with inaccurate equipment; failed to maintain accurate records of reinspection and retest. [173.34(e), 173.34(e)(6), 173.34(e)(3), 173.34(e)(5)] Case No. 91-134-CR	\$2,500
UNITED STATES WELDING INC (Cylinder Retester)	Performed hydrostatic retests with inaccurate equipment; failed to determine the minimum or average wall stress for cylinders marked with "+" mark to indicate authorization for 10% overfill; failed to maintain adequate records of reinspection and retest; failed to properly mark RIN on cylinders. [173.34(e)(3), 173.302(c)(5), 173.34(e)(5), 173.34(e)(6)] Case No. 92-13-CR	\$6,570
UNITED WAREHOUSE INC (Shipper)	Offered bromotrifluoromethane in DOT 110A800W ton tanks which had not been visually inspected within five years as required; provided unauthorized additional information in the HM shipping description on a shipping paper. [173.31(d)(9), 173.314(c), 172.201(a)(4)] Case No. 93-30-STT-WE	\$3,500

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

UNIVERSITY OF NORTH CAROLINA (Shipper)	Offered radioactive material in nonspecification packaging; failed to mark the proper shipping name and ID number on the package; failed to properly label a package of radioactive material; failed to provide the proper shipping name and ID number on shipping papers. [173.415(a), 172.202(a), 172.301(a)(1), 172.400(a)(1)] Case No. 95-09-RMS-HQ	\$5,920
VAN LEER CONTAINERS INC (Steel Drum Manufacturer)	Failed to conduct periodic drop and hydrostatic tests on DOT 17E and DOT17H drums; certified steel drums as UN1A1 and UN1A2 when design qualification tests were not conducted. [178.116-12(a), 178.118-12(a), 178.601(d)] Case No. 94-158-DM-CE	\$12,500
VAN WATERS & ROGERS INC (Shipper)	Offered toluene in nonspecification packaging. [173.119(b)] Case No. 93-208-SB-WE	\$8,100
VAN WATERS & ROGERS INC (Shipper)	Offered chloropicrin liquid in nonspecification packaging; failed to label packages of HM; failed to mark packages for proper orientation; failed to mark the proper shipping name and ID number on packages of HM. [173.357(a), 172.400(a), 172.312(a)(2), 172.301(a)] Case No. 93-68-SB-WE	\$15,175
VARNCO HOLDINGS INC (Shipper)	Failed to register with RSPA after offering in excess of 5,000 pounds of HM of the same hazard class in non-bulk packaging in a single shipment requiring placarding; failed to provide the proper shipping description on a shipping papers. [107.608(a)(2), 107.620, 172.202(a), 172.203(k)(3)] Case No. 94-166-SB-CE	\$1,050
VIDEOJET SYSTEMS INTERNATIONAL INC (Fiberboard Box Manufacturer/Shipper)	Certified UN 4G boxes when design qualification tests were not conducted. [178.601(d)] Case No. 94-110-BMS-CE	\$6,885
WAXIE SANITARY SUPPLY (Shipper)	Offered corrosive material in nonspecification packaging. [173.245(a), 173.203(a)] Case No. 93-229-SP-WE	\$1,825
WELDERS SUPPLY CO - BELOIT INC (Cylinder Retester)	Performed hydrostatic retesting with inaccurate equipment. [173.34(e)(3)] Case No. 93-270-CR-CE.	\$3,225
WELDERS SUPPLY CO OF LOUISVILLE INC (Shipper)	Failed to register with RSPA after offering in excess of 5,000 pounds of HM of the same hazard class in non-bulk packaging in a single shipment requiring placarding. [107.608(a)] Case No. 95-142-REG-CE	\$250

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

WESCHEM INC (Shipper)	Offered potassium hydroxide solution for transportation in nonspecification packaging; failed to mark the proper shipping name on the package. [173.249(a), 172.301(a)] Case No. 92-104-SB-WE	\$1,500
WEST AGRO INC (Shipper)	Offered hydriodic acid, solution in DOT-E10090 containers that have not been retested as specified in the exemption; failed to indicate exemption number on the shipping paper. [173.32(f), DOT-E10090 para. 7.g., 172.203(a)] Case No. 93-232-SPT-CE	\$4,160
WESTAR CORP (Carrier)	Failed to submit a DOT 5800.1 report within 15 days following an unintentional release of a HM. [171.16] Case No. 89-52-HMI	\$1,264
WESTERN AUTO SUPPLY COMPANY (Shipper)	Failed to mark, label, and properly package batteries, wet filled with acid. [172.301(a), 172.400(a), 173.159(a)] Case No. 93-148-BAT-HQ	\$6,600
WESTERN DRUM INC (Drum Manufacturer)	Manufactured, marked, certified, and sold open-head steel drums as meeting DOT 17H that could not pass the hydrostatic test; failed to conduct periodic drop and hydrostatic tests on DOT 17C, 17E and 17H drums; failed to mark the registration number on rings and closures of DOT 17H 55-gallon 18-gauge drums; failed to properly mark the gauge on DOT 17H drums. [178.118-12(a)(2), 178.115-12(a)(1), 178.115-12(a)(2), 178.118-6(a), 178.118-10(a)(4), 178.116-12(a)(1), 178.116-12(a)(2), 178.118-12(a)(1), 178.118-12(a)(2)] Case No. 91-102-DM	\$11,856
WESTERN FIRE & SAFETY COMPANY (Cylinder Retester)	Conducted a second retest at the same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure. [173.34(e)(3)] Case No. 92-27-CR	\$1,100
WESTERN ZINC CORP (Shipper)	Offered water reactive solid n.o.s., a flammable solid, in unauthorized packaging, under the terms of an exemption which had expired. [173.154(a)] Case No. 92-132-EXR	\$3,031
WESTVACO CORP (Fiberboard Box Manufacturer)	Failed to conduct drop tests on boxes marked DOT 12A prior to initial use. [178.210-10(a), 178.210-10(b)] Case No. 94-42-BM-CE	\$4,000

## Research and Special Programs Administration Penalty Actions Report (1994-1995)

WEYERHAUSER PAPER COMPANY INC (Fiber Box Manufacturer)	Certified boxes as meeting DOT 12B when inner flaps did not butt and fill-in pieces or pads were not included; failed to mark the name and address or registered symbol of the manufacturer on DOT 12B boxes. [178.205-14(a), 178.0-2(a)-(c), 178.205-18(a)(2)] Case No. 94-163-BM-CE	\$5,280
WICHITA FIRE EQUIPMENT (Cylinder Retester)	Failed to hold an approval or current RIN; conducted second retest at same pressure instead of 10% or 100 psi higher, whichever is lower, when accuracy of the system could not be maintained due to equipment failure.[173.34(e)(1)(i), 173.34(e)(3)] Case No. 91-32-CR	\$2,700
WILSON PRODUCTS COMPRESSED GAS CO INC (Cylinder Retester)	Failed to remark exemption aluminum cylinders as DOT 3AL; failed to condemn cylinders with permanent expansion exceeding 10% of total expansion; performed retesting with inaccurate equipment. [173.23(c), 173.34(e)(4), 173.34(e)(3)] Case No. 92-32-CR-EA	\$3,200
WORLD LABORATORIES LTD (Shipper)	Offered hydrochloric acid in nonspecification packaging; failed to mark package with the proper shipping name; failed to include the proper shipping name on the shipping paper; failed to provide a shipper's certification on the shipping paper; included additional unauthorized information in a HM shipping description on the shipping paper. [173.263(a), 173.202(a), 172.301(a), 172.202(a), 172.204(a), 172.201(a)(4)] Case No. 93-175-SB-WE	\$5,000
WRICO CORP (Shipper)	Offered corrosive materials in nonspecification packaging; failed to include the hazard class and ID number on the shipping paper; failed to provide a shipper's certification on the shipping paper; failed to include a 24-hour emergency response telephone number on the shipping paper; provided an incomplete hazard class on the shipping paper; provided the shipping description on the shipping paper in the wrong sequence. [173.245(a), 172.202(a)(2), 172.204(d), 172.201(d), 172.202(b)] Case No. 92-85-SB-HQ	\$4,600
WRIGHT BROTHERS INC (Shipper)	Failed to provide employee HM training; failed to register with RSPA when offering in excess of 5,000 pounds of HM of the same hazard class in non-bulk packaging in a single shipment requiring placarding; failed to provide the HM shipping description in the proper sequence on a shipping paper. [172.702, 107.608, 172.202(b)] Case No. 94-162-SC-CE	\$2,700

# Research and Special Programs Administration

## Penalty Actions Report (1994-1995)

YOUNG EXPLOSIVES CORP (Importer)	Failed to inform a foreign shipper of the requirements of the HM Regulations that would apply to a shipment of HM imported into the United States. [171.12(a)] Case No. 92-09-IMP	\$2,700
--	---	---------

