

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1700	Recall	Savage Laboratories	Melville, NY	11747
16 CFR 1501	Recall	Nolte Co. Ltd/Aldi Stores	Batavia, IL	60510
16 CFR 1511	Recall	Tiny Treasures, Inc	Memphis, TN	38134
16 CFR 1511	Recall			
16 CFR 1511	Recall			
16 CFR 1511	Recall			
16 CFR 1501	Recall	Inventory Liquidators Corp	Itasca, IL	60143
16 CFR 1501	Recall			
16 CFR 1501	Recall	Penn Daniels, Inc	Quincy, IL	62301
FHSA— Sec. 2(q) (1A)	Recall	China Pyrotechnics, Inc	Florence, AL	35631
16 CFR 1501	Recall	Assoc. Merchandise Corp	New York, NY	10018
16 CFR 1501	Recall	Chingmaw USA Corp.	Hoboken, NJ	07030
16 CFR 1501	Recall	Sears Roebuck & Co	Chicago, IL	60684
16 CFR 1501	Recall	Ramco Trading Corporation	Hialeah, FL	33014
16 CFR 1303	Recall	Today's Kids	Booneville, AR	72927
16 CFR 1303	Recall			
16 CFR 1303	Recall			
16 CFR 1501	Recall	Yuchius Morality, Inc	New York, NY	10001
16 CFR 1501	Recall			
16 CFR 1501	Recall	Magnifique Trading, Inc	S. El Monte, CA	91733
16 CFR 1501	Recall	Nashco Products, Inc	Scranton, PA	18504
16 CFR 1501	Recall			
16 CFR 1501	Recall	Mar-Ching Export Corp	Hialeah, FL	33014
16 CFR 1501	Recall	Raffoler Importing	Farmingdale, NY	11733
16 CFR 1303	Recall	Lillian Vernon Corp	Mt. Vernon, NY	10550

Date	Product	Model	Violation	Violation
3/91	Evanol	P-017-06	Fails Standard	PPPA
	Rumalon	P-034-11	Fails Standard	PPPA
	Flecha Sure Medicated Oil	PS-037-24	Fails Standard	PPPA
	Periavit	PD-033-36	Fails Standard	PPPA
3/91	Chicco Pacifier Chicco Baby Sets	64180 63097 and 63098	Banned Banned	Pacifier Rattle
3/91	Double Vision Super Beads 'N Pegs Play Station Caterpillar 'N Pegs	TM 001 TM 003 TM 005 TM 008	Banned Banned Banned Banned	Small Parts Small Parts Small Parts Small Parts
4/91	Educational Telephone	H80K-0469/Item 8905B	Banned	Small Parts
4/91	Infant Baseball Caps	96550, 96551, 97550	Banned	Small Parts
4/91	Wooden Soldier Train	96774	Banned	Small Parts
4/91	Abearham & Strauss Bear		Banned	Small Parts
4/91	Terry Cloth Robe	846-C	Fails Standard	Children's Sleepwear
4/91	Zipper Airplanes	3160, 3135, 4635, 3137, 4637	Banned	Small Parts
4/91	Rescue Truck	8115	Banned	Small Parts
4/91	Pacifier Pal	CP-301	Banned	Small Parts
4/91	Pacifier Holder	136	Banned	Small Parts
4/91	MYKIDS Pull-a-long Wood Train	7126/Item 8831	Banned	Small Parts
4/91	Musical Farm	BB4581	Banned	Small Parts
4/91	Green Brontosaurus	Stuffed Animal	Banned	Small Parts
4/91	Oscos Daily Vitamins for Seniors	120 Tablet Size	Fails Standard	PPPA
4/91	Plush Bunnies	In-Store Premium	Banned	Small Parts

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1700	Recall	Propharma, Inc	Miami, FL	33122
16 CFR 1700	Recall			
16 CFR 1700	Recall			
16 CFR 1700	Recall			
16 CFR 1511	Recall	Luis Garraton, Inc	San Juan, PR	00936
16 CFR 1510	Recall			
16 CFR 1501	Recall	Everything Educational	Milford, MA	01757
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall	Farmacias Jose Guillermo	San Juan, PR	00936
16 CFR 1501	Recall	Michael Friedman Corp	Brooklyn, NY	11208
16 CFR 1501	Recall	Chadwick Miller, Inc	Canton, MA	01021
16 CFR 1501	Recall	Abraham & Strauss	New York, NY	10018
16 CFR 1615	Recall	French Clothier, Inc	Folcroft, PA	19032
16 CFR 1501	Recall	SLM, Inc	Gloversville, NY	12078
16 CFR 1501	Recall	Harco, Inc	Tuscaloosa, AL	35406
16 CFR 1501	Recall	W.B Nod & Company	Atlanta, GA	30328
16 CFR 1501	Recall	Safety 1st, Inc	Chestnut Hill, MA	02167
16 CFR 1501	Recall	E Mishan & Sons, Inc	New York, NY	10001
16 CFR 1501	Recall	Battat, Inc	Plattsburgh, NY	12901
16 CFR 1501	Recall	Welch's Foods, Inc	Concord, MA	01742
16 CFR 1700	Recall	Osco/American Drug Stores	Oak Brook, IL	60521
16 CFR 1501	Recall	Kellogg Company	Battle Creek, MI	49016

Date	Product	Model	Violation	
4/91	Pre-Vites with Iron	3270, 100 Tablets	Fails Standard	PPPA
4/91	Wooden Truck w/Crane	1072	Banned	Small Parts
	Wooden Tractor	1076	Banned	Small Parts
	Wooden Cars (2 pc.)	1386	Banned	Small Parts
	Wooden Trucks (2 pc.)	1387	Banned	Small Parts
	Wooden Cars (4 pc.)	1388	Banned	Small Parts
	Wooden Cars (3 pc)	1390	Banned	Small Parts
	Wooden Fire Brigade Car	1391	Banned	Small Parts
	Wooden Soldier Car	1392	Banned	Small Parts
	Wooden Train	1073	Banned	Small Parts
5/91	Telephone Car	WL-362	Banned & Technical Guideline	Small Parts & Sharp Points
5/91	Arm & Hammer 64 oz Laundry Detergent	OF340-09, OF340-10, OF340-11, and OF340-12	Voluntary	Increased pH
5/91	Stuffed Bunnies	A8740S, A8740M	Technical Guideline	Sharp Points
5/91	Wind-Up Circus Wagon	THK4766	Banned	Small Parts
	Funny Zig Zag Copter	THK3309	Banned	Small Parts
5/91	Push-A-Long Train	8841	Banned	Small Parts
	Shape Sorter Pull Toy	8809	Banned	Small Parts
5/91	Roll Back Wheel Toy	B-356	Banned	Small Parts
6/91	Teddy Bear Puzzle	4668	Banned	Small Parts
6/91	Portable Piano Phone	1106	Banned	Small Parts
	Wind-Up Whistle Asst.	77688	Banned	Small Parts
6/91	Jumpin' Jeans Denim Paint Kits	Paint Brush in Various Kits	Banned	Lead-in-Paint
6/91	Toddler Skirt Set	12417	Banned & Technical Guideline	Small Parts & Sharp Point
6/91	Building Block Clock	5777	Technical Guideline	Sharp Points

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1700	Recall	Vitamin World, Inc	Bohemia, NY	11716
16 CFR 1501	Recall	Hanford's	Charlotte, NC	28232
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501 & 16 CFR 1500.48	Recall	Regent Products Corp	Itasca, IL	60143
N/A	Recall	Church & Dwight Co., Inc	Princeton, NJ	08543
16 CFR 1500.48	Recall	Associated Merchandising	New York, NY	10018
16 CFR 1501	Recall	McCrory Corp	York, PA	17402
16 CFR 1501	Recall			
16 CFR 1501	Recall	Nylint Corp	Rockford, IL	61104
16 CFR 1501	Recall			
16 CFR 1501	Recall	Remco Baby / Azrak-Hamway	New York, NY	10010
16 CFR 1501	Recall	Early Learning Centre	Milford, CT	06460
16 CFR 1501	Recall	Kay Bee Toy & Hobby Shops	Pittsfield, MA	01201
16 CFR 1501	Recall			
16 CFR 1303	Recall	Polymeric, Inc-Tulip Prod	Waltham, MA	02254
16 CFR 1501 & 16 CFR 1500.48	Recall	Pete's Partner/Good Lad	Philadelphia, PA	19134
16 CFR 1500.48	Recall	Etna Worldwide Corp	New York, NY	10010

Date	Product	Model	Violation
7/91	Pacifiers	P8, G24, P24, P20, P20/2, P21, P22, P25, P26, P27, P42, P43, P45, P46, P47, P52	Banned Pacifier
7/91	Toy Nursing Bottle	3/211	Banned Small Parts
7/91	Stuffed Santa Bear	44750	Banned Small Parts
7/91	Teething Wheel	SIL 893	Banned Small Parts
7/91	Wooden Train with Guards Set	16346	Banned Small Parts
7/91	Standing Ovation Blitzkrieg Desert Storm	CP243 CP231 CP245	Banned Banned Banned Fireworks Fireworks Fireworks
7/91	Comic Zoo Animals Magic Milk & Juice Bottles	31170 1703	Banned Banned Small Parts Small Parts
7/91	Wisdom Blocks	WP262	Banned Small Parts
8/91	Flashing Thunder Blossom After Thunder Celebrating Frwksw/FC Celebration Crackers	2026C N2018C 2034 T805	Banned Banned Banned Banned Fireworks Fireworks Fireworks Fireworks
8/91	Racers	2010R	Banned Small Parts
8/91	Paint Brushes	Do It Yourself	Banned Lead-in-Paint
8/91	Butterfly Bracelets	P4136	Banned Small Parts
9/91	Plastic Cooking Set Musical TV Bank	E28 7750A	Banned Banned Small Parts Small Parts
9/91	Cracklin' Thunder	TB 1012	Banned Fireworks
9/91	Missile Shooting Plane	1744	Technical Guideline Sharp Edges
9/91	2 Piece Maracas	15565	Banned Small Parts
9/91	Wind-Up Helicopter	1743	Banned Small Parts
9/91	Learn the Alphabet	11151	Banned Small Parts

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1511	Recall	Luv'N Care, Inc	Monroe, LA	71201
16 CFR 1501	Recall	Esco Imports of Texas, Inc	San Antonio, TX	78210
16 CFR 1501	Recall	S & D Importing	Farmingdale, NY	11735
16 CFR 1501	Recall	Scenique Toys, Inc	San Francisco, CA	94107
16 CFR 1501	Recall	Midwest Importers	Cannon Falls, MN	55009
16 CFR 1500 17	Recall	China Pyrotechnics, Inc	Florence, AL	35630
16 CFR 1500 17	Recall			
16 CFR 1500 17	Recall			
16 CFR 1501	Recall	E Fomil & Sons, Inc	Burlingame, CA	94010
16 CFR 1501	Recall			
16 CFR 1501	Recall	Lederer Industries	New York, NY	10010
16 CFR 1500 17	Recall	Reichenbach Fireworks	Billings, MT	59105
16 CFR 1500 17	Recall			
16 CFR 1500 17	Recall			
16 CFR 1500.17	Recall			
16 CFR 1501	Recall	Unique Industries	Philadelphia, PA	19144
16 CFR 1303	Recall	Marx Brush Mfg Co	Palisades Park, NJ	07650
16 CFR 1501	Recall	Western Novelty	Denver, CO	80216
16 CFR 1501	Recall	Yuchius Morality, Inc	New York, NY	10001
16 CFR 1501	Recall			
16 CFR 1500.17	Recall	Mid-American Fireworks	Springfield, MO	64802
16 CFR 1500.49	Recall	Lewis Greenberg & Sons	Hauppauge, NY	11787
16 CFR 1501	Recall	Lewis Greenberg & Sons	Hauppauge, NY	11787
16 CFR 1501	Recall	Lewis Greenberg & Sons	Hauppauge, NY	11787
16 CFR 1501	Recall	Lewis Greenberg & Sons	Hauppauge, NY	11787

Date	Product	Model	Violation	
9/91	Bear Play Mat	130189	Banned	Rattle
	Special Skunk	510052	Banned	Small Parts
9/91	Mini Wooden Puzzle	404	Banned	Small Parts
	Wood Preschool Puzzle	401	Banned	Small Parts
9/91	Peg Pounder	8839	Banned	Small Parts

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1510 16 CFR 1501	Recall Recall	House of Lloyd, Inc	Grandview, MO	64030
16 CFR 1501 16 CFR 1501	Recall Recall	Ranger International	Norcross, GA	30071
16 CFR 1501	Recall	Unitrade Marketing Group	New York, NY	10001

Voluntary Corrective Action Plans Under
Section 15 of the Consumer Product Safety Act and
Section 15 of the Federal Hazardous Substances Act

Date	Firm and Product	Alleged Hazard	Remedy
10/90	Delta Enterprise Corporation Brooklyn, NY Delta Luv Pop-Corn Walker	Plastic and plastic-coated labels and decals found on plastic toy dials on the walker trays may present a choking hazard to children who pull them off and place them in their mouths.	A joint press release was issued notifying consumers to immediately check, pull off and discard labels and decals from their walkers
10/90	U.S Divers c/o Gibson, Dunn and Crutcher Los Angeles, CA Micro Power Inflators on Buoyancy Compensators	There could be a slow increase in, or slow loss of, buoyancy in the Buoyancy Compensators in question. The firm does not believe that either of these conditions creates a substantial product hazard, but it voluntarily offered free upgrades of this product.	Existing inventory was upgraded and free upgrade programs for dealers and customers were instituted.
10/90	China Pyrotechnics, Inc. Florence, AL Screaming Tiger with Three Whistles #CP158	The multiple plastic shells shot from this fireworks device may exhibit unpredictable and erratic flight striking persons nearby.	The item was removed from sale and all inventory was returned to the manufacturer.

Date	Firm and Product	Alleged Hazard	Remedy
10/90	Solar Impex New York, NY Electrical transformer with a removable power supply cord equipped with a male plug on each end of the cord	When one plug is inserted into a wall receptacle first, the plug at the other end is electrically charged. Consumers could receive severe burns or be electrocuted if they touch the energized plug.	The firm cooperated in a joint press release with CPSC and the NY Attorney General's Office and will provide a full refund to consumers who purchased the product.
10/90	Star Sales Co. Knoxville, TN Teddy Pet With Cassette #3851	The wires in the teddy bear may be inadequately insulated, thus leading to short circuiting and over heating. This could result in the teddy bear catching on fire.	Consumers were advised to return the teddy bears to the store where purchased for a refund.
10/90	Procter & Gamble Co. Cincinnati, OH Stuffed Rabbit	The ribbons exceed the length described in ASTM F963 and could present a potential strangulation risk.	The item was only distri- buted as a promotion to retail store employees. Stores were notified to remove ribbons.
11/90	Service Merchandise Co. Nashville, TN "Pro Sport" Lawn Spinner game	The plastic spinner discs present the potential for face and eye injuries to young children.	The firm issued a joint press release with the CPSC and offered a refund of the purchase price to consumers returning the discs to a Service Merchandise store.

Date	Firm and Product	Alleged Hazard	Remedy
11/90	Panaria International, Inc. New York, NY Sonic Flashergun shaped novelty cigarette lighter	If children use the lighter as a toy, fires or injury may result.	The firm stopped sales of product and agreed not to import or sell product again
11/90	Regent Sports Corporation Hauppauge, NY Regent Lawn Discus, Model 73939	The plastic spinner discs may cause serious facial lacerations or loss of sight when thrown by younger children unable to control flight path	Firm issued joint news release on 11/13/90 offering a cash or credit refund of the purchase price to consumers returning the discs to the retail store where purchased
11/90	Franklin Sports Industries Stoughton, MA Franklin Yard Spinner plastic disc game	The plastic fins of the spinner discs may cause serious facial lacerations or loss of sight when thrown by young children unable to control flight path	The firm issued a joint news release with CPSC offering a refund of \$5 to consumers returning the discs to the firm
11/90	General Sportcraft Bergenfield, NJ Aero Discs plastic discus game	The plastic fins of the Aero Discs may cause serious facial lacerations or loss of sight when thrown by younger children who are unable to control the flight path.	The firm stopped distribution and requested customers to return units
11/90	Iron Mountain Forge Farmington, MO Tire Swing Bolt	If the bolt fails the tire swing will drop causing possible injury to user	The firm offered a retrofit kit to consumers

Date	Firm and Product	Alleged Hazard	Remedy
11/90	Midwest Electric Products, Inc Mankato, MN Weatherproof Power Outlet Cabinet (69 Models)	Wiring errors may have occurred with some units made during the January 15 to March 16, 1990 production. If not properly grounded as installed, the metal door (enclosure) of a defective unit could be electrically energized to present a severe electric shock or an electrocution hazard	Each distributor, contractor or operator locating a unit which has not been examined or repaired should call the company at (597) 625-4414 or write to Midwest Electric Products Inc., Quality 90, P.O. Box 910, Mankato, MN 56002-0910
11/90	Kmart Corporation International Headquarters Troy, MI Infant soft carrier, item #2130	If one or more of the four straps are not securely fastened to the quick release buckle, the weight of the baby may cause the strap to slip, allowing the baby to fall from the carrier	Return the Soft Carrier to any Kmart store for a full refund
11/90	S. Goldberg & Co., Inc. Hackensack, NJ Hard Soled Woman's Slippers	The wearer may slip and fall.	The firm cooperated with the retailer to destroy defective slippers or returned them to the foreign manufacturer.
11/90	Jet Comb of Arkansas Flippin, AR Junior Golf Clubs	If a person were standing in the line of fire or direction of the ball when club is swung, he may be struck by a club head which has separated from its shaft.	Jet Comb is not initiating any form of recall, but will refund or replace any units returned to them.

Date	Firm and Product	Alleged Hazard	Remedy
11/90	Child Craft Salem, IN Crib, Model 12281 03	Structural failure of the drop side could allow child to fall out of crib	All units distributed have been repaired
11/90	Fisher-Price East Aurora, NY Carriage Stroller, #9121	In some cases, the locking mechanism may not engage fully, allowing the stroller to collapse. Injury to a child in the stroller may occur	Consumers with Model #9121, Carriage Stroller should call Fisher-Price at 1-800-527-1034 for instructions on how to obtain a replacement stroller
12/90	Space Walk Metairie, LA Air Inflatable Bounce Rides	When not properly anchored, the ride could become airborne	The firm is providing a "fix kit" to customers containing a revised set-up and operating manual, a sign warning operators to unload ride in excessive winds, and additional rules of operation

Date	Firm and Product	Alleged Hazard	Remedy
12/90	Poolmaster Menlo Park, CA Child Floatation Device	The product's instability may pose a drowning hazard to an unattended child.	Poolmaster revised and shortened warning labeling on the product and its packaging to enhance the likelihood that it will be read. Also, age and weight limits were placed on the packaging for safe operation. Misleading words used in advertising such as "Tip Resistant" will be avoided in the future.
12/90	Specialized Bicycle Components Morgan Hill, CA Water Bottle Poppet	If the poppet becomes detached it can present a choking hazard to children.	The firm redesigned the product and made it available to customers.
12/90	Control Data Corporation Winco, Inc. Minneapolis, MN Portable electric generators between 2000 & 8000 watts labeled Winco, Dyna, Fairbanks Ward, or Dayton	If the portable electric generator is operated indoors with insufficient ventilation, carbon monoxide gas from the motor may accumulate in the air. This may present a poisoning hazard.	Warning letters were sent to distributors, owners and rental agencies offering free warning labels to attach to the generators.

Date	Firm and Product	Alleged Hazard	Remedy
12/90	<p>Shell Oil Company Houston, TX</p> <p>Liquid Petroleum (LPG) Gas</p>	<p>Approximately 400,000 barrels of liquid petroleum (LPG) gas Shell shipped from its Martinez, CA, refinery between April and September 1989 may have been inadequately odorized (with ethyl mercaptan). Without adequate odorant, potentially hazardous leaks that occur could go undetected</p>	<p>Shell sent out teams to check odorant levels at consumers' residential tanks and add odorant if it was needed It also instructed RV owners to top off their tanks with (odorized) gas Shell is also instituting improved odorizing and testing procedures at its facilities For further information call 1-800-852-0344.</p>
12/90	<p>Morgan Buildings & Spas, Inc. Dallas, TX</p> <p>Portable Spa</p>	<p>The spa heater may remain on indefinitely Serious burn injuries are possible from the escaping hot water vapor or if the spa is being used when overheating occurs</p>	<p>The firm is repairing units in consumer hands by replacing the contactor and modifying the power pack by adding a heat- sensitive switch which operates as a surrogate thermostat.</p>

Date	Firm and Product	Alleged Hazard	Remedy
12/90	Shell Oil Company Houston, TX Propane Gas	Approximately 54,000 gallons of propane gas distributed by Shell in April 1990 was contaminated with hydrogen sulfide. Hydrogen sulfide and its combustion by-products could be toxic if inhaled. It may also cause corrosion of components in the system.	Shell replaced the fuel, tanks, regulators and pigtails in residential installations with potentially significant levels of contamination. It also replaced the fuel and tanks of portable tank owners who purchased the subject gas, and cleaned all bulk tanks and trucks that had held the gas. For further information call 1-800-852-0344.
12/90	Shell Oil Company Houston, TX Propane Gas	Approximately 65,000 gallons of liquid petroleum (LP) gas Shell shipped from its Wood River manufacturing complex in Roxana, IL, in August 1990 lacked adequate odorant (ethyl mercaptan). Without adequate odorant, potentially hazardous leaks that occur could go undetected.	Shell sent out teams to check odorant levels at consumers' residential tanks and add odorant if it was needed. It also instructed RV owners to replace the fuel in their tanks with odorized gas. Shell is also instituting improved odorizing and testing procedures at its facilities.

Date	Firm and Product	Alleged Hazard	Remedy
12/90	<p>Zenith Electronics Corporation Glenview, IL</p> <p>27-Inch Color Television Receiver, Models SS2761S and SG5740W</p>	<p>An electrolytic capacitor could fail and short circuit to chassis ground and to the external antenna connector. An electrically energized antenna connector or antenna would present a severe electric shock hazard.</p>	<p>Zenith contacted owners by mail with instructions to disconnect their TV until a Zenith representative could make an appointment for repair</p>
12/90	<p>General Electric Company Cleveland, OH</p> <p>Seven 1990 Mini Light Set Models (Three "TD-90" Date Code Models: UXL2-50, UXL2-100, ULC2-140, Three "TF-90" Date Code Models, UXL2-50, UXL2-100, UXM2-70, and Model ULF2-160)</p>	<p>The metal conductors in the wires and plugs may be exposed. Contact with an exposed and energized metal conductor could present an electric shock hazard</p> <p>NOTE. Light sets with stickers on the carton with the following letters, numbers, and symbols are not included in the recall.</p> <p>TD-90-(Circle Symbol) TF-90-(Triangle Symbol) WE-90-(Star Symbol)</p>	<p>Owners who identify their mini light sets as being recalled should call the General Electric Company at 1-800-626-2000 for instructions on returning their sets for replacement or refund.</p>
12/90	<p>Consolidated Stores Corporation Columbus, OH</p> <p>Toyo 100 Indoor/Outdoor Chasing and Music Christmas Light Sets</p>	<p>Control box may overheat and be a potential for ignition of combustibles near/on Christmas trees to cause fire and injury.</p>	<p>The firm offered refunds or credit to consumers returning light sets to its stores</p>

Date	Firm and Product	Alleged Hazard	Remedy
01/91	Kransco San Francisco, CA Child Floatation Devices—"Baby Tender Pool Seat," "Swim Sweater," and "Baby Sitter"	On both the "Baby Tender Pool Seat" and the "Swim Sweater" it is possible that through improper use and/or poor supervision, a child may tip over and drown. The name "Baby Sitter" gives the subliminal message that the child is secure and can be left momentarily by the caretaker	—On the "Baby Tender," the warning on the product and packaging will be revised to enhance the possibility it will be read —On the "Swim Sweater," instructions will advise never to place child's legs through the arm holes. —On the "Baby Sitter," the name will be changed to "Baby Float."
01/91	Breman Corporation Bremen, IN "The Shrimp Boat," a child floatation device	The product may flip over in water possibly causing a child to be trapped upside down The child may drown	The firm revised the warning label on the product to enhance the likelihood that it will be read.
01/91	Petrus Imports Framingham, MA Umbrella	A child occupant may lean forward and strike his head on the ground or on the front of the stroller Also, loose tube end plugs may pose a choking hazard to a child who places the plug in his mouth.	During January 1991, the firm announced the availability of free modification kits to consumers who a toll-free 800 number

Date	Firm and Product	Alleged Hazard	Remedy
01/91	<p>The Wiremold Company West Hartford, CT</p> <p>Plastic Electrical Switchplate & Outlet Covers for "On-Wall" Series of Surface Wiring</p> <p>In-Line Receptacle (843G), In-Channel Outlets (NM 12 and NM 100), In-Line & In- Channel Switches (840 & NM 13)</p>	<p>Covers installed too tightly may crack and break when exposed to some household oil- based products such as insect spray and cooking oils. If such cracking is severe, there is a possibility that the electrical wires may become exposed Should wiring become exposed, there is a possibility of severe electrical shock if a consumer inadvertently comes in contact with the exposed wiring</p>	<p>The firm is providing the free replacement of any cracked units and any unopened units in consumer hands with appropriate replacement units which do not exhibit the same degradation problems</p>
01/91	<p>Sachs Bicycle Components Paramount, CA for. Modolo International, St Lucia, ITALY</p> <p>Master; Speedy; Flash; Equipe; Pro, Modolo Bicycle Stems</p>	<p>Should a stem break at the pinch-bolt on the handlebars, loss of bicycle control could result in a fall to the rider.</p>	<p>The firm recalled the product and re- designed the stems to ensure their strength at the pinch- bolt Modolo of Italy has shipped replacements to the U S. for distribution through Sachs Bicycle Components</p>

Date	Firm and Product	Alleged Hazard	Remedy
01/91	Polaris Industries L.P. Minneapolis, MN 1991 Indy Trail Snowmobile	During production testing particles of O-ring may get lodged in the braking system impeding the flow of brake fluid and resulting in diminished braking capabilities of the snowmobile.	The firm has notified 100% of its dealers, distributors and all warranty card holders. A service bulletin was issued with instructions to replace brake lines on all 382 units with the potential problem.
01/91	IKEA Plymouth Meeting, PA Tantal Halogen Torchiere Lamp	The glass shield that covers the light bulb of the lamp has the tendency to shatter if the "dimmer" light control is placed at its maximum wattage of 500 watts	The firm has removed the defective lamps from the marketplace
01/91	Levi Strauss and Co San Francisco, CA Child's red leather belt with metal tip sold with two styles of Little Levi's girlswear.	Metal tip may detach and could be a choking hazard if child puts it in his mouth.	Consumers should return only the belt to Levi Strauss & Co for a \$5 refund
01/91	Club Car Inc. Augusta, GA Club Car Golf Car Brake Pawls	The loss of the parking brakes ability to hold could result in movement of an unattended car on an incline.	The firm implemented a replacement program for the defective pawls.

Date	Firm and Product	Alleged Hazard	Remedy
01/91	Branko Inc LaPorte, CO Yard Spinner outdoor game for children	The plastic fins of the spinner discs have the potential to cause serious facial lacerations or loss of sight when thrown by young children who are unable to control disc's flight path.	Firm will destroy 104 units in inventory.
01/91	Revco Drugs Inc. Twinsburg, OH Toyo 100 Music and Chasing Christmas Light Sets	Control box may overheat, melt and ignite combustibles on or near Christmas tree and result in fire and injury	The firm placed posters in stores 12/17/90 to 3/31/91 offering a refund to consumers
02/91	Personalized Software, Fairfield, IA "Empower" AC Power Supply for laptop computers	The current overload and safety grounding features may be inadequate.	The firm will replace consumer units with an improved design free of charge
02/91	Enertech Industries, Inc. Little Rock, AR Model PLP-32 Portable Unvented Propane Gas Heater	Gas could leak if the heater's regulator is not sufficiently tightened to the heater or is faulty Leaking gas could present a fire hazard	The firm recalled and leak tested the heaters to find inadequately tightened regulators

Date	Firm and Product	Alleged Hazard	Remedy
02/91	<p>IBM Somers, NY</p> <p>Certain powercords for IBM PS/2 55SX Personal Computer bearing "MULTILEC" marking.</p>	<p>Some of the powercords have a black/green (hot/safety ground) polarity reversal. This polarity reversal will put full line voltage on all exposed metal parts, presenting an electrocution hazard</p>	<p>IBM has replaced all located powercords with powercords from a different vendor.</p>
02/91	<p>U.S. Divers Co. Inc , Santa Ana, CA</p> <p>1st Stage Hi-Pressure Seal on Regulators</p>	<p>Air leakage at hi-pressure seat of 1st stage of regulator. Possibility of drowning exists.</p>	<p>The firm defined and corrected the technical bonding error. It issued a press release and other forms of notice to inform the public of the correction.</p>
02/91	<p>Polaris Industries, L.P., Minneapolis, MN</p> <p>Polaris 1991 350 4x4 "Trail Boss & Big Boss" ATVs (hub nuts)</p>	<p>If a hub nut is not properly staked, it could come off the wheels during use; the wheel could then come off and the rider could lose control of the ATV and crash.</p>	<p>Service Bulletins and letters were sent to all dealers and warranty card holders on October 24, 1990. The firm claims 100% of the 3,026 units affected will receive notice.</p>
02/91	<p>Roadmaster Corporation, Olney, IL</p> <p>Tricycle with golf bag attachment</p>	<p>The plastic cable tie, included in the unassembled kit and intended for retail display only, may pose a strangulation hazard to young children.</p>	<p>Roadmaster will discontinue their use of plastic cable ties as display components for their products in the future.</p>

Date	Firm and Product	Alleged Hazard	Remedy
02/91	Corning Incorporated, Corning, NY Pyrex baking dishes Nos. 232 & 233	Consumers may sustain cuts or scratches when picking up chipped or cracked products in the stores.	The firm recalled the dishes from the stores and redesigned the packaging that allowed dishes to be damaged.
02/91	Black and Decker, Towson, MD 37156 4.5 Inch Grinding Wheel marked "Made in Thailand"	The grinding wheels may crack and shatter in service causing mechanical injury.	Black and Decker is providing replacement wheels free of charge.
02/91	Ralph's Grocery Co., Los Angeles, CA Toyo 100 Dancing and Music Christmas Light Set	The control box may overheat and present a potential for ignition of combustibles which could result in fire and injuries.	The product was recalled and refunds offered to consumers.
03/91	Seward Company, Petersburg, VA Decorator Cubes	Hinged-lid cubes manufactured before 6/90 may present strangulation and/or suffocation hazards to young children if improperly used to store toys or children's belongings.	The firm instructed owners of the cubes to remove the lid entirely or to use spacer clamps to prevent the lid from closing. Cubes produced after 6/90 have lids that are completely removable.

Date	Firm and Product	Alleged Hazard	Remedy
03/91	Mercury Luggage Manufacturing Co. Jacksonville, FL Decorator Cubes	Hinged-lid cubes manufactured before 6/90 may present strangulation and/or suffocation hazards to young children if improperly used to store toys or children's belongings.	The firm instructed owners of the cubes to remove the lid entirely or to use spacer clamps to prevent the lid from closing. Cubes produced after 6/90 have lids that are completely removable
03/91	Trojan Luggage Company West Memphis, AR Decorator Cubes	Hinged-lid cubes manufactured before 6/90 may present strangulation and/or suffocation hazards to young children if improperly used to store toys or children's belongings.	The firm instructed owners of the cubes to remove the lid entirely or to use spacer clamps to prevent the lid from closing. Cubes produced after 6/90 have lids that are completely removable.
03/91	Lantec, Inc. Litchfield, MN Eco-Lite Charcoal Starter	Product's flash point is too low for it to be used safely as charcoal lighter fluid.	Consumers are to return product to place of purchase for a refund

Date	Firm and Product	Alleged Hazard	Remedy
03/91	Jack Eckerd Corp Largo, FL #629188 Charcoal Grill	The unattended grill is hot enough to ignite underlying flammable surfaces	The firm recalled the product and offered refunds to consumers
03/91	Foremost Sports Co General Sportscraft Co , Inc Bergenfield, NJ Wilson Batting Tees (Foremost) General Sportscraft Batting Tees	When the cord or ball of the batting tee is pulled during normal use the spike of the device may come out of the ground and strike the user causing severe injury to the head	Consumers can return the units to the place of purchase for a \$3 refund
03/91	Western States Imports Camarillo, CA Arrival & Diamondback Mountain Bikes	Should the bike frame crack at the weldments and possibly break during use the rider could lose control and fall	The firm recalled the product through a press release and other forms of notice
03/91	Heath Company Saint Joseph, MI Model IDW-5001 Weather Computer	Under certain conditions of use internal miswiring could present an electrocution hazard.	Heath Company will repair the computers free of charge A toll-free number (800-253-0570) is available for arranging repair

Date	Firm and Product	Alleged Hazard	Remedy
03/91	Briggs and Stratton Corp Wauwatosa, WI Gas Tanks on "Quantum Power" 3.5, 4, and 5 H.P Lawnmower Engines	On some units the gasoline tank may leak. The gasoline leak could present fire hazards.	Briggs and Stratton is offering free replacement of the suspect tanks at all authorized Briggs and Stratton service centers.
03/91	Topstone Industries Danbury, CT Pumpkin Candles	The plastic container holding the candle has the potential to ignite when in use resulting in a fire hazard	The firm recalled the candles and redesigned the candle container to eliminate the plastic container
03/91	Jobo Fototechnic, Inc Ann Arbor, MI Photo processors and tempering boxes	Corrosion of heating elements may allow current to pass through the water bath. A person could receive an electric shock	Customers were notified to contact Jobo for free replacement of substandard parts.
03/91	Maytag Corporation Newton, IA Teledyne Still-Man Cookeville, Tenn. Surface heating elements on freestanding 30" ranges	If the element fails as a result of internal contamination, an electric arc may produce sputtering metal that could cause injury.	The firm is replacing all elements on affected ranges, destroying contaminated parts, and changing element manufacturing process.

Date	Firm and Product	Alleged Hazard	Remedy
03/91	<p>Biobottoms Petaluma, CA</p> <p>Dugan and Bob Tee-Snap Rompers (Cut- Nos 16914, 16915, 16821, 16845, 16848, 16860)</p>	<p>Snaps fastened directly to knit fabric rather than to snap tape may detach and could present a risk of ingestion-or aspiration</p>	<p>Letters were sent to mail- order customers offering full refund.</p>
04/91	<p>Dynathrust Props Inc. Georgetown, TN</p> <p>Radio Controlled Model Airplane Propellers 6" to 22"</p>	<p>Lacerations or eye injury may result due to propelled plastic pieces of the propeller</p>	<p>The firm changed the material used to mold the plastic props The firm destroyed the defective props which they had in inventory</p>
04/91	<p>Security Chimneys, Ltd Quebec, Canada</p> <p>Direct Vent Natural and Propane Gas Kit Fireplaces Model 5GN36HAP Model 5GP36HAP</p>	<p>Improper installation and use could allow gas to accumulate and explode upon lighting the unit Consumers could be injured by flying debris or pieces of glass.</p>	<p>The firm is retrofitting units with new glass frames and screens to contain shattered glass, a sensing system to quickly stop the flow of gas if the pilot and burner are extinguished, and a warning label with new lighting instructions Propane units will be retrofitted with a device to harmlessly absorb the force of any explosions. For further information call 1-800-875-3131</p>

Date	Firm and Product	Alleged Hazard	Remedy
04/91	GE Appliances Bridgeport, CT Drip Coffeemakers	The company believes that a fire hazard may occur when a purchased thermal fuse in the coffeemaker fails to function as intended.	The firm recalled the coffeemakers and offered a \$10 incentive and pre-paid packaging.
04/91	Sakae USA, Inc Kent, WA Sakae MTS Bicycle Stems	A fall could result if the rider loses control of the bike due to a loose fitting at the stem and handlebars.	The firm improved its quality assurance program to detect inconsistencies in the tube steel thicknesses. The firm is also offering FREE replacements.
04/91	Lillian Vernon Mount Vernon, NY Set of 3 adult garden tools	The paint used on the handles of the garden tools contains an excess amount of lead.	The firm applied a plastic coating on the handles of a certain number of the tools to prevent exposure to the lead paint. The remaining number of tools were returned to the manufacturer.
05/91	Badger-Powhatan of American LaFrance Charlottesville, VA Dry chemical fire extinguisher Model P-25OMA & P-275RA American LaFrance and BECO brands.	Explosion of the extinguishers due to separation of the plastic valve threads in the nozzle assembly could cause serious injuries to consumers.	The firm replaced 1985 models with new units.

Date	Firm and Product	Alleged Hazard	Remedy
05/91	Dynamic Classics, Ltd Saddle Brook, NJ Exer-Climber and Promo-Stepper	The springs are <i>overloaded for normal</i> use and may break, resulting in bruises, lacerations and fractures of the foot	The firm offered <i>replacement</i> springs with metal clips to prevent breaking of the springs at the end loops
05/91	Design Products Company, Inc Jonesboro, AR Cabinet Light Model No. C-2-3T	Possible substandard solder connections of the supply wires to the lampholder terminals could create a short circuit and a fire hazard.	The J C. Penney Co , Inc. and a distributor recalled the product Design Products Co., Inc. redesigned the cabinet <i>light to</i> eliminate the lampholder solder connection problem.
05/91	Isanti Engineering, Inc. Isanti, MN 55040 Auger Type Log Splitter	The user or a bystander may become entrapped by the log splitter's auger which may result in serious injury including the loss of limbs or death.	Consumers were notified by a press release to remove the auger from the log splitter and discard it
05/91	Saerona Company Calexio, CA Animal String Toys by Esmond Made in Korea	Young children may be asphyxiated or strangled from the small parts or the strings present on the toy.	The firm recalled the product and offered consumers a full refund.

Date	Firm and Product	Alleged Hazard	Remedy
05/91	Noma Outdoor Products Des Moines, IA Dynamark gas riding mower (A3812060)	Gasoline fuel line may disconnect and ignite possibly burning rider.	The firm offered free replacement gas lines and clamps.
05/91	Tekna dba S-Tron Mt View, CA Tekna Diver Vehicle DV-100	Explosion from gas buildup in the fore shell of the vehicle compartment could disfigure or dismember a diver or bystander	Firm notified all owners worldwide via mail regarding the potential, gas buildup dangers and included a warning label to be affixed to the vehicle(s)
05/91	National Presto Industries, Inc. Eau Claire, WI Presto Control Master Heat Control, Model No 0690003	A wire strand can protrude through the plastic housing seam Under certain conditions, the exposed wire strand could be electrically energized and present an electric shock hazard	The company inspected and corrected, as needed, 100% of all product inventory and revised plant assembly procedures
05/91	R G Barry Corporation Columbus, Ohio Children's slipper socks with animal faces	A decorative fabric "pom-pom" nose may detach from its sock and be inhaled or swallowed by a small child, causing accidental choking.	Firm issued a press release on 1/29/91; firm notified all customers of the problem through a direct mail campaign

Date	Firm and Product	Alleged Hazard	Remedy
05/91	<p>Sta-Rite Industries, Inc. Milwaukee, WI</p> <p>"M" Series fuel oil pumps with "L90", "M90" or "A91" date code used on furnace burners</p>	<p>The pumps may leak fuel oil posing a fire hazard</p>	<p>The firm is recalling all affected pumps</p>
05/91	<p>The Thermos Company Freeport, IL</p> <p>Gas Grills</p>	<p>Some 1991 grills were assembled with Marshall Gas Controls, Inc model 150 regulators that might leak gas. Leaking gas could present a fire hazard</p>	<p>Thermos will provide a replacement for all suspect regulator and hose assemblies at no charge. Thermos will send consumers a free gift upon the return of their old regulator assembly For further information call 1-800-545-0432</p>
06/91	<p>CTC International Inc Los Angeles, CA</p> <p>100 Miniature Lights, Art. No. A8-1, (Made in China)</p>	<p>The product has no overcurrent protection and the #28 AWG wire size is deemed inadequate Damage to the wire insulation during the life of the product could expose the conductors to short circuit or arcing conditions, creating a fire hazard.</p>	<p>All shipments of product in 1990 were to Mexican accounts Also, the company intends that all future shipments of inventory will be to Mexican accounts The Mexican embassy has been notified of the company's plans</p>

Date	Firm and Product	Alleged Hazard	Remedy
06/91	CTC International, Inc Los Angeles, CA 50 Miniature Lights, 3-Way Flashing	The product has no overcurrent protection and the #27 AWG wire size is deemed inadequate. Damage to the wire insulation during the life of the product could expose the conductors to short circuit or arcing conditions, creating a fire hazard.	All shipments of product in 1990 were to Mexican accounts. Also, the company intends that all future shipments of inventory will be to Mexican accounts. The Mexican embassy has been notified of the company's plans.
06/91	Toyo Industrial Co., Ltd. Thailand Toyo 100 Light Indoor/Outdoor Chasing and Music Christmas Light Sets	The control box may overheat and be a potential for ignition of combustibles near/on Christmas trees to cause fire and injury.	Recall notices were posted in Consolidated and Revco stores. Toyo provided 800 number and refund of purchase price to consumers.
06/91	Fisher-Price Division of The Quaker Oats Co. East Aurora, NY Fun Bus, #1019	Decorative shrink wrap plastic may be removed by children who could then choke on one or more pieces of the plastic.	Consumers are instructed to remove the toy's plastic band by tearing it with a ball point pen and then removing it from the toy's roller.
06/91	Maytag Corporation Newton, IA Built-in and convertible dishwashers	An electrocution hazard could exist if the dishwasher is not properly grounded.	The firm recalled the products from its distribution chain.

Date	Firm and Product	Alleged Hazard	Remedy
06/91	<p>Maytag Corporation Newton, IA</p> <p>Jenn-Air modular electric, two-bay cooktop grills/ranges with down-draft</p>	<p>If a short circuit occurs and if the cooktop has been installed without being properly grounded, a shock hazard could exist.</p>	<p>Consumers of suspect units should contact their retailers for inspection and repair. The manufacturer is inspecting and reworking in- stock units.</p>
06/91	<p>HBSA Industries, Inc. Brooklyn, NY</p> <p>Shoe Bench (Product I D. #FX864)</p>	<p>The shoe bench may collapse when in use</p>	<p>The firm asked retailers to examine all benches and offer to replace all identified defective units</p>
06/91	<p>Yamaha Motor Corporation, U.S.A. Cypress, CA</p> <p>Sun Classic G-5A Golf Car</p>	<p>Leaking fuel could pose a fire hazard</p>	<p>The firm is offering free installation of a redesigned gas tank filler neck</p>
06/91	<p>American Honda Motors Inc. Torrence, CA</p> <p>All-Terrain Vehicle Model TRX300FW</p>	<p>Brake line contact with fender may result in loss of front brakes and longer stopping distance</p>	<p>The firm mailed notice to owners and issued a press release offering owners a technical fix.</p>

Date	Firm and Product	Alleged Hazard	Remedy
07/91	Hartman Products Los Angeles, CA 1/2 Inch Curling Iron, Model PC-2	The lead wires from the curling iron barrel to the handle were pinched in some units, causing Hi Pot test failures. A Hi Pot test failure could result in a direct short circuit to the barrel to present an electric shock hazard.	Owners who purchased this Hartman curling iron 8/90 to 10/18/90 from a Sears catalog outlet should return it to the nearest Sears store for a refund or to Hartman Products for a free replacement.
07/91	Orca Industries Inc Toughkenamon, PA Delphi 3 0 Dive Computer	Due to a software "bug" in the dive computer an inaccurate depth read-out was found during decompression dives.	The firm sent recall letters to all authorized dealers and consumers. Replacement with a 4.0 version dive computer was offered for the return of the 3.0 version.
07/91	Thomson Consumer Electronics, Inc. Indianapolis, IN 20 Inch RCA Television Receivers for hotel and motel industry.	Television bracket/stand mounting screws may, if too long, contact live electrical part in TV receiver resulting in a potential electric shock hazard.	The firm notified distributors and consumers of problem and sent authorized servicers to modify TV receivers without charge.

Date	Firm and Product	Alleged Hazard	Remedy
8/91	Schwinn Bicycle Company Chicago, IL XR-5 Exerciser	Amputation and crushing injuries to fingers and toes of children	The firm issued notice and posters to all authorized Schwinn dealers. Pediatrician posters were distributed through the American Academy of pediatrics. A chain guard retrofit kit was offered and an advertisement appeared in "Cycling and Fitness" magazine. Also, a joint press release was issued with the Commission on 10/1/91.
08/91	Sanitoy, Inc Fitchburg, MA "Nursery Crib Toy"	The crib toy may be torn exposing inner foam rubber presenting a possible suffocation hazard if material is inhaled or ingested.	All units in the hands of importer were destroyed and retail units are no longer offered for sale.
08/91	Sassy, Inc. Grand Rapids, MI Infant Bath Seat	Snaps located on seat belt of infant bath seat do not hold or separate from plastic belt.	The company replaced the plastic belt with a nylon webbing belt and installed a polypropylene side release buckle

Date	Firm and Product	Alleged Hazard	Remedy
08/91	<p>KG Engineering/Ocean State International Inc. Woonsocket, RI</p> <p>Mountain Bike Stem (Girvin—Pro Flex)</p>	A rider may lose control of the bike's steering, possibly resulting in a fall from the bike.	The firm sent safety bulletins to all its customers and dealers warning of the stem cracking problem. Replacement stems were offered in return. Also, a recall notice appeared in the July issues of "Velo News" and "Bicycle Showcase" magazines.
08/91	<p>DeLonghi America Carlstadt, NJ</p> <p>Oil-filled Electric Radiator Heaters produced 1980-1988.</p>	Possible failure of electrical components could result in fire escaping the unit.	DeLonghi will provide new replacement control panels to owners who call 201-507-1110.
08/91	<p>20th Century Companies, Inc. Wheeling, IL</p> <p>3/8" x 1/4" Anchor Brass Flare Connectors, Part #406-64</p>	Connectors produced in early 1990 were improperly machined and are subject to breakage. Some of these connectors may be used with gas appliances. In the unlikely event a connector were to break without being detected, it could leak gas which could ignite and create a fire or explosion hazard.	The firm recalled all connectors from the suspect period.

Date	Firm and Product	Alleged Hazard	Remedy
08/91	Stanley Home Automation, Inc Novi, MI Printed Circuit Boards used in Garage Door Operators	The downward motion of the door could cause serious injury or death by entrapment or the continuous drive could result in fire.	The firm provides a free replacement circuit board in a postage pre-paid carton so that the consumer can return the old unit.
08/91	Mitsubishi Electronics America, Inc Cypress, CA Models SS-2100 and SS-3100 stereo loudspeakers	Smoke and fire may result when speaker parts overheat.	Consumers should return speakers to the nearest service center for repairs.
08/91	Pomeco Corporation Long Beach, CA Hose end swivel for gasoline filler nozzle	When swivels separate, there is leakage of gasoline. Fire or explosion is possible.	Distributors should return affected swivels for free replacements
08/91	Robertshaw Controls Company, Grayson Controls Division Long Beach, CA 7100 Series Gas Valves	Residue on the gas valve seat can cause the valve's regulator to stick causing improper gas pressure regulation that could produce carbon monoxide or fire hazards.	Robertshaw revised its cleaning procedures to ensure that the residues are removed on future production. It also recalled for replacement the suspect gas valves already sold.

Date	Firm and Product	Alleged Hazard	Remedy
08/91	<p>Gerry Baby Products Denver, CO</p> <p>Folding umbrella stroller, #127, 136, 166, 195, 196 Only those produced in May 1991.</p>	<p>Brakes, when locked, may not hold on an incline Stroller may roll, putting child at risk of fall or collision.</p>	<p>Consumers who purchased these strollers should call Gerry at 1-800-525-2472 regarding how to obtain a replacement stroller</p>
08/91	<p>Pentapco, Inc. Elizabeth, NJ</p> <p>Garment Steamer</p>	<p>Overtightening of the water fill plug could cause the lock tab to break allowing steam and/or hot water to leak from the back of the steamer and burn the user</p>	<p>Consumers will be refunded the purchase price at the retail level or by mail to the firm</p>
09/91	<p>Hollander Home Fashions Newark, NJ</p> <p>"Mother's Helper" Infant Cushion</p>	<p><i>Suffocation risk</i></p>	<p>Call 1-800-638- 2772 for information</p> <p>Note: Recall begun in April 1990 Corrective action plan accepted by Commission following additional public notice through posters in physicians' offices and hospital maternity wards</p>

Date	Firm and Product	Alleged Hazard	Remedy
09/91	Patient Comfort d/b/a Comfort Products, Inc Carrollton, TX Comfort Tote, Comfy Tot, Cushie Comfort	Suffocation risk.	Call 1-800-638- 2772 for information. Note. Recall begun in April 1990 Corrective action plan accepted by Commission following additional public notice through posters in physicians' offices and hospital maternity wards
09/91	Nooner Productions, Inc d/b/a Pinky Baby Products Co Houston, TX Pinky Cozy Cushion	Suffocation risk.	Call 1-800-638- 2772 for information Note. Recall begun in April 1990. Corrective action plan accepted by Commission following additional public notice through posters in physicians' offices and hospital maternity wards.

Date	Firm and Product	Alleged Hazard	Remedy
09/91	Tailored Baby San Fernando, CA Comfort Cushion	Suffocation risk	Call 1-800-638-2772 for information. Note: Recall begun in April 1990. Corrective action plan accepted by Commission following additional public notice through posters in physicians' offices and hospital maternity wards
09/91	MFP, Inc. Hays, KS Sof Sak Infant Cushion	Suffocation risk.	Call 1-800-638-2772 for information. Note: Recall begun in April 1990. Corrective action plan accepted by Commission following additional public notice through posters in physicians' offices and hospital maternity wards.

Date	Firm and Product	Alleged Hazard	Remedy
09/91	Gold, Inc Denver, CO Gold Bug Support Sack	Suffocation risk.	Call 1-800-638-2772 for information Note Recall begun in April 1990 Corrective action plan accepted by Commission following additional public notice through posters in physicians' offices and hospital maternity wards
09/91	The Fourth Little Pig San Anselmo, CA "Baby Minder" Infant Cushion	Suffocation risk	Call 1-800-638-2772 for information Note Recall begun in April 1990 Corrective action plan accepted by Commission following additional public notice through posters in physicians' offices and hospital maternity wards

Date	Firm and Product	Alleged Hazard	Remedy
09/91	Cozy Baby Products, Mount Vernon, NY Cozy Baby Infant Cushion	Suffocation risk.	Call 1-800-638-2772 for information. Note: Recall begun in April 1990. Corrective action plan accepted by Commission following additional public notice through posters in physicians' offices and hospital maternity wards
09/91	Jumping-Jacks Shoes, Inc Monett, MO Baby Jacks Infant Cushion	Suffocation risk.	Call 1-800-638-2772 for information. Note: Recall begun in April 1990. Corrective action plan accepted by Commission following additional public notice through posters in physicians' offices and hospital maternity wards.

Date	Firm and Product	Alleged Hazard	Remedy
09/91	Baby Sak Pembroke Pines, FL Baby Sak Infant Cushion	Suffocation risk.	Call 1-800-638-2772 for information. Note: Recall begun in April 1990 Corrective action plan accepted by Commission following additional public notice through posters in physicians' offices and hospital maternity wards.
09/91	Kalencom, Inc. New Orleans, LA Baby Comfy Cushion	Suffocation risk.	Call 1-800-638-2772 for information. Note: Recall begun in April 1990 Corrective action plan accepted by Commission following additional public notice through posters in physicians' offices and hospital maternity wards.

Date	Firm and Product	Alleged Hazard	Remedy
09/91	Sommers Oil Co. Savannah, GA Gasoline contaminated kerosene.	The gasoline contaminated kerosene could cause a serious explosion or fire.	Consumers were advised by public notice to return any kerosene purchased from this dealer between 2/17/91 and 2/19/91.
09/91	American Appliance Manufacturing Company Santa Monica, CA Decorative gas valve covers on natural gas water heaters manufactured from 7/86 through 7/88.	The original covers were of a flammable plastic. If flames came from the combustion chamber, the cover could ignite.	The firm offered free replacement gas valve covers of a flame-retardant material.
09/91	Chilcote Homes, Inc. Anaheim, CA 92805 Decorative Chimney Shrouds	Redirection of the chimney smoke and gases by the decorative shroud can cause the chimney to overheat and cause a fire.	Chilcote is inspecting all residences built and replacing the defective shrouds.
09/91	General Power Equipment Co. Harvard, IL 5 HP Gasoline Powered Chipper Shredder	Failure of an electrical interlock switch could allow a person to contact the rotating shredding mechanism, resulting in possible laceration or amputation.	Consumers should return affected products to retailers or service centers for replacement of interlock switches.

Date	Firm and Product	Alleged Hazard	Remedy
09/91	<p>Lashdell Underwater Partners d/b/a Tekna San Diego, CA</p> <p>5500 series of 2nd Stage Regulator and Octopus manuf. and dist. by S-Tron Holdings, Inc. from 5/89 through 12/90</p>	<p>A design defect that causes the regulator to be difficult to breathe through, results in the regulator failing to deliver air to the diver or free-flows air causing possible air embolism, decompression sickness or drowning.</p>	<p>The firm has notified all Tekna dealers via company news letter and point of purchase bulletin. The firm is offering a suitable replacement regulator at no charge. An 800 number is set-up for the consumers' convenience. A unilateral press release was issued by the firm, specifically to diving publications.</p>
09/91	<p>Mr. Coffee, Inc Bedford Heights, OH</p> <p>Cone Filter Microwave Coffee Brewer</p>	<p>The cone filter microwave coffee brewer section may separate from coffee mug, which may result in hot water or coffee spilling on user.</p>	<p>Firm will exchange original cone filter brewer with a basket style replacement when consumer returns blade part of original brewer to company. Joint press release, letters of notification to service centers, retailers, sales reps.</p>

Date	Firm and Product	Alleged Hazard	Remedy
09/91	Zenith Products Corp Alston, PA Bathroom Cabinet Model TCS30	The mirror of the bathroom cabinet may fall from the cabinet door possibly injuring someone in the immediate area.	The firm has enacted a quality control checklist to ensure the situation does not recur.

APPENDIX G

Litigation and
Settlements

LITIGATION AND SETTLEMENTS

Part I of this appendix summarizes the federal court cases, categorized by type, to which the Commission was a party during fiscal year 1991. Part II summarizes the civil penalty settlement agreements accepted by the Commission during FY 1991.

Part I

INJUNCTIONS

1. United States v Toys R Us, Inc , Charles Lazarus, and Michael Goldstein, Civil Action No 90-3315 (D N.J.) On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys. Following discovery, both sides filed briefs on October 17, 1990 and reply briefs a week later. On October 31, 1990 U S District Judge Maryanne Trump Barry heard oral arguments, in Newark, New Jersey, on a preliminary and permanent injunction. Following the hearing the parties attempted, unsuccessfully, to settle the case. On January 9, 1991 the Judge denied the government's motion for an injunction and dismissed the case. In a 25-page opinion, the Judge found that Toys R Us had committed 11 toy violations (of 13 charged) and that it was a "close question" whether the firm is reasonably likely to commit future violations. The Judge's "deciding factor" was the promise that ACTS Testing Labs, Inc would begin testing, in January 1991, all toys imported by Toys R Us. On January 25, 1991 the government filed a motion for the Judge to reconsider her opinion and order, arguing that an injunction should issue and that the toy "Ernie the Drummer" is intended for children under three. On March 8, 1991 the Judge denied the motion, finding that it was untimely filed and that it did not present any new facts or identify any controlling cases that were overlooked.
2. United States v. Ilco Toy Co , USA and Martin Scheman, Civil Action No. 90-C-5405 (JFK) (S.D.N.Y) On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys. Following some discovery and the filing of briefs, U S. District Judge John F. Keenan on January 17, 1991 denied the government's motion for a preliminary injunction. He did so "reluctantly," and primarily because of the government's "inability, despite inspections of defendants' products, to establish that there have been any violations since October 1989." On March 4, 1991 the Judge decided to keep the case on his docket, at least until November 18, 1991, to see whether Ilco committed any additional violations. On April 9, 1991 Ilco wrote a letter to the Judge asking for an order that its counsel be permitted to be present, on five days notice, for all government sampling and testing of Ilco's toys. The Judge signed the order on April 10, 1991, before the government even knew that Ilco had proposed it. On April 16, 1991 the government sent a letter to the Judge asking that he vacate the order pending a hearing on this issue. On September 9, 1991 the Judge vacated the order and directed the Commission to videotape its tests of Ilco's toys when requested by Ilco to do so.
3. United States v Lionel Leisure, Inc. and Michael J. Vastola, Civil Action No. 90-5417 (E.D. Pa.). On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys. Following discovery, but before a preliminary injunction hearing scheduled for November 5, 1990 in Philadelphia, the parties settled the case. On November 9, 1990 the Court entered a consent decree which enjoins Lionel Leisure from importing violative toys.
4. United States v. Beachcombers International, Inc. and Harry Chernin, Civil Action No 90-255-CIV-FTM-17D (M D Fla.). On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys. Following two status

hearings held in September 1990 in Ft Myers, Florida, the parties settled the case On October 17, 1990 the Court entered a consent decree which enjoins Beachcombers from importing violative toys

5. United States v Child World, Inc and Dennis H. Barron, Civil Action No 1 90 CV 1486 (N D Ohio) On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys The parties settled the case On November 9, 1990 the Court entered a consent decree which enjoins Child World from importing violative toys
- 6 United States v. Value Merchants, Inc and Phillip Cohen, Civil Action No 90-C-0824 (E D Wisc) On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys Following discovery, but before a scheduled preliminary injunction hearing on November 28, 1990, the parties settled the case On December 14, 1990 the Court entered a consent decree which enjoins Value Merchants from importing violative toys
- 7 United States v. Division Sales, Inc., Justen Products and Morton Marks, Civil Action No 90-C-4837 (N D Ill) On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys Following five status conferences in Chicago, the parties settled the case On November 11, 1990 the Court entered a consent decree which enjoins Division Sales and Justen Products from importing violative toys
8. United States v Hanstai International, Inc and James Ou, Civil Action No CV-90-4168 (JFK) (S D N Y) On August 31, 1990 the government filed a complaint and motion for preliminary injunction against an importer of bicycles The parties settled the case On October 22, 1990 the Court entered a consent decree which enjoins Hanstai and Mr Ou from importing violative toys
- 9 United States v Mike Catalano and R.W. Bond, d/b/a Great Lakes Fireworks Co , Civil Action No 1 91CV0333 (N D Ohio) On February 21, 1991 the government filed a complaint and consent decree signed by a mail order distributor of fireworks components On March 22, 1991 the Court entered the decree which enjoins Mr Catalano and Mr. Bond from distributing violative fireworks
- 10 United States v O.K K Trading and Chun-Ting Hung, Civil Action No. H91-1625 (S D Tex) In June 1991 the government filed a complaint and consent decree signed by an importer of toys On June 18, 1991 the Court entered the decree which enjoins O K.K. Trading from importing violative toys.

SEIZURE

U S v Articles of Banned Hazardous Substances Consisting of an Undetermined Number of Cans of Rainbow Foam Paint, Civil Action No 3 91CV00230 (PCD) (D. Conn.) On April 26, 1991 the government filed an action seeking the seizure of self-pressurized containers of banned children's paint. On April 29, 1991 U S Marshals seized the cans of paint. Following the May 9, 1991 due date for filing claims for the paint, the government moved for default and judgment on June 6, 1991. On June 11, 1991 Linda Weill filed an opposition to that motion. On the same day, however, Judge Peter Dorsey signed an order granting judgment against the paint, which was entered on June 13, 1991 On June 20, 1991 Ms. Weill and X-Tra Art, Inc. filed a motion to intervene in the case and to vacate the default judgment. On July 10, 1991 the government filed an opposition. On July 31, 1991 Judge Dorsey granted the motion to intervene and to vacate the judgment. The parties engaged in discovery in August and September 1991.

CRIMINAL ACTION

During fiscal year 1990 the government had presented to a grand jury information concerning possible violations of a CPSC statute. The grand jury continued through fiscal year 1991 to consider this matter. No additional details can be disclosed.

INSPECTION WARRANTS

In the Matter of Establishment Inspection of Skil Corporation, Civil Action No. 86-M-263 (N.D. Ill.) and No. 88-1126 (7th Cir.). Upon the Commission's application, the U.S. Magistrate issued a warrant on November 14, 1986, pursuant to section 16 of the CPSA, for inspection of books and records concerning Skil circular saws. The warrant was served on November 17, 1986, but Skil refused the Commission access. The Government filed a motion for an order to show cause why Skil should not be held in contempt. Skil filed an opposition and a motion to quash the warrant. Following a January 8, 1987 hearing, the Magistrate granted the Government's motion and denied Skil's motion. The district court affirmed the Magistrate, and then the Court of Appeals affirmed the district court on May 13, 1988. The parties continue to disagree about the Commission's right to certain documents that Skil claims are privileged. The parties agreed to a settlement under which CPSC would see test reports on the saws and would question Skil engineers about other documents for which Skil claims privilege. On January 10, 1991 the Magistrate entered an order incorporating this settlement.

CIVIL PENALTY

United States v. Division Sales, Inc. and Justen Products, Civil Action No. 91-C5203 (N.D. Ill.). On August 29, 1991 the government filed a complaint seeking civil penalties against two toy firms based on the sale of banned lawn darts and the failure to report to the Commission.

FREEDOM OF INFORMATION

Reliance Electric Company and Challenger Electric Equipment Corporation v. CPSC, Civil Action No. CV-87-1478 (D. D.C.). On May 29, 1987, the plaintiffs filed a complaint and application for temporary restraining order, to enjoin the disclosure of information under section 6 of the CPSA. After a June 2, 1987 hearing, the court issued a TRO and ordered the parties to file cross-motions for summary judgment. Both parties did so in July 1987. On September 19, 1989, the court ruled that the Commission had followed the proper procedures and that most of the documents could be released. Oral argument was heard on November 2, 1990. On January 22, 1991 the Court of Appeals affirmed in part and remanded in part. In its opinion, the Court: (1) upheld the District Court's decision that the Commission could disclose some pages; (2) ruled that Reliance is not entitled to a trial de novo; and (3) with respect to many pages, remanded to the District Court with directions to remand the matter to the Commission to "explain why it believes [Reliance's] accuracy objections are not well-taken, if it continues to adhere to that position." On March 15, 1991 the Court of Appeals denied the government's request for costs, and awarded costs in the amount of \$1796.70 to Reliance. On the same day the Court of Appeals sent a letter to the District Court transmitting the case to that Court. On April 26, 1991 the District Court remanded the case to the Commission.

OTHER CASES AGAINST THE COMMISSION

1. X-Tra Art, Inc. and Linda Weill v. Consumer Product Safety Commission, Civil Action No. 91-1336MHP (N.D. Cal.) and No. 91-16027 (9th Cir.). On May 3, 1991 the distributors of self-pressurized containers of paint for children, Rainbow Foam Paint, filed a complaint against the Commission seeking declaratory relief, a temporary restraining order (TRO), and a preliminary

and permanent injunction (In a separate action in Connecticut in April 1991, the government had seized cans of the paint which it found to be banned hazardous substances under the Federal Hazardous Substances Act) Following a hearing on May 7, 1991 in San Francisco, Judge Marilyn Hall Patel granted a TRO prohibiting the Commission from further acting against or disclosing information on Rainbow Foam Paint Both sides filed briefs on May 14, 1991 At a hearing on May 29, 1991 the Judge heard oral argument on a preliminary injunction On June 12, 1991 Judge Patel entered orders denying the preliminary injunction and dismissing the case In an accompanying opinion, she ruled that in issuing the letter of advice to X-Tra Art and declaring the paint to be a banned hazardous substance, the Commission had followed the Federal Hazardous Substances Act, and that no proceeding to issue a rule specifically banning the paint was required The Judge also rejected X-Tra Art's due process, equal protection, and 6(b) arguments She did not consider the merits of the Commission staff's determination that the paint was a banned hazardous substance, holding that that determination could be challenged only in an enforcement action On July 3, 1991 X-Tra Art filed a notice of appeal to the U S. Court of Appeals for the Ninth Circuit The Court ordered X-Tra Art's brief to be filed on October 21, 1991, and the government's brief to be filed on November 18, 1991

2. Writing Instrument Manufacturers Association, Inc , et al v Consumer Product Safety Commission, et al , Civil Action No. 4-91-048 (E D Tenn) On July 1, 1991 a trade association and some of its members filed an action against the government seeking an injunction to prevent the Commission from enforcing chronic hazard labeling requirements, as well as an order that the Commission issue final chronic hazard guidelines On September 3, 1991 the government filed a motion to dismiss the case and/or for summary judgment The Association filed an opposition to the motion on September 30, 1991

Part II

CIVIL PENALTY SETTLEMENT AGREEMENTS ACCEPTED BY THE COMMISSION

1. In the Matter of Turri Disposal, Inc , CPSC Docket No 90-C0012. Turri agreed to pay a civil penalty of \$4,000 in settlement of Commission staff allegations that the New Jersey based corporation failed to report, pursuant to Section 15(b) of the CPSA, 15 U S C. 2064(b), the distribution of certain refuse bins which had been banned and declared hazardous products The staff alleged that although Turri was aware that it had distributed hazardous bins, it failed to report that information to the Commission. Subsequently, one of these bins tipped over and critically injured a child. Turri denied that its refuse bins were in violation of the ban and that it had any obligation to report any information to the Commission under Section 15(b) of the CPSA with respect to the refuse bins.
2. In the Matter of Wagner Spray Tech Corporation, CPSC Docket No 91-C0002. Wagner Spray Tech Corporation agreed to pay a civil penalty of \$120,000 in settlement of Commission staff allegations that the firm failed to report a defect in its power paint rollers which could create a substantial product hazard, as required under 15 U.S C 2064(b). The staff alleged that the firm did not report to the Commission until it had become aware of twenty six head and facial injuries caused by the ejection of the paint roller's canister lid Wagner denied that its power paint rollers contain a defect which creates or could create a substantial product hazard within the meaning of 15 U S C 2064(a) The firm also denied any obligation to report information to the Commission under Section 15(b) of the CPSA with respect to its power paint rollers

3. In the Matter of Graco Children's Products, Inc., CPSC Docket No 91-C0003. Graco agreed to pay a civil penalty of \$100,000 in settlement of Commission staff allegations that the Pennsylvania manufacturer failed to report a defect in its line of full size "stroll-a-bed" type strollers which could create a substantial product hazard, as required by 15 U.S.C. § 2064(b). The staff alleged that Graco learned of seven incidents whereby the tip of a young child's fingers were crushed or amputated in a stroller's recline mechanism latch, that Graco designed a latch cover for future production and placed latch covers on strollers in inventory but did not report the defective latch to the Commission. The firm denied that its strollers contained a defect which could create a substantial product hazard within the meaning of 15 U.S.C. § 2064(a) of the CPSA. It also denied any obligation to report information to the Commission under section 15(b) of the CPSA with respect to these strollers.
4. In the Matter of Century Products Company, CPSC Docket No. 91-C0004. Century Products Company agreed to pay a civil penalty of \$50,000 in settlement of Commission staff allegations that the firm failed to report a defect in its Roadster baby walkers, Model 3676, which could create a substantial product hazard, as required by 15 U.S.C. § 2064(b). The staff alleged that the firm did not report to the Commission until it had become aware of ten safety complaints concerning a potential choking hazard involving the horn of the walker. Century stated its walkers are safe and defect free and denied that the subject baby walkers contain a defect which creates or could create a substantial product hazard within the meaning of 15 U.S.C. § 2064(a). The firm also denied any obligation to report information to the Commission under Section 15(b) of the CPSA, with respect to these baby walkers.
5. In the Matter of Amerex Corporation, CPSC Docket No 91 C0005. Amerex agreed to pay a civil penalty of \$30,000 in settlement of Commission staff allegations that Amerex failed to report a defect in its model 456 dry chemical fire extinguisher which could create a substantial product hazard, as required under 15 U.S.C. § 2064(b). The staff alleged that between 412 and 550 units of a suspect population of 15,000 units of the fire extinguisher contained carry handles that were not properly shaped by the casting die. The staff further alleged (1) these misformed handles did not make proper contact with the valve that activates the outflow of the fire extinguishing chemicals, and (2) a consumer attempting to use the fire extinguisher to put out a fire would not be able to activate the fire extinguisher in accordance with the operating instructions. Amerex denied that the fire extinguisher is a consumer product, that it knew or should have known that the fire extinguisher could create a substantial product hazard, and that it had any obligation to report any information regarding the fire extinguisher to the Commission under Section 15(b) of the CPSA.
6. In the Matter of Russ Berrie and Company, Inc. CPSC No. 91-C0006. Russ Berrie and Company, Inc. agreed to pay a civil penalty of \$30,000 to settle staff allegations that it had failed to report a defect in its Baby Bibi Bears, #844. The staff alleged that in 1988 the firm received at least 16 complaints from retailers about loose, missing or damaged eyes on these bears, that the firm tested its inventory and discovered the eyes could come off easily, and that the eyes could create a serious choking hazard to small children. Although Russ Berrie conducted a recall of these bears from its distribution chain, it did not publicize its recall or report the problem to the Commission staff under Section 15(b) of the CPSA. The firm denied that its bears presented a hazard or that it had any obligation to report to the Commission under Section 15(b) of the CPSA.
7. In the Matter of Black and Decker (U.S.) Inc., CPSC Docket No. 91-C0007. Black and Decker agreed to pay a civil penalty of \$125,000 in settlement of Commission staff allegations that the Maryland based corporation failed to report a defect which could create a substantial product hazard involving its model no. 82209 (types 1 and 2) and 82210 (types 1 and 2) electric weed trimmers, as required by 15 U.S.C. § 2064(b). The staff alleged that Black and Decker had

sufficient information by October 1986 and no later than January 1987 to reasonably support the conclusion that these weed trimmers contained a reportable defect. Black and Decker did not report such information to the Commission until September 11, 1987. The firm denied that the trimmers contained a defect which creates or could create a substantial product hazard within the meaning of 15 U S C § 2064(a). The firm also denied any obligation to report information to the Commission under Section 15(b) of the CPSA with respect to these trimmers.

APPENDIX H

Advisory Opinions

ADVISORY OPINIONS

No.	Date of	From/To	Subject
312	03/06/91	Clement D. Erhardt/ Stephen S. Kellner	Sign and the like bearing certain warnings are "accompanying literature containing directions for use" and thus are labeling under Section 2(n) of the FHSA

APPENDIX I

Index of Products
Regulated by CPSC

INDEX OF PRODUCTS REGULATED BY CPSC

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Acetaminophen	PPPA	special packaging exemption	1700.14(a)(16) 1700.14(a)(16)(i), (ii)
Acetic acid	HSA	labeling	1500.129(g)
Adhesives, containing methyl alcohol	HSA HSA	labeling exemption from labeling	1500.133 1500.83(a)(34)
nitrocellulose base	HSA	exemption from labeling	1500.83(a)(10)
floor covering	HSA	exemption from labeling	1500.83(a)(13)
extremely flammable contact	CPSA CPSA	ban to be regulated under CPSA	1302 1145.3
Aerosols (see self-pressurized products)	HSA	suggested labeling	1500.130
Aluminized polyester film kite	HSA	ban	1500.18(c)(1)
Ammonia, ammonia water (household), ammonium hydroxide	HSA	labeling	1500.129(g)
Antennas (CB base station and TV) (Omnidirectional CB base station)	CPSA CPSA	labeling requirement performance and certification	1402 1204
Antifreeze, ethylene glycol-base	HSA PPPA	labeling special packaging	1500.132 1700.14(a)(11)
Antiquing kits	HSA	exemption from labeling	1500.83(a)(25)
Appliances, coal and wood-burning	CPSA	provision of performance and technical data	1406
Architectural glazing materials	CPSA	safety standard	1201
Art materials	HSA	exemption from ban	1500.85(a)(4)
Artist's paints	CPSA	exemption from lead limit	1303.3(c)(2)
Asbestos-containing patching compounds	CPSA CPSA	ban to be regulated under the CPSA	1304 1145.4

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Asbestos-containing garments for general use	HSA	ban	1500.17(a)(7)
Asbestos-containing artificial emberizing materials	CPSA CPSA	ban to be regulated under the CPSA	1305 1145.5
Aspirin products	PPPA	special packaging effervescent tablet exemption unflavored powders exemption	1700 14(a)(1) 1700.14(a)(1)(i) 1700 14(a)(1)(ii)
Baby bouncers and walkers	HSA	standard and ban exemption from banning	1500 18(a)(6) 1500 86(a)(4)
Balloons, plastic mixtures	HSA	exemption from banning	1500 85(a)(4)
Bassinet legs	CPSA	to be regulated under the CPSA	1145.15
Batteries, storage, wet-cell	PPPA	exemption from special packaging	1700.14(a)(9)
Benzene (benzol)	HSA	special labeling	1500.14(b)(3)(i)
Benzene (paint solvents)	PPPA	special packaging	1700.14(a)(15)
Bergamot oil	HSA	labeling	1500 13(e)
Betamethasone	PPPA	exemption from special packaging	1700.14(a)(10)(viii)
Bicycles	HSA	ban safety requirements	1500 18(a)(12) 1512
Biological specimens, preserved	HSA	exemption from ban	1500.85(a)(4)
Blasting caps	HSA	exemption from labeling	1500.83(a)(35)
Butane in cigarette lighters	HSA	exemption from labeling	1500.83(a)(29)
Carbolic acid (phenol)	HSA	labeling	1500.129(d)
Carbon tetrachloride	HSA	ban	1500.17(a)(2)
Carpets and rugs (large)	FFA	standard (FF 1-70)	1630
Carpets and rugs (small)	FFA	standard (FF 2-70)	1631

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Caustic poisons potash	HSA	labeling	1500.129
	HSA	labeling	1500.129
soda	PPPA	special packaging	1700.14(a)(5)
	HSA	labeling	1500.29(j)
	PPPA	special packaging	1700.14(a)(5)
Cellulose sponges	HSA	exemption from labeling	1500.83(a)(15)
Cellulose insulation	CPSA	standard	1209
	CPSA	labeling	1404
Charcoal briquettes	HSA	classification as hazardous special labeling	1500.12(a)(1) 1500.14(b)(6)
Chemistry sets	HSA	exemption from labeling exemption from banning	1550.83(a)(23) 1500.85(a)(1)
Child-resistant packaging (and see special packaging)	PPPA	criteria and substances subject	1700
Chlorofluorocarbons, self- pressurized products containing	CPSA	labeling requirement	1401
Cholestyramine, anhydrous	PPPA	exemption from special packaging	1700.14(a)(10)(v)
Cigarette lighters	HSA	exemption from labeling exemption from labeling	1500.83(a)(29) 1500.83(a)(20)
Cleaning products	HSA	exemption from labeling	1500.83(a)(11)
Clothing (see wearing apparel, sleepwear)			
Coal burning appliances (see appliances)			
Coldwave permanent neutralizers containing sodium bromate or potassium bromate	PPPA	special packaging	1700.14(a)(19)
Colestipol	PPPA	exemption from special packaging	1700.14(a)(10)(xv)
Combustible hazardous substances	HSA	definition flashpoint testing	1500.3(c)(iii) 1500.43a

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Conjugated estrogens tablets	PPPA	exemption from special packaging	1700 14(a)(10)(xvii)
Consumer product	CPSA	reporting of substantial product hazards	1115
Containers, consumer-owned (portable)	HSA	exemption from full labeling	1500 83(a)(14)
Controlled drugs	PPPA	special packaging	1700 14(a)(4)
Corrosive substances	HSA	definition	1500 3(b)(7), (c)(3)
Cosmetics	HSA	exemption	1500 81(a)
Crib hardware	CPSA	to be regulated under the CPSA	1145 14
Cribs (full-size)	HSA	ban safety requirements	1500.18(a)(13) 1508
Crib (non full-size)	HSA	ban safety requirements	1500.18(a)(14) 1509
Crib, mesh-sided	CPSA	to be regulated under the CPSA	1145.12
Cyanide salts	HSA	ban	1500 17(a)(5)
Dietary supplements, iron-containing	PPPA	special packaging	1700 14(a)(13)
Diethylene glycol	HSA	labeling special labeling exemption from labeling	1500 14(a)(1) 1500.14(b)(1) 1500.83(a)(15)
Diethylenetriamine	HSA	labeling	1500.13(c)
Diglycidyl ethers	HSA	labeling	1500 13(c)
Diphenhydramine preparations	PPPA	special packaging	1700 14(a)(17)
Disclaimer deceptive use of	HSA	misbranded	1500.122

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Drain cleaners, liquid	HSA PPPA	ban special packaging	1500.17(a)(4) 1700.14(a)(5), (9)
Drugs, controlled	PPPA	special packaging	1700.14(a)(4)
Drugs, oral prescription Except: Nitroglycerin tablets (sublingual) Isosorbide dinitrate (10 mg. sub- lingual and chewable tablets)	PPPA	special packaging	1700.14(a)(10) 1700.14(a)(10)(i) 1700.14(a)(10)(ii)
Erythromycin ethylsuccinate (8 gm oral suspension and granules for oral suspensions)			1700.14(a)(10)(iii)
Erythromycin ethylsuccinate tablets (no more than 16 gm)			1700.14(a)(10)(xvi)
Cyclical oral contraceptives			1700.14(a)(10)(iv)
Anhydrous cholestyramine (powder form)			1700.14(a)(10)(v)
Potassium supplements (containing not more than 50 MEq potassium per unit dose package)			1700.14(a)(10)(vi)
Sodium fluoride (264 mg per package of liquid forms and tablet forms)			1700.14(a)(10)(vii)
Betamethasone (12.6 mg per package)			1700.14(a)(10)(viii)
Pancrelipase in tablet, capsule or powdered form			1700.14(a)(10)(ix)
Prednisone tablets (not more than 105 mg per package)			1700.14(a)(10)(x)
Mebendazole (600 mg per package)			1700.14(a)(10)(xiii)
Methylprednisolone tablets (not more than 84 mg per package)			1700.14(a)(10)(xiv)
Colestipol (packages containing not more than 5 grams of powder)			1700.14(a)(10)(xv)
Conjugated estrogens tablets (not more than 32 mg per package)			1700.14(a)(10)(xvii)
Norethindrone acetate tablets (not more than 50 mg per package)			1700.14(a)(10)(xviii)
Medroxyprogesterone acetate tablets			1700.14(a)(10)(xix)
Drugs, iron containing	PPPA	special packaging	1700.14(a)(12)
Dry-cleaning solvents	HSA	exemption from labeling	1500.83(a)(18)
Emberizing materials, arti- ficial containing asbestos	CPSA	ban	1305

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Epoxy resins	HSA	labeling	1500.13(c)
Erythromycin ethylsuccinate, suspension and granules for suspension chewable tablets	PPPA	exemption from special packaging	1700.14(a)(10)(iii) 1700.14(a)(10)(xvi)
Ethylenediamine	HSA	labeling	1500.13(c)
Ethylene glycol in felt pads	HSA	exemption from labeling special labeling	1500.83(a)(28) 1500.14(b)(4)
Ethylene glycol	HSA	labeling special packaging	1500.14(a)(2), (b)(2) 1700.14(a)(11)
Ethylene glycol antifreeze	HSA	labeling	1500.132
Expandable children's enclosures	CPSC	to be regulated under the CPSA	1145.13
Exports (noncomplying products)	All	reporting requirements	1019
Extremely flammable contents of self-pressurized containers	HSA	definition method to determine flashpoint testing exemption from labeling.	1500.3(c)(6)(vii) 1500.45 1500.46 1500.83(a)(1)
Extremely flammable hazardous substances	HSA	definition testing method	1500.3(c)(6)(i) 1500.43a
Extremely flammable solids	HSA	definition testing method	1500.3(c)(6)(v) 1500.44
Eye irritants	HSA	testing method definition	1500.3(b)(8), (c)(4) 1500.42
Fabrics	FFA	flammability	1602-1632
Felt-tip marking devices	HSA	labeling exemption	1500.83(a)(9)
Ferrous oxalate	HSA	exemption from labeling	1500.83(a)(17)
Fertilizers, dry granular	HSA	exemption from labeling	1500.83(a)(21)
Fire extinguishers	HSA	exemption from labeling labeling, warning	1500.83(a)(24) 1500.15(a)(b)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Fireworks	HSA	ban (more than 2 grains pyrotechnic material for audible reports)	1500.17(a)(3)
		ban (firecrackers more than 50 mg.)	1500.17(a)(8) & 9
		exemption from labeling	1500.83(a)(27)
		agricultural exemption	1500 17(a)(3)
		exemption from classification	1500 85(a)(2)
special labeling	1500.14(b)(7)		
ban reloadable tube	1500.17(a)(11)		
aerial shells more than 1 7 inches in outer diameter)			
		safety requirements	1507
First Aid	HSA	policy for emesis labeling	1500.134
Flammable contents of self-pressurized containers	HSA	definition	1500 3(c)(6)(viii)
		method for determining flashpoint testing	1500.45
		exemption from labeling	1500.46
			1500.83(a)(1)
Flammable solids	HSA	definition	1500.3(c)(6)(vi)
		testing method	1500.44
Flammable substances	HSA	definition	1500.3(c)(6)(iii)
		flashpoint testing	1500 43a
Food	HSA	exemption from specific labeling	1500 81(a)
Formaldehyde	HSA	labeling	1500 13(d)
Fuel	HSA	exemptions	1500.81(b)
		exemptions from banning	1500.85(a)(5)
		special packaging	1700.14(a)(7)
Fuel kits with difluorodichloromethane	HSA	exemption from banning warning label	1500.85(a)(12), (13)
Furniture, painted with lead-containing paint	CPSA	ban	1303
Furniture polish, liquid	PPPA	special packaging	1700.14(a)(2)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Furniture polish, paste	HSA	exemption from labeling	1500 83(a)(8)
Garage Door Openers automatic residential	CPSA	requirements for equipment protector	1211
Gasoline	HSA	exemption from labeling special labeling labeling	1500 83(a)(14) 1500 14(b)(3) 1500 14(a)(3)
Glazing compounds	HSA	exemption from labeling	1500 83(a)(13)
Glue remover containing acetone nitrile (household)	PPPA	special packaging	1700 14(a)(18)
Hartshorn	HSA	labeling	1500 129(1)
Heaters (see appliances)			
Highly toxic substances	HSA	definition testing method labeling	1500 3(e) 1500 40 1500 121
Household substances	HSA	definition	1500 3(c)(10)
Hydrochloric acid	HSA	labeling	1500 129(a)
Hypochlorous acid	HSA	labeling	1500.129(h)
Imported products & importers	ALL	policy	1009.3
Imports	HSA	various	1500 265 272
Industrial supplies	HSA	exemption	1500 3(c)(10)(i)
Ink, cartridges dry concentrate containers	HSA HSA	exemption from labeling exemption from labeling	1500 83(a)(7) & (38) 1500 83(a)(12)
Ink-marking devices	HSA	exemption	1500.83(a)(9)
Insulation, cellulose	CPSA	standard	1209
Iron preparations	PPPA	special packaging	1700.14(a)(12), (13)
Irritant substances	HSA	definition testing method	1500.3(g) 1500.41
Isobutane in cigarette lighters	HSA	exemption from labeling	1500 83(a)(29)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Isosorbide dinitrate, pre- scription sublingual and chewable forms	PPPA	exemption from special packaging	1700.14(a)(10)(ii)
Kerosene	HSA	labeling special labeling exemption from labeling special packaging	1500.14(a)(4) 1500 14(b)(3) 1500.83(a)(14) 1700.14(a)(7)
Kindling and illuminating preparations	PPPA	special packaging	1700.14(a)(7)
Kites, aluminized polyester film	HSA	ban	1500.18(c)(1)
Labels	HSA	requirements condensation informal comment on exemption from labeling	1500 121 1500.123 1500.128 1500 83(a)(5)
Laboratory chemicals, if educational	HSA	exemption from banning and labeling	1500 85(a)(4) 1500 85(a)(5)
Lacquers	HSA	exemption from labeling	1500 83(a)(13)
Lawn darts	HSA CPSA	ban ban	1500 18(a)(4) 1306
Lawnmowers, power	CPSA	performance standard, labeling rule, and certification rule	1205
Lead in paint	HSA CPSA	ban over 0.5% (pre- 1978) ban over 0.06% (1978 and later)	1500.17(a)(6) 1303
Lighter fluid, etc.	PPPA	special packaging	1700.14(a)(7)
Lunar caustic (silver nitrate)	HSA	labeling	1500.129(k)
Lye	HSA PPPA	labeling special packaging	1500.129(j) 1700 14(a)(5)
Matchbooks	CPSA	standard	1202
Matches	HSA	exemption from flamma- bility labeling	1500.83(a)(2)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Mattresses	FFA	standard (FF 4-72)	1632
Mebendazole	PPPA	exemption from special packaging	1700.14(a)(10)(xiii)
Medroxyprogesterone acetate tablets	PPPA	exemption from special packaging	1700.14(a)(10)(xix)
Methyl alcohol (methanol)	HSA	exemption from labeling labeling	1500.83(a)(10) 1500.14(a)(4), (b)(4)
	PPPA	exemption from labeling special packaging	1500.83(a)(19) 1500.83(a)(34) 1700.14(a)(8)
Methylprednisolone	PPPA	exemption from special packaging	1700.14(a)(10)(xiv)
Methyl salicylate	PPPA	special packaging	1700.14(a)(3)
Mineral oil (in toys)	HSA	exemption from labeling	1500.83(a)(33)
Mineral seal oil	HSA	labeling special labeling	1500.14(a)(3) 1500.14(b)(3)
	PPPA	special packaging	1700.14(a)(2)
Mineral spirits	HSA	labeling special labeling special packaging	1500.14(a)(3) 1500.14(b)(3) 1700.14(a)(15)
Mirrors	CPSA	exemption from lead limit	1303.3(c)(2)
Mixtures of hazardous substances	HSA	labeling	1500.5
Multiple hazard, substances with	HSA	labeling	1500.127
Naphtha	HSA	labeling special labeling	1500.14(a)(3) 1500.14(b)(3)
Nitric acid	HSA	labeling	1500.129(c)
Nitroglycerine, prescription, sublingual dosage	PPPA	exemption from special packaging	1700.14(a)(10)(i)
Norethindrone acetate tablets	PPPA	exemption from special packaging	1700.14(a)(10)(xviii)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Oral contraceptives, cyclical	PPPA	exemption from special packaging	1700.14(a)(10)(iv)
Orris root, powdered	HSA	labeling	1500.13(b)
Oxalic acid and salts of	HSA	labeling	1500.129(e), (f)
Packages, child-resistant (see child-resistant packaging)			
Packages, sample	PPPA	submission	1700.14(b)
Paint, lead in	HSA	ban over 0.5% (pre-1978)	1500.17(a)(6)
	CPSA	ban over 0.06% (1978 and later)	1303
	CPSA	to be regulated under the CPSA	1145.2
Paint solvents	PPPA	special packaging	1700.14(a)(15)
Painting kits	HSA	exemption	1500.83(a)(25)
Pancrelipase	PPPA	exemption from special packaging	1700.14(a)(10)(ix)
Paper items	HSA	exemption from labeling list	1500.83(a)(3)
Paraphenylenediamine	HSA	labeling	1500.13(a)
Patching compounds, containing asbestos	CPSA	ban	1304
Perchloroethylene in visual	HSA	exemption from labeling	1500.83(a)(31)
Percussion explosives	HSA	definition	1500.3(c)(7)(i)(a)
Petroleum distillates	HSA	labeling special labeling exemption from labeling	1500.14(a)(3) 1500.14(b)(3) 1500.83(a)(8), (9), (11), (13), (14), (20)
	PPPA	special packaging	1700.14(a)(7), (2), (15)
Phenol (carbolic acid)	HSA	labeling	1500.129(d)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Photodynamic sensitizer	HSA	definition	1500 3(b)(9)
Photographic color processing kits	HSA	exemption from labeling	1500.83(a)(25)
Plant foods, dry granular	HSA	exemption from labeling	1500 83(a)(21)
Playpens: expandable	CPSA	to be regulated under the CPSA	1145 13
mesh-sided	CPSA	to be regulated under the CPSA	1145 11
Poisons, caustic	HSA	labeling requirements	1500.129
Polishing products	HSA	exemption from labeling	1500.83(a)(11)
Potash, caustic	HSA	labeling special packaging	1500.129(i) 1700 14(a)(5)
Potassium hydroxide	HSA PPPA	labeling special packaging	1500 129(i) 1700.14(a)(5)
Potassium supplements, effervescent	PPPA	exemption from special packaging	1700 14(a)(10)(vi)
Prednisone	PPPA	exemption from special packaging	1700.14(a)(10)(x)
Pressure-generating substances	HSA	definition	1500 3(c)(7)(i)
Primary irritant	HSA	definition testing method	1500 3(g)(2) 1500 41
Propellant devices for model rockets	HSA	exemption from banning	1500.85(a)(8), (9), (12), (13)
Radiator cleaners	HSA	as household substance	1500.3(c)(10)(i)
Radioactive substances	HSA	defined exemption	1500.3(b)(11), (c)(8)
Refrigerator doors	RSA	standard to permit opening from inside	1750