

Affective tWis bridges in tillion, i could not be geolociated because of insufficient data. Structurally deficient tWis provide the second of the second structural data and the second st

16266531737		
10200001101	US12,20,45 LAGRANG	5M SW IL 43
16982203932	I-294 NB	0.6 M NW ILL 171 P10
16245522281	ILL 171 SB	1.0 M.W.OF I-55 P10
16048404170	ILL171 SB FIRST AV	1.4 M SW ILL 43 P10
16048504171	ILL171 NB FIRST AV	1.4 M SW ILL 43 P10
16048604172	ILL171 SB FIRST AV	0.2 M SE I55 P10
16048704173	ILL171 NB FIRST AV	0.2 M SE I55 P10
16982803938	I-294 SB	0.7 M NW ILL 43 P19
16982903939	I-294 WB	0.7 M NW ILL 43 P19
16031604058	ILL43 HARLEM AVE	0.47 MI N OF ARCHER
16983303943	I-294 SB	0.7 M SE ILL 43 P26
16983203942	I-294 NB	0.7 M SE ILL 43 P26
	16245522281 16048404170 16048504171 16048604172 16048704173 16982803938 16982903939 16031604058 16983303943	16982203932 I-294 NB 16245522281 ILL 171 SB 16048404170 ILL171 SB FIRST AV 16048504171 ILL171 NB FIRST AV 16048604172 ILL171 SB FIRST AV 16048704173 ILL171 NB FIRST AV 16982803938 I-294 SB 16982903939 I-294 WB 16031604058 ILL43 HARLEM AVE 16983303943 I-294 SB 16983203942 I-294 NB