




Structurally Deficient Bridges on the National Highway System Colorado - Congressional District 05



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 136 structurally deficient NHS bridges in Colorado, 14 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	K-14-B	US 50 ML	0.1 MI E OF COTOPAXI
2	K-14-J	US 50 ML	4 MI EAST OF COTOPAXI
3	I-17-AE	US 24 ML EBND	0.4 MI SE OF PIKES PEAK-T
4	I-17-X	US 24 SERVICE RD	1.7 MI SE OF PIKES PEAK-T
5	H-17-I	I 25 ML SBND	4.7 MI N OF JCT SH 83 ML
6	I-17-DT	I 25 ML NBND	2.8 MI N OF JCT SH 38
7	I-17-DU	I 25 ML SBND	IN COLORADO SPRINGS
8	I-17-DS	I 25 ML NBND	IN COLORADO SPRINGS
9	J-18-T	I 25 ML NBND	6.1 MI NW OF EL PASO-PUEB
10	J-18-U	I 25 ML NBND	5.8 MI NW OF EL PASO-PUEB
11	I-18-G	US 24 ML	1.9 MI NE OF FALCON
12	H-18-A	US 24 ML	7.1 MI E OF FALCON
13	H-19-C	US 24 ML	2.1 MI E OF PEYTON