

efficient NNS bridges in China 27 could not be gelocated because of insufficient data. Sincuturally deficient NNSes and Yaco Acc. So in the traductory all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed

| Bridge Label | Structure ID | Bridge Description | Location Description |
|--------------|--------------|--------------------|--------------------------|
| 1 | 7501625 IF | R-75 | 2.94MI.S.OF JCT. SR-47 |
| 2 | 4600363 U | ISR-33 | .29MI.NM. OF JCT. SR-117 |
| 3 | 3202194 U | IS 68 SR 15 | NO DATA |
| 4 | 5901626 I- | 71 | 2.61 MI N OF SR95 |
| 5 | 7001142 U | IS 30 | .62 MILES EAST OF SR 39 |