




Structurally Deficient Bridges on the National Highway System Massachusetts - Congressional District 07



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 187 structurally deficient NHS bridges in Massachusetts, 11 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	F07001276MHDNBI	ST 9 WORCESTER RD	.5 MI. WEST OF TEMPLE ST
2	F07006274MHDNBI	ST 9 /ST30/WRCSTR	3.5 MI W OF JCT 27 & 9
3	N0302028QMHDNBI	ST 27 N MAIN ST	AT JCT OF RTES 9 & 27
4	N120582LHMHDNBI	ST128 SERVICE RD	NEWTON-WESTON TOWN LINE
5	M120054DUMDCNBI	ST 16 MYST VAL PKY	.4 MI W OF WINTHROP ST
6	E120044E9MDCNBI	ST 16 REV BCH PKWY	.2 MI W OF SANTILLI CIR
7	R0500939GMHDNBI	ST107 BROADWAY	1.6 KM N OF SR 60
8	R0500739AMHDNBI	ST107 SALEM TPK	@ SAUGUS TL = S05002
9	R050164DCMDCNBI	ST145 REV BCH PKWY	.1 MI N OF WINTHROP AVE