

Inventory (NB), With the exception of Kenlucky and Pennsylvania, whose meat current data is 2006, all data is from the 2607 NBI. Of the 1930 structurally deficient NHS bridges in California, 54 could not be geoloand be cause of imatificient data. Structurally deficient bridges are not no consulty ursally, all public read bridges receive equipar andley inspections. The bridge in lated were categorized as attructurally deficient bridges are not no consulty ursally.

Bridge Label	Structure ID	Bridge Description	Location Description
1	35 0179G	N280-S1 CONNECTOR	04-SM-280-R25.26-DLC
2	35 0174K	S280-JUNIPERO SERR	04-SM-280-M27.2-DLC
3	35 0116R	STATE ROUTE 280	04-SM-280-R24.2-DLC
4	35 0202R	STATE ROUTE 280	04-SM-280-R23.16-DLC
5	35 0226	STATE ROUTE 380	04-SM-380-T4.98-SBR
6	35 0253	STATE ROUTE 380	04-SM-380-5.73-SBR
7	35 0121	U.S. HIGHWAY 101	04-SM-101-21.8-SSF
8	35 0119	U.S. HIGHWAY 101	04-SM-101-21.69-SSF
9	35 0272H	S101-E380 CONNECTR	04-SM-101-R20.69-SBR
10	35 0271F	W380-N&S101 CONN	04-SM-380-6.4-SBR
11	35 0262G	N101-W380 CONNECTR	04-SM-101-R20.52
12	35 0274K	SFO AIRPRT-S101 ON	04-SM-101-19.09
13	35 0130	U.S. HIGHWAY 101	04-SM-101-23.66-BSBN
14	35 0199	STATE ROUTE 280	04-SM-280-R12.73
15	35 0156R	EB STATE ROUTE 92	04-SM-092-R11.19-SM
16	35 0156L	WB STATE ROUTE 92	04-SM-092-R11.19-SM
17	35 0157R	EB STATE ROUTE 92	04-SM-092-R11.38-SM
18	35 0157L	WB STATE ROUTE 92	04-SM-092-R11.38-SM
19	35 0158R	EB STATE ROUTE 92	04-SM-092-R11.61-SM
20	35 0252R	EB RTE 92 & RAMPS	04-SM-092-R11.78-SM
21	35 0252L	WB RTE 92 & RAMPS	04-SM-092-R11.78-SM