

**PALMER (PAQ) AIRPORT FLY-IN
JUNE 7th, 2008
COLONY DAYS
JUNE 13/14, 2008**

**RECOMMENDED ARRIVAL PROCEDURES
KENAI AFSS/PAQ FSS**

LANDING RY 16

All Aircraft enter downwind over the Butte, 3 SE of the airport. Report entering left downwind to PAQ FSS on 123.6, and monitor CTAF for traffic.

From South – Report over Glenn Highway Knik River Bridge.

From East – Report 10 East of Airport.

From North – Report 10 North of Airport. Remain at least 2 miles East of the airport.

From West – Report the intersection of the Glenn and Parks Highways (new MATSU Valley Regional Hospital)

LANDING RY 34

All Aircraft enter downwind 2 NW of the airport over the intersection of Glenn Highway and Fishhook Road. Report entering left downwind to PAQ FSS on 123.6, and monitor CTAF for traffic.

From South – Report over the Glenn Highway/Knik River Bridge. Fly over the intersection of the Glenn and Parks Highways (new MATSU Valley Regional Hospital), and thence northbound remaining at least 2 miles west of the airport.

From East – Report 10 East of Airport. Fly northbound remaining at least 2 miles East of airport until at least 2 miles Northeast of the airport.

From North – Report 10 North of Airport.

From West – Report 10 West of Airport.



Randy K. Rogers
Manager, Kenai Automated Flight Service Station
May 16, 2008


**Palmer Fly-in/Colony Days
Arrival Procedures**

Palmer FSS 907 745-2495

1 800 WX BRIEF

Palmer Fly-in: June 7, 2008

Colony Days: June 13-14, 2008



10 Miles Out

Glenn Hwy/Fishhook Rd.

New MATSU Hospital

Knik River Bridge

Bodenburg Butte

RWY 16

All aircraft enter downwind from over the Butte, 3 mi SE of airport. Report entering **left** downwind to Palmer (PAQ) FSS on 123.6, and monitor CTAF for traffic.

From South: Report over Glenn Hwy/Knik R. Bridge.

From East: Report 10 miles East of airport.

From North: Report 10 miles North of airport. Remain at least 2 miles East of the airport.

From West: Report intersection of Glenn/Parks Hwys (new hospital).

RWY 34

All aircraft enter downwind from over Glenn/Fishhook Rd intersection. Report entering **left** downwind to PAQ FSS on 123.6, and monitor CTAF for traffic.

From South: Report over Glenn Hwy/Knik R. Bridge. Fly to new Hospital remaining 2 miles West of airport.

From East: Report 10 miles East of airport. Fly north remaining at least 2 miles East of airport until 2 miles NE of airport.

From West: Report 10 miles West of airport.