

DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION
MERRILL FIELD AIRPORT TRAFFIC CONTROL TOWER
1950 EAST 5TH AVENUE
ANCHORAGE, ALASKA 99501

ISSUE: November 15, 2007

EFFECTIVE: November 15, 2007

MERRILL ATCT LETTER TO AIRMEN NO. 07-02

SUBJECT: AREAS OF NON-VISIBILITY

CANCELLATION: November 15, 2009

Use caution, the following areas are not visible from the Merrill Airport Traffic Control Tower:

Portions of Runway 34 between taxiway Quebec and taxiway Sierra.

Portions of taxiway Charlie between taxiway Sierra and taxiway November.

Portions of uncontrolled taxiway Quebec between taxiway Charlie and taxiway Golf.

Portions of taxiway Golf between taxiway November and taxiway Quebec.

Seasonal snow piles may restrict visibility to additional portions of taxiways and runways.

Due to non-visibility issues, Merrill Airport Traffic Control Tower may be unable to provide airport traffic control advisories in the above areas.



John J Schommer

Air Traffic Manager, Merrill ATCT