

## **State Fire Marshal**

### **Bulletin 11**

## **E-85 Fuel Dispensers**

We have become aware of the lack of an approved national standard for the dispensers and connected appurtenances involved in the dispensing of fuel, which contains more than 15% alcohol (E-85). The Michigan State Fire Code currently requires all dispensing equipment to be listed by a nationally recognized testing laboratory; however, since there is no standard, no listing can currently be placed on these systems.

We have discussed this issue with representatives from UL (Underwriters Laboratories). They are actively reviewing current E-85 research and meeting with industry and government experts to gather the information required to draft the appropriate testing and listing requirements. UL anticipates that testing of E-85 dispenser components will commence immediately following publication of UL's E-85 listing requirements. This process could take up to 2 years to complete.

Our research has not indicated any failures connected to E-85 fuel dispensing systems in Michigan or anywhere across the country.

Because of these factors, it is our recommendation that local fire officials continue to monitor this situation while allowing the current E-85 fuel dispensing systems to operate, and new dispensers to be installed. If system failures occur in the future, this issue should be revisited. As soon as a listing is available for dispensing equipment for this type of fuel, the requirement should be enforced.

If you have any questions regarding this bulletin, please contact BFS at (517) 241-8847 or DEQ at (517) 335-7211.

Please be advised as a recipient of this State Fire Marshal Bulletin, you are free to treat the contents as a news release in your name to the local news media or any other means of circulation.