May 29, 2002

Mr. Craig G. Anderson Vice President, Operations ANO Entergy Operations, Inc. 1448 S. R. 333 Russellville. AR 72801

SUBJECT: BULLETIN 2002-01, "REACTOR PRESSURE VESSEL HEAD DEGRADATION

AND REACTOR COOLANT PRESSURE BOUNDARY INTEGRITY," 15-DAY RESPONSE FOR ARKANSAS NUCLEAR ONE, UNITS 1 AND 2 (TAC NOS.

MB4524 AND MB4525)

Dear Mr. Anderson:

On March 18, 2002, the Nuclear Regulatory Commission (NRC) staff issued Bulletin 2002-01 to the industry requesting that addressees provide information related to the structural integrity of the reactor coolant pressure boundary, including the reactor pressure vessel head, and the extent to which inspections have been undertaken to satisfy applicable regulatory requirements. Bulletin 2002-01 also required licensees to provide the basis for concluding that plans for future inspections of the reactor coolant pressure boundary will satisfy applicable regulatory requirements at their respective pressurized water reactor plants. All addressees were requested to respond to Items 1.A. through E. within 15 days of the Bulletin's issuance, or to provide a written response to the NRC in accordance with the provisions of Title 10, Section 50.54(f), of the *Code of Federal Regulations* [10 CFR 50.54(f)] if they are unable to provide the information or they can not meet the requested completion dates.

You provided your 15-day Bulletin response by letter dated April 1, 2002. The NRC staff finds that you have provided the requested information, and has concluded that your plant does not appear to have conditions similar to those which lead to the degradation at Davis-Besse. However, the staff may issue questions to confirm or verify the information that was provided in your 15-day response to Bulletin 2002-01.

We will complete a full review of your response to Bulletin 2002-01 after we review your response to Items 2 and 3 of the Bulletin.

Sincerely,

/RA/

Thomas W. Alexion, Project Manager, Section 1
Project Directorate IV
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket Nos. 50-313 and 368

cc: See next page

Mr. Craig G. Anderson Vice President, Operations ANO Entergy Operations, Inc. 1448 S. R. 333 Russellville, AR 72801

SUBJECT: BULLETIN 2002-01, "REACTOR PRESSURE VESSEL HEAD DEGRADATION

AND REACTOR COOLANT PRESSURE BOUNDARY INTEGRITY," 15-DAY RESPONSE FOR ARKANSAS NUCLEAR ONE, UNITS 1 AND 2 (TAC NOS.

MB4524 AND MB4525)

Dear Mr. Anderson:

On March 18, 2002, the Nuclear Regulatory Commission (NRC) staff issued Bulletin 2002-01 to the industry requesting that addressees provide information related to the structural integrity of the reactor coolant pressure boundary, including the reactor pressure vessel head, and the extent to which inspections have been undertaken to satisfy applicable regulatory requirements. Bulletin 2002-01 also required licensees to provide the basis for concluding that plans for future inspections of the reactor coolant pressure boundary will satisfy applicable regulatory requirements at their respective pressurized water reactor plants. All addressees were requested to respond to Items 1.A. through E. within 15 days of the Bulletin's issuance, or to provide a written response to the NRC in accordance with the provisions of Title 10, Section 50.54(f), of the *Code of Federal Regulations* [10 CFR 50.54(f)] if they are unable to provide the information or they can not meet the requested completion dates.

You provided your 15-day Bulletin response by letter dated April 1, 2002. The NRC staff finds that you have provided the requested information, and has concluded that your plant does not appear to have conditions similar to those which lead to the degradation at Davis-Besse. However, the staff may issue questions to confirm or verify the information that was provided in your 15-day response to Bulletin 2002-01.

We will complete a full review of your response to Bulletin 2002-01 after we review your response to Items 2 and 3 of the Bulletin.

Sincerely, /RA/

Thomas W. Alexion, Project Manager, Section 1

Project Directorate IV

Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket Nos. 50-313 and 368

cc: See next page <u>DISTRIBUTION</u>:

PUBLIC RidsNrrPMWReckley ALee
PDIV-1 r/f RidsNrrPMSBloom SCoffin

EMCB r/f RidsNrrPMTAlexion RidsOgcRp RidsNrrLADJohnson

RidsAcrsAcnwMailCenter RidsRgn4MailCenter (KBrockman)
RidsNrrDlpmLpdiv1 (RGramm) RidsNrrDlpmLpdiv (CHolden, Acting)

RidsNrrDeEmcb (WBateman)

Accession No.: ML021400619

OFFICE	PDIV-1/PM	PDIV-1/PM	PDIV-1/LA	EMCB	PDIV-1/SC
NAME	TAlexion;as	WReckley	DJohnson	SBloom	RGramm
DATE	5/23/02	5/23/02	5/23/02	5/24/02	5/24/02

Arkansas Nuclear One

CC:

Executive Vice President & Chief Operating Officer Entergy Operations, Inc. P. O. Box 31995 Jackson, MS 39286-1995

Director, Division of Radiation Control and Emergency Management Arkansas Department of Health 4815 West Markham Street, Slot 30 Little Rock, AR 72205-3867

Winston & Strawn 1400 L Street, N.W. Washington, DC 20005-3502

Mr. Mike Schoppman Framatome ANP, Richland, Inc. Suite 705 1911 North Fort Myer Drive Rosslyn, VA 22209

Senior Resident Inspector U.S. Nuclear Regulatory Commission P. O. Box 310 London, AR 72847

Regional Administrator, Region IV U.S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011-8064

County Judge of Pope County Pope County Courthouse Russellville, AR 72801 Vice President, Operations Support Entergy Operations, Inc. P. O. Box 31995 Jackson, MS 39286-1995

Wise, Carter, Child & Caraway P. O. Box 651 Jackson, MS 39205