Initial and Repetitive Inspections for Cracking and Corrective Action

- (k) If, during any HFEC inspection required by paragraph (h) or (i) of this AD, any fitting is found not to be made of 7075–T73 or 7050–T7451 material, before further flight, perform a detailed inspection for cracks of the fitting in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747–53– 2485, dated January 8, 2004.
- (1) If no crack is detected, repeat the detailed inspection specified in paragraph (k) of this AD thereafter at intervals not to exceed 36 months or 2,000 flight cycles, whichever comes first. Doing the replacement specified in paragraph (k)(2) of this AD ends the repetitive inspections for the replaced fitting.
- (2) If any crack is detected, before further flight, replace the fitting with a fitting made of 7075–T73 or 7050–T7451 material in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747–53–2485, dated January 8, 2004. No further action is required by this AD for that fitting; however, paragraph (1) of this AD still applies.

Parts Installation

- (l) As of the date specified in paragraph (l)(1) or (l)(2) of this AD, as applicable, no person shall install on any airplane a stop support fitting of the MEDs made from either 7079–T651 or 7075–T651 material.
- (1) For airplanes having line numbers 1 through 830 inclusive: As of January 25, 1999.
- (2) For airplanes having line numbers 831 through 1301 inclusive: As of the effective date of this AD.

Alternative Methods of Compliance (AMOCs)

- (m)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.
- (2) AMOCs, approved previously per AD 98–26–13, amendment 39–10954, are approved as AMOCs with paragraph (f) or (g) of this AD, as applicable. However, any stop support fitting, 2L through 6L and 2R through 6R, of MED 3 that was replaced is still required to be inspected as required in paragraph (h) of this AD.

Issued in Renton, Washington, on November 26, 2004.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-26664 Filed 12-2-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2004-19410; Airspace Docket No. 04-ANM-09]

RIN 2120-AA66

Proposed Revision of Federal Airways V-2, V-257 and V-343; MT

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to revise three Very High Frequency Omnidirectional Range (VOR) Federal airways southeast of Missoula, MT (V–2, V–257, and V–343). These VOR Federal airways are being impacted due to the decommissioning of the Drummond VOR and would be revised or eliminated by this proposed action. **DATES:** Comments must be received on or before January 18, 2005.

ADDRESSES: Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590–0001. You must identify FAA Docket No. FAA–2004–19410 and Airspace Docket No. 04–ANM–09, at the beginning of your comments. You may also submit comments on the Internet at http://dms.dot.gov.

FOR FURTHER INFORMATION CONTACT: Ken McElroy, Airspace and Rules Division, Office of System Operations and Safety, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267–8783.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–2004–19410 and Airspace Docket No. 04–ANM–09) and be submitted in triplicate to the Docket Management System (see ADDRESSES section for address and phone number). You may

also submit comments through the Internet at *http://dms.dot.gov*.

Commentors wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to FAA Docket No. FAA–2004–19410 and Airspace Docket No. 04–ANM–09." The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of comments received. All comments submitted will be available for examination in the public docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at http://dms.dot.gov. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov or the Federal Register's Web page at http://www.gpoaccess.gov/fr/index.html.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see ADDRESSES section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division, Federal Aviation Administration, 1601 Lind Avenue, SW., Renton, WA 98055–4056.

Persons interested in being placed on a mailing list for future NPRM's should call the FAA's Office of Rulemaking, (202) 267–9677, for a copy of Advisory Circular No. 11–2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

Background

The Drummond VOR has been out of service since April 2003, for the reasons discussed below, and the site on which the VOR was located was leased land. In 2002, the FAA learned that the landowner had constructed a house within 1,000 feet of the VOR without providing proper notice to the FAA. The VOR was temporarily taken out of service until the impacts of the house could he identified. A subsequent flight

check of the VOR indicated that the house did not cause a problem; however, large vehicles parked near the VOR facility were interfering with the integrity of the signal. As such, portions of the airways have been NOTAMed out of service. Additionally, subsequent to this NOTAM action the Drummond VOR was decommissioned on January 13, 2004.

The Proposal

The FAA is proposing an amendment to Title 14 Code of Federal Regulations (14 CFR) part 71 (part 71) to revise V—2, V—257, and V—343 southeast of Missoula, MT. Specifically, this notice is proposing to eliminate segments of V—2 and V—343. It would also establish new airway segments on V—2 (between Missoula, MT, and Helena, MT) and V—257 (between SCAAT intersection and the Coppertown VOR).

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation: (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.9M, Airspace Designations and Reporting Points, dated August 30, 2004, and effective September 16, 2004, is amended as follows:

Paragraph 6010(a) Domestic VOR Federal Airways

V-2 [Revised]

From Seattle, WA; Ellensburg, WA; Moses Lake, WA; Spokane, WA; Mullan Pass, ID; Missoula, MT; Helena, MT; INT Helena 119° and Livingston, MT, 322° radials; Livingston; Billings, MT; Miles City, MT; 24 miles, 90 miles, 55 MSL, Dickinson, ND; 10 miles, 60 miles, 38 MSL, Bismarck, ND; 14 miles, 62 miles, 34 MSL, Jamestown, ND; Fargo, ND; Alexandria, MN; Gopher, MN; Nodine, MN; Lone Rock, WI; Madison, WI; Badger, WI; Muskegon, MI; Lansing, MI; Salem, MI; INT Salem 093° and Aylmer, ON, Canada, 254° radials; Aylmer; INT Aylmer 086° and Buffalo, NY, 259° radials; Buffalo; Rochester, NY; Syracuse, NY; Utica, NY; Albany, NY; INT Albany 084° and Gardner, MA, 284° radials; to Gardner. The airspace within Canada is excluded.

V-257 [Revised]

From Phoenix, AZ, via INT Phoenix 348° and Drake, AZ, 141° radials; Drake; INT Drake 003° and Grand Canyon, AZ, 211° radials; Grand Canyon; 38 miles 12 AGL, 24 miles 125 MSL, 16 miles 95 MSL, 26 miles 12 AGL, Bryce Canyon, UT; INT Bryce Canyon 338° and Delta, UT, 186° radials, Delta; 39 miles, 105 MSL INT Delta 004° and Malad City, ID, 179° radials; 20 miles, 118 MSL, Malad City; Pocatello, ID; DuBois, ID; Dillon, MT; Coppertown, MT; INT 002° and Great Falls, MT, 222° radials; Great Falls; 73 miles, 56 MSL, Havre, MT. The airspace within Restricted Area R–6403 is excluded.

V-343 [Revised]

From Dubois, ID; Bozeman, MT.

Issued in Washington, DC, November 26, 2004

Reginald C. Matthews,

Manager, Airspace and Rules. [FR Doc. 04–26585 Filed 12–2–04; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 117

[CGD07-04-124]

RIN 1625-AA09

Drawbridge Operation Regulations; Skidaway Bridge (SR 204), Intracoastal Waterway, Mile 592.9, Savannah, Chatham County, GA

AGENCY: Coast Guard, DHS.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Coast Guard proposes to change the operating regulations of the Skidaway Bridge (SR 204) across the Intracoastal Waterway, mile 592.9 in Savannah, Georgia. This proposed rule would allow the drawbridge to not open from 6:30 a.m. to 9 a.m. and 4:30 p.m. to 6:30 p.m., daily. Due to the amount of vehicle traffic and the lack of openings during the requested time period, this proposed action would improve the movement of vehicular traffic while not unreasonably interfering with the movement of vessel traffic. Public vessels of the United States, tugs with tows, and vessels in distress would be passed at anytime.

DATES: Comments and related material must reach the Coast Guard on or before February 1, 2005.

ADDRESSES: You may mail comments and related material to Commander (obr), Seventh Coast Guard District, 909 S.E. 1st Avenue, Room 432, Miami, FL, 33131–3050, who maintains the public docket for this rulemaking. Comments and material received from the public, as well as documents indicated in this preamble as being available in the docket, will become part of this docket and will be available for inspection or copying at Commander (obr), Seventh Coast Guard District, between 7:30 a.m. and 4 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Mr. Gwin Tate, Project Officer, Seventh Coast Guard District, Bridge Branch, at (305) 415–6747.

SUPPLEMENTARY INFORMATION:

Request for Comments

We encourage you to participate in this rulemaking by submitting comments and related material. If you do so, please include your name and address, identify the docket number for this rulemaking (CGD07–04–124), indicate the specific section of this document to which each comment applies, and give the reason for each