

---

# Corrections

---

Federal Register

Vol. 68, No. 132

Thursday, July 10, 2003

---

This section of the FEDERAL REGISTER contains editorial corrections of previously published Presidential, Rule, Proposed Rule, and Notice documents. These corrections are prepared by the Office of the Federal Register. Agency prepared corrections are issued as signed documents and appear in the appropriate document categories elsewhere in the issue.

---

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39****[Docket No. 2003-NE-24-AD; Amendment 39-13211; AD 2003-13-11]****RIN 2120-AA64****Airworthiness Directives: Pratt & Whitney PW4074, PW4074D, PW4077, PW4077D, PW4090, and PW4090-3 Turbofan Engines***Correction*

In rule document 03-15992 beginning on page 38592 in the issue of Monday,

June 30, 2003 make the following correction:

**§ 39.13 [Corrected]**

On page 38594, in Table 1., in § 39.13, in the first column, in the second entry, in the second line, “incorporating a scalloped J” should read “incorporating a scalloped J flange design during production”.

[FR Doc. C3-15992 Filed 7-9-03; 8:45 am]

BILLING CODE 1505-01-D