

Joint ops with Shuttle

06:00	06:10		ISS morning inspection	
06:10	06:40		Post-Sleep	
06:40	06:50	CDR	Calf Measurement.	Medical Support [] Book 2, 3-37
paragr.3.7				
06:40	06:55	FE-1	Body Mass Measurement	Medical Support [] Book 2, 3-42
paragr.3.8.1				
06:55	07:10	CDR	Body Mass Measurement	Medical Support [] Book 2, 3-42
paragr.3.8.2				
07:00	07:10	PLT	Calf Measurement.	Medical Support [] Book 2, 3-37
paragr.3.7				
07:10	07:25	PLT	Body Mass Measurement	Medical Support [] Book 2, 3-42
paragr.3.8.2				
07:15	07:25	FE-1	Calf Measurement.	Medical Support [] Book 2, 3-37
paragr.3.7				
07:20	07:30	CDR	PMA3 leak check ECLSS/NOMINAL: INGRESS/EGRESS: PMA LONG LEAK CHECK; STEPS 22-26 + OCA_0437;	
07:25	07:45	FE-1	Body Mass Measurement (final ops)	Medical Support [] Book 2, 3-42
paragr.3.8.2, 3.8.3				
07:30	07:45	CDR	Air quality measurement in Node 1 ECLSS /NOMINAL: THC: 2.510 AIR QUALITY MEASUREMENT;	
Breakfast				
07:45	08:35	FE-1	SM ventilation system hardware maintenance	
á/è Ñ ÌÒÐ Ñ Ì paragr. 4.5.3, 4.5.4, 4.5.6 3.p.4-9 through 4-11				
08:35	09:05	CDR	RED COMPLEX SHOOTING PREPARATION AND SHOOTING SCENES /P/TV 100 IN-CABIN OPERATIONS;	
08:35	08:45	PLT	Condensate check on connector of the condensate separation and pumping unit fan [] (ÑÄÄ-É 2 Ì)	
09:05	11:05	CDR, PLT	RED assembly and check out	R/G OCA_0319
10:05	11:05	FE-1	TVIS-2 exercise	
11:05	12:05	PLT	Ergometer-2 exercise	
11:05	12:05	CDR	TVIS exercise	
11:05	11:10	FE-1	TVIS weekly maintenance R/g OCA_0319	
12:05	12:10	CDR	TVIS weekly maintenance R/g OCA_0319	
12:05	13:35		LUNCH (CDR – 12:10-13:35)	
13:35	17:00	PLT	SM ventilation system hardware maintenance á/è Ñ ÌÒÐ Ñ Ì paragr. 4.5.3, 4.5.4, 4.5.6 p.p.4-9 through 4-11	
13:35	15:05	CDR	Cables installation in RED	R/g OCA_0319
13:35	15:15	FE-1	SM ventilation system hardware maintenance	
15:05	15:15	CDR	Equipment disconnect and stow after shooting SCENES /P/TV 100 IN-CABIN OPERATIONS;	
15:15	15:25	CDR	FPP software reloading ACTIVATION AND CHECKOUT / FPP OPERATIONAL CHECKOUT;	
15:15	15:30	FE-1	URAGAN [] Observations as per r/g162	
16:00	17:00	FE-1	Ergometer-2 exercise	
16:50	17:00	CDR	PMA3 leak check ECLSS / NOMINAL: INGRESS/EGRESS: PMA LONG LEAK CHECK; STEPS 22-26 + OCA_0437;	
17:00	17:30	FE-1	Sound level meter equipment test check á/è Ì Ì book1 paragr.11.1.1, 11.1.2 3.p.11-1 through 11-3+r/g 243	
17:00	18:00	PLT	TVIS-2 exercise	
17:00	18:00	CDR	Ergometer exercise	
17:30	17:40	FE-1	Conference after sound level meter measurements completion in SM	

18:00	18:30	Next day program review
18:30	19:00	Report preparation
19:00	19:15	Daily planning conference (evening)
19:30	20:00	DINNER
20:00	20:30	Daily food ration prep
20:30	21:30	Pre-sleep
21:30	06:00	Sleep

End of r/g