November 23, 2001

Mr. John T. Herron Vice President Operations Entergy Operations, Inc. 17265 River Road Killona, LA 70066-0751

SUBJECT: BULLETIN 2001-01, "CIRCUMFERENTIAL CRACKING OF REACTOR

PRESSURE VESSEL HEAD PENETRATION NOZZLES," RESPONSES FOR WATERFORD STEAM ELECTRIC STATION, UNIT 3 (TAC NO. MB2674)

Dear Mr. Herron:

On August 3, 2001, the staff issued Bulletin 2001-01, "Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles," to the industry requesting that addressees provide information related to the structural integrity of the reactor pressure vessel head penetration (VHP) nozzles for their respective facilities, including the extent of VHP nozzle leakage and cracking that has been found to date, the inspections and repairs that have been undertaken to satisfy applicable regulatory requirements, and the basis for concluding that their plans for future inspections will ensure compliance with applicable regulatory requirements at their respective pressurized water reactor plants. You were requested to respond to Items 1 and 4 of the Bulletin within 30 days of its issuance.

You provided your response by letter dated September 4, 2001, as supplemented November 8, 2001, for Waterford Steam Electric Station, Unit 3 (Waterford 3). The staff finds that you have provided the requested information and there is reasonable assurance that the public health and safety will be maintained. Your proposed inspection scope and schedule described in your responses, which included the description of your plan to examine "all" or "100%" of the VHPs at your facility during the next scheduled outage, were integral to the staff's finding. It is the staff's expectation that you will submit a revised response to the Bulletin if you make any substantive changes to the schedule and/or scope of future inspections for Waterford 3. If warranted by such changes, the staff will reevaluate this issue for Waterford 3.

Please be reminded that Item 5 of the Bulletin requested the following information within 30 days after plant restart following the next refueling outage:

 a description of the extent of VHP nozzle leakage and cracking detected at your plant, including the number, location, size, and nature of each crack detected; b. if cracking is identified, a description of the inspections (type, scope, qualification requirements, and acceptance criteria), repairs, and other corrective actions you have taken to satisfy applicable regulatory requirements. This information is requested only if there are any changes from prior information submitted in accordance with this bulletin.

Sincerely,

/RA/

N. Kalyanam, Project Manager, Section 1 Project Directorate IV Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket No. 50-382

cc: See next page

b. if cracking is identified, a description of the inspections (type, scope, qualification requirements, and acceptance criteria), repairs, and other corrective actions you have taken to satisfy applicable regulatory requirements. This information is requested only if there are any changes from prior information submitted in accordance with this bulletin.

Sincerely,

/RA/

N. Kalyanam, Project Manager, Section 1 Project Directorate IV Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket No. 50-382

cc: See next page

**DISTRIBUTION** 

**PUBLIC** 

PDIV-1 r/f

Rids OgcRp

RidsAcrsAcnwACRS

RidsNrrDlpmLpdiv1 (RGramm)

RidsNrrLADJohnson

RidsNrrPMNKalyanam

RidsRgn4MailCenter (KBrockman)

WBateman

**AHiser** 

EMCB R/F

**JZimmerman** 

**JCollins** 

## Accession No.: ML013270344

OFFICE	PDIV-1/PM	PDIV-1/LA	PDIV-1/SC
NAME	NKalyanam	DJohnson	DJaffe for RGramm
DATE	11/19/01	11/20/01	11/23/01

OFFICIAL RECORD COPY

## Waterford Generating Station 3

CC:

Mr. Michael E. Henry, Administrator and State Liaison Officer Department of Environmental Quality P. O. Box 82135 Baton Rouge, LA 70884-2135

Vice President, Operations Support Entergy Operations, Inc. P. O. Box 31995 Jackson, MS 39286-1995

Director Nuclear Safety Assurance Entergy Operations, Inc. 17265 River Road Killona. LA 70066-0751

Wise, Carter, Child & Caraway P. O. Box 651 Jackson, MS 39205

General Manager Plant Operations Waterford 3 SES Entergy Operations, Inc. 17265 River Road Killona, LA 70066-0751

Licensing Manager Entergy Operations, Inc. 17265 River Road Killona, LA 70066-0751

Winston & Strawn 1400 L Street, N.W. Washington, DC 20005-3502

Resident Inspector/Waterford NPS P. O. Box 822 Killona, LA 70066-0751

Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, TX 76011

Parish President Council St. Charles Parish P. O. Box 302 Hahnville, LA 70057

Executive Vice-President and Chief Operating Officer Entergy Operations, Inc. P. O. Box 31995 Jackson, MS 39286-1995

Chairman Louisiana Public Services Commission Baton Rouge, LA 70825-1697