7TH STR EET PUBLIC CONTAINER TERM. (Facility)	Offered for transportation by water freight containers containing class 4 materials when the containers were not properly placarded. Incorrect and missing placards. [172.504] Case No. MV93007611	\$5,000
AFRAM LINES (USA) CO., LTD (Carrier)	M/V Corpus Christi transported hazardous materials by water when DCM was not properly prepared. Class 6.1 poison and 1.3G explosives were improperly stowed in the same freight container. The cargo was not secured to prevent movement in any direction. [176.30, 176.83, 176.63] Case No. MV93002523	\$7,000
AMERICAN PRESIDENT LINES (Carrier)	M/V President Lincoln transported hazardous materials by water when a freight container containing corrosives, oxidizers, and flammable materials was not placarded. [172.504] Case No. MV93002088	\$2,500
AMERICAN PRESIDENT LINES LTD (Carrier)	M/V President Kennedy transported hazardous materials by water when the Dangerous Cargo Manifest was not signed by the Master, Mate, or designated deck officer. [176.30] Case No. MV93007945	\$2,000
AMP DO BRASIL CONNECTORES ELETRIC (Shipper)	Offered for transportation by water a freight container containing packages of class 9 materials, UN 3077, which were improperly placarded as class 6.1 poison. Improper labeling on packaged hazardous waste. [172.502, 172.401] Case No. MV93008520	\$4,000
ANDANIA SHIPPING CO. LTD. (Carrier)	M/V Herman Bodewes transported hazardous materials by water without a DCM. [176.30] Case No. MV91009594	\$1,000
ANGYUTA SHIPPING COMPANY, LTD. (Carrier)	M/V Fidel Jr. transported hazardo us materials by water without a DCM. Fuel tanks in motor vehicles more than 1/4 full and battery cables connected. [176.30, 176.905] Case No. MV93011210	\$12,500
CARLISLE SYNTEC SYSTEMS (Shipper)	Offered for transportation by water packages of hazardous materials when the packing group was not listed on the shipping papers. Hazardous materials were not stowed in a manner that would facilitate inspection or removal in the event of an emergency as required. [172.202, 176.69] Case No. MV93004019	\$6,000
CENCO (Shipper)	Offered for transportation by water corrosives, oxidizers and flammable materials in a freight container that was not placarded. Packages not labeled properly. [172.504, 172.400] Case No. MV93002087	\$2,250
CHINA XINSHIDAI COMPANY (Shipper)	Offered for transportation by water cartridges for weapons which were not properly classed, described, or in condition for shipment. [171.2] Case No. MV92000740	\$7,500
CIA TRASATLANTICA ESPANOLA (Carrier)	M/V Al Khalmah transported hazardous materials by water when the DCM contained several discrepancies. [176.30] Case No. MV93003181	\$4,600
CROWLEY MARINE SERVICES, INC. (Carrier)	M/V Lanai transported motor vehicles by water when fuel tanks were more than 1/4 full and battery cables were connected. [176.905] Case No. MV93006947	\$2,500

CROWLEY MARINE SERVICES, INC.(Carrier)	M/V Molokai transported motor vehicles by water when fuel tanks were more than 1/4 full and battery cables were connected. [176.905] Case No. MV93003649	\$2,500
DAVID K. LINDEMUTH CO., INC. (Shipper)	Offered for transportation by water a freight container containing hazardous materials which were not properly blocked and braced to prevent movement in any direction. Shipping papers missing additional description of 'Poison by Inhalation'. [176.76, 172.203] Case No. MV93003856	\$750
DEESIDE TITANIUM LTD (Shipper)	Offered a shipment of class 4 materials for transportation by water in a freight container which was not declared or listed on the shipping papers. Cargo was not secured to prevent movement in all directions. Freight container with improper placarding. [176.76, 172.200(a), 172.502] Case No. MV93012119	\$6,000
EASTERN CHEMICAL WASTE SYSTEMS (Shipper)	Offered hazardous materials for transportation by water when the emergency response telephone number was missing from the shipping papers. [171.2, 172.201] Case No. MV93006132	\$1,250
EASTERN SHIPPING (Carrier)	M/V Eastern Trader transported motor vehicles by water when the fuel tanks were more than 1/4 full and the battery cables were connected. [176.905] Case No. MV92000118	\$1,500
ELMA GENERAL AGENCY (Carrier)	M/V Libertador General transported hazardous materials by water when the DCM was missing the preparer's signature or the master's signature. Motor vehicles were shipped with the battery cables connected. [176.30, 176.905] Case No. MV93003241	\$2,500
EMPRESA LINEAS MARITIMAS (Carrier)	M/V Salta transported a freight container by water which was improperly placarded "flammable solid" when no hazardous materials were inside. A freight container of Class "A" explosives was not placarded on all four sides, and the cargo was not secured to prevent movement in any direction. [172.502, 172.504, 176.130] Case No. MV92000865	\$4,500
EMPRESA NAVIERA SANTA (Carrier)	M/V Santa Rosa de Lima transported hazardous materials by water in freight containers that were not placarded. [172.504] Case No. MV92010376	\$2,100
EMPRESA NAVIERA SANTA S.A. (Carrier)	M/V Santa Clara I transported hazardous materials by water when the DCM did not list stowage locations for trichloroethane, xylene, and aerosols and did not describe packaging of all listed materials. Containers containing drums of arsenic trioxide improperly stowed directly above portable tanks of hydrogen peroxide. Container containing packages of arsenic trioxide improperly stowed directly above a container containing packages of foodstuffs. Hydrogen peroxide improperly stowed below deck. Improper UN markings on portable tanks. Portable tank missing required oxidizer placards. Portable tanks containing residue of petroleum products missing required placards and labels. Container containing tinplate waste improperly placarded as flammable. [176.30, 176.83, 176.600, 176.63, 172.300, 172.504, 172.502] Case No. MV92001900	\$88,500

EMPRESA NAVIERA SANTA S.A. (Carrier)	M/V Santa Clara I transported hazardous materials by water when poison materials were improperly stowed with foodstuffs. No shipping papers on board for Magnesium Phosphide. Proper shipping name, emergency response telephone number, description, number and gross weight of packages, classification and stowage location not listed for Magnesium Phosphide on DCM. Proper shipping name for Arsenic Trioxide not listed on DCM. DCM missing vessel's official number and signature of master or designated deck officer. [176.30, 176.24, 172.202, 176.600] Case No. MV92010548	\$100,000
FMC CORPORATION (Shipper)	Offered for transportation by water six containers which were improperly placarded. Improper dunnaging and packaging allowed hazardous materials to shift in transit. [172.504, 176.69] Case No. MV93006539	\$10,000
FRANK H. FLEER CORP (Shipper)	Offered hazardous materials for transportation by water when the shipping papers were missing packing group, shipper's certification and the hazardous materials description was not listed first, highlighted or otherwise indicated as required. Hazardous materials were not blocked and braced to prevent movement in any direction. [172.201, 172.202, 172.204, 176.76] Case No. V93004020	\$5,250
GUAM FREIGHT FORWARDERS (Freight Forwarder)	Offered for transportation by water 1.3 and 1.4 explosives which were not dunnaged to prevent movement in any direction. [176.76] Case No. MV93007519	\$3,500
HAINAN FOREIGN ECON DEV CO., LTD (Shipper)	Offered for transportation by water packages of hazardous materials in freight containers which were not secured to prevent movement in any direction. Shipping papers did not contain the proper emergency response telephone number. [176.76, 172.600] Case No. MV93008295	\$4,000
HANJIN SHIPPING CO., LTD.(Shipper)	Shipper failed to remove hazardous materials placards from three intermodal freight containers which contained general cargo. [172.502] Case No. MV92012053	\$750
HOP KEE PYROTECHNICS, LTD. (Shipper)	Offered for transportation by water 1.3G explosives in a freight container which were not sufficiently secured to prevent movement in any direction. [176.76] Case No. MV93002348	\$10,000
ICI EXPLOSIVES CANADA INC. (Shipper)*	Offered for transportation by water containers of hazardous materials which were not dunnaged properly to prevent cargo from shifting. [176.69] Case No. MV93007028	\$7,500
KARL GROSS- SPEDITION AUTO SHIPPING (Shipper)	Offered for transportation by water two motor vehicles which were improperly stowed in a freight container. [176.905] Case No. MV91007781	\$1,000
KISEN KAMBARA (Carrier)	M/V Dang Delima transported hazardous materials be water when the DCM was missing shipper and consignee's complete name and address. [176.30] Case No. MV93007755	\$1,750
KYOWA SHIPPING CO.LTD. (Carrier)	M/V Kyowa Rose transported hazardous materials by water when the DCM had 14 improper shipping names, incorrect shipping class and eighte en missing emergency response telephone numbers. [176.30] Case No. MV93011009	\$8,600

LOTMORE V (Carrier)	M/V Lady Lotmore transported a motor vehicle by water which was leaking gasoline from the fuel tank. [176.905] Case No. MV91007896	\$1,500
MAERSK LINE, LTD. (Carrier)	M/V Maersk Constellation transported hazardous materials by water when the DCM was not properly prepared. [176.30] Case No. MV93002061	\$7,500
MAERSK LINES (Facility)	Accepted hazardous materials for shipment by water in freight containers which were missing the required placards. [172.504] Case No. MV93003676	\$1,500
MATSON TERMINALS, INC. (Freight Consolidator)	Offered for transportation by water cylinders of hydrochloric acid without UN number marked. [172.301] Case No. MV93002877	\$1,000
MEDITERRANEAN SHIPPING CO S.A. (Carrier)	MSC Sabrina transported hazardous materials by water when the DCM was missing emergency response telephone number, preparer's signature, flag/nationality, vessel official number or call sign, and 'NOS' description. Improper ID number and missing package quantity. [176.30] Case No. MV93003906	\$2,400
MERICHEM COMPANY (Shipper)	Offered for transportation by water a freight container containing undeclared Cresols, class 6.1 poison. [171.2] Case No. MV93002853	\$1,000
METROPOLITAN CA. STEVEDORE CO. (Shipper)	Prohibited placarding on two freight containers which were empty. [172.502] Case No. MV93006779	\$1,000
OCEAN EXPRESS LINES (Carrier)	M/V S uperten transported hazardous materials by water without a DCM. Motor vehicles stowed below deck with fuel tanks more than 1/4 full and battery cables connected. Freight container containing general cargo placarded as "corrosive". [176.905, 176.30, 172.502] Case No. MV92001395	\$3,500
ORIENTAL OVERSEAS CONT. LINE LTD. (Carrier)	M/V Pacific Song transported hazardous materials by water when the DCM was missing an emergency response telephone number. [176.30] Case No. MV92012554	\$500
OVERSEAS SUPER EXPRESS INC. (Shipper)	Offered for transportation by water a freight container containing undeclared hazardous materials. No shipping papers were prepared and the container was not placarded. [172.201, 172.504] Case No. MV93008539	\$3,400
PACIFIC COAST CONTAINER (Freight Consolidator)	Offered for transportation by water a freight container with explosives that were not dunnaged to prevent movement in any direction. Container not properly placarded. [176.130, 172.504] Case No. MV92000873	\$1,000
PM&O LINES (Carrier)	M/V Micronesian Independence transported hazardous materials by water when DCM was missing preparer's signature. Vessel name and official number were incorrect, and two emergency response telephone numbers were incorrect. [176.30] Case No. MV93001532	\$2,500
RIVER MARINE TERMINAL (Carrier)	M/V Sea Mist transported 61 motor vehicles by water in a cargo hold with battery cables connected. [176.905] Case No. MV91006975	\$2,500

S. E. RYKOFF & CO. (Shipper)	Corrosive materials improperly stowed in the same container as foodstuffs. Shipper failed to provide information required for hazardous materials on shipping papers. Packages not marked with proper shipping name or ID number Improper labeling. The container was not placarded. Cargo not properly secured to prevent movement in any direction. [172.203, 176.800, 172.300, 172.400, 172.504, 176.76] Case No. MV93002804	\$4,000
SEAFARERS SHIPPING INC. (Carrier)	M/V Westwood Marianne transported hazardous materials by water with an improperly prepared DCM. [176.30] Case No. MV93005842	\$1,000
SEALIFT INC. (Carrier)	M/V Cleveland transported hazardous materials by water with an improperly prepared DCM. Placards missing from a freight container carrying hazardous materials. [172.504, 176.30] Case No. MV93002864	\$9,000
TRI-STATE MOTOR TRANSPORT (Shipper)	Failure to properly provide required information for hazardous materials on shipping papers. Shipping papers for container containing high explosive 1.1D missing emergency response telephone number. [172.201] Case No. MV93012647	\$750
UNIQUE GAIN PRODUCTS LTD. (Shipper)	Shipper failed to properly package hazardous materials. Packages containing fireworks wet, smashed, and opened during transportation. Labels missing from packages. [176.76, 171.2] Case No. MV93004113	\$5,000
WAH KWONG SHIPPING AGENCY CO. LTD (Carrier)	M/V Venture Star transported hazardous materials by water when the DCM was missing the stowage location, proper shipping name, official number or call sign, the masters signature and the preparer's signature. [176.30] Case No. MV93008853	\$4,000
WALLENIUS LINES (Carrier)	M/V Don Carlos transported hazardous materials by water when the DCM did not contain the vessel's official number or call sign and proper shipping names. [176.30] Case No. MV92012686	\$250
WALLENIUS SAFE GOTHIA AB (Carrier)	M/V Otello transported hazardous materials by water when the DCM did not contain the vessel's official number or call sign, stowage location and proper shipping name. [176.30] Case No. MV93000651	\$1,000
YANGMING MARINE TRANSPORT CORP. (Carrier)	M/V Ming Pleasure transported hazardous materials by water when the DCM had an incorrect emergency response telephone number, missing vessel's official number and nationality, missing name and hazard class of each cargo. [176.30] Case No. MV93002315	\$750
YELLOW FREIGHT SYSTEM I (Freight Consolidator)	Offered an undeclared shipment of Ethyl Mercaptan for transportation by water. Cargo was discovered due to its involvement in a hazardous material release. Container was sealed and transported to be serviced by a cleanup company. [171.2] Case No. MV93009858	\$4,000