



U.S. Department  
of Transportation

**Pipeline and Hazardous  
Materials Safety Administration**

400 Seventh Street, S.W.  
Washington, D.C. 20590

Mr. Barry R. Pearl  
Chief Executive Officer  
Texas Eastern Products Pipeline Company  
2929 Allen Parkway  
Houston, TX 77252-2521

MAY - 1 2007

RE: CPF No. 3-2003-5014H

Dear Mr. Pearl:

A Corrective Action Order was issued on November 25, 2003 by the Associate Administrator for Pipeline Safety in the above-referenced case. As you know, the Order required Texas Eastern Products Pipeline Company to take the necessary corrective action to address a failure involving the P-42 and A-1 segments of its 8-inch highly volatile liquid pipeline running from the Todhunter pump station to the Greensburg pump station. The Director, Central Region, PHMSA has determined that all actions required by the Order have been completed. Accordingly, this case is now closed. Thank you for your cooperation in our joint effort to ensure pipeline safety.

Sincerely,

James Reynolds  
Pipeline Compliance Registry  
Office of Pipeline Safety

cc: Mr. Ivan Huntoon  
Director, Central Region, OPS

**CERTIFIED MAIL - RETURN RECEIPT REQUESTED**