

Corrective Actions

(c) If any crack is found during any inspection required by paragraph (a) or (b) of this AD and Boeing Alert Service Bulletin 767-53A0087, dated October 21, 1999, specifies to contact Boeing for repair: Before further flight, repair per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved, the approval must specifically reference this AD.

Previously Installed Repairs

(d) If previously installed repairs are installed in the inspection area, and Boeing Alert Service Bulletin 767-53A0087, dated October 21, 1999, specifies to contact Boeing for inspection details, an alternative method of compliance must be approved as required by sections 39.15, 39.17, and 39.19 of the Code of Federal Regulations (14 CFR 39.15, 39.17, 39.19).

Alternative Methods of Compliance

(e) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance for this AD.

Issued in Renton, Washington, on September 29, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-25230 Filed 10-3-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HEALTH AND HUMAN SERVICES**Food and Drug Administration****21 CFR Part 356**

[Docket No. 81N-033P]

Oral Health Care Drug Products for Over-the-Counter Human Use; Antigingivitis/Antiplaque Drug Products; Establishment of a Monograph; Extension of Comment Period; Correction

AGENCY: Food and Drug Administration, HHS.

ACTION: Advance notice of proposed rulemaking; extension of comment period; correction.

SUMMARY: The Food and Drug Administration (FDA) is correcting a document that appeared in the **Federal Register** of August 25, 2003 (68 FR 50991). The document announced that FDA extended to November 25, 2003, the comment period for an advance notice of proposed rulemaking (ANPR)

for over-the-counter antigingivitis/antiplaque drug products. The ANPR was published in the **Federal Register** of May 29, 2003 (68 FR 32232). The document published with an inadvertent error. This document corrects that error.

DATES: Submit written or electronic comments by November 25, 2003. Submit reply comments by February 23, 2004.

FOR FURTHER INFORMATION CONTACT:

Joyce Strong, Office of Policy and Planning (HF-27), Food and Drug Administration, 5600 Fishers Lane, Rockville, MD 20857, 301-827-7010.

SUPPLEMENTARY INFORMATION: In FR Doc. 03-21669, appearing on page 50992 in the **Federal Register** of August 25, 2003, the following correction is made:

1. On page 50992, in the second column, under **IV. Comments**, in the sixth line, "two" is corrected to read "three".

Dated: September 25, 2003.

Jeffrey Shuren,

Assistant Commissioner for Policy.

[FR Doc. 03-25044 Filed 10-3-03; 8:45 am]

BILLING CODE 4160-01-S

DEPARTMENT OF DEFENSE**Department of the Army; Corps of Engineers****33 CFR Part 334****Department of the Air Force, Wisconsin Air National Guard Danger Zone Under Restricted Air Space R-6903, Lake Michigan, Sheboygan County, WI**

AGENCY: United States Army Corps of Engineers, Department of Defense.

ACTION: Proposed rule and request for comments.

SUMMARY: The Corps of Engineers is proposing an amendment to its regulations to designate an existing military exercise area as a Danger Zone. The military exercise area is located off the Wisconsin shoreline in Lake Michigan from Manitowoc to Port Washington, as shown on National Oceanographic and Atmospheric Administration (NOAA) Chart 14901 (1999). The Danger Zone will only be activated by the Wisconsin Air National Guard (WiANG) during military exercises. The Air Guard will advise fishermen and mariners in the vicinity when a military exercise is scheduled and thus ensure their safety by alerting them of temporary, potentially hazardous conditions which may exist

as a result of the military exercises. There will be no change in the use of the existing military exercise area which is currently shown on aeronautical charts as restricted air space. The area, however, needs to also be marked on navigation charts as a Danger Zone to conform with the restricted air space designation to better insure security and safety for the public.

DATES: Written comments must be submitted on or before November 5, 2003.

ADDRESSES: U.S. Army Corps of Engineers, ATTN: CECW-OR, 441 G Street, NW., Washington, DC 20314-1000.

FOR FURTHER INFORMATION CONTACT: Mr. Frank Torbett, Headquarters Regulatory Branch, Washington, DC at (202) 761-4618, or Mr. Howard J. Ecklund, Corps of Engineers, St. Paul District, Regulatory Branch, at (262) 547-4171.

SUPPLEMENTARY INFORMATION: Pursuant to its authorities in Section 7 of the Rivers and Harbors Act of 1917 (40 Stat. 266; 33 U.S.C. 1) and Chapter XIX, of the Army Appropriations Act of 1919 (40 Stat. 892; 33 U.S.C. 3), the Corps proposes to amend the restricted area regulations in 33 CFR part 334 by adding § 334.145 as a Danger Zone in Lake Michigan offshore from Manitowoc and Sheboygan Counties in Wisconsin, as shown on NOAA Chart 14901 (1999). This is a revision of a similar proposal published in the **Federal Register** on March 11, 2002. This revision is being published because the earlier proposal contained incomplete information and did not adequately explain the reason for the regulation change. As a result, various interested parties expressed concerns regarding the change and its impact on boats using the area. The area to be designated as a Danger Zone already exists as restricted air space R-6903 which is shown on current aeronautical charts. This amendment of the regulation will allow WiANG to request that the U. S. Coast Guard issue a Notice to Mariners when exercises are planned and thus better inform fishermen and mariners of military activities in this area. WiANG intends to continue to schedule this area for use in a similar manner as it has been used during the past 20 years. Historical activity includes, but is not limited to, inert air-to-air and air-to-surface delivery, defensive countermeasures training, and sonar buoy drops.

Procedural Requirements

a. Review Under Executive Order 12866

This proposed rule is issued with respect to a military function of the