

# Rules and Regulations

Federal Register

Vol. 69, No. 123

Monday, June 28, 2004

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 89-ANE-10-AD; Amendment 39-13644; AD 2004-10-14]

RIN 2120-AA64

#### Airworthiness Directives; Lycoming Engines (Formerly Textron Lycoming), Direct-Drive Reciprocating Engines; Correction

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This document makes corrections to Airworthiness Directive (AD) 2004-10-14, applicable to Lycoming Engines (formerly Textron Lycoming), direct-drive reciprocating engines that was published in the **Federal Register** on May 21, 2004 (69 FR 29210). Some corrections to engine models have been made by adding missing dashes, clarification to changes in requirements from the proposed rule are made, and some corrections are made for clarification in the compliance section. In all other respects, the original document remains the same.

**DATES:** *Effective Date:* Effective June 28, 2004.

**FOR FURTHER INFORMATION CONTACT:** Norm Perenson, Aerospace Engineer, New York Aircraft Certification Office, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (516) 228-7337; fax (516) 794-5531.

**SUPPLEMENTARY INFORMATION:** A final rule AD, FR Doc. 04-11406, applicable to Lycoming Engines direct-drive reciprocating engines (except O-145, O-320-H, O-360-E, IO-360-E, LTO-360-E, O-435, and TIO 541 series engines), was published in the **Federal Register** on May 21, 2004 (69 FR 29210). The following corrections are needed:

On page 29210, in the second column, in the **SUMMARY** section, in the sixth and seventh lines, "O-320H, O-360E, LO-360E, LTO-360E" are corrected to read "O-320-H, O-360-E, LO-360-E, LTO-360-E, TO-360-E".

In the third column, in the **SUMMARY** section, in the 14th line, after the words "propeller strike.", a sentence is added to read "This AD removes the requirement to perform inspections at overhaul and during repair of the gear train, because Lycoming has incorporated those procedures from their Service Bulletin into their Overhaul Manual."

Also in the third column, in the **SUPPLEMENTARY INFORMATION** section, in the seventh and eighth lines, "O-320H, O-360E, LO-360E, LTO-360E" is corrected to read "O-320-H, O-360-E, LO-360-E, LTO-360-E, TO-360-E".

On page 29211, in the second column, after the second paragraph, add the following paragraph:

#### Other Corrections

The TO-360-E engine model was inadvertently omitted from the list of exceptions of engines. That engine model has been added to the list of exceptions of engines not affected by this AD. Also, some of the engine model numbers were missing dashes and are corrected in this AD. Also, the phrase after the effective date of this AD, was inadvertently omitted from paragraph (e). This phrase is added to paragraph (e) to cover engines that experience a propeller strike after the effective date of the AD.

#### § 39.13 [Corrected]

■ Also, on page 29211, in the third column, eighth paragraph, fourth and fifth lines, "O-320H, O-360E, LO-360E, LTO-360E" is corrected to read "O-320-H, O-360-E, LO-360-E, LTO-360-E, TO-360-E".

■ Also, on page 29211, in the third column, paragraph (e), which reads "Compliance with this AD is required as indicated before further flight if the engine has experienced a propeller strike as defined in paragraphs (i) and (j) of this AD, unless already done." is corrected to read "Compliance with this AD is required as indicated before further flight if the engine experiences a propeller strike after the effective date of this AD, as defined in paragraphs (i) and (j) of this AD."

Issued in Burlington, MA, on June 18, 2004.

**Francis A. Favara,**

*Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 04-14477 Filed 6-25-04; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2004-17433; Airspace Docket No. 04-ACE-31]

#### Modification of Class E Airspace; Kimball, NE

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Direct final rule; confirmation of effective date.

**SUMMARY:** This document confirms the effective date of the direct final rule which revises Class E airspace at Kimball, NE.

**DATES:** *Effective Date:* 0901 UTC, August 5, 2004.

**FOR FURTHER INFORMATION CONTACT:** Brenda Mumper, Air Traffic Division, Airspace Branch, ACE-520A, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas City, MO 64104; telephone: (816) 329-2524.

**SUPPLEMENTARY INFORMATION:** The FAA published this direct final rule with a request for comments in the **Federal Register** on May 11, 2004 (69 FR 26031). The FAA uses the direct final rulemaking procedure for a non-controversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, were received within the comment period, the regulation would become effective on August 5, 2004. No adverse comments were received, and thus this notice confirms that this direct final rule will become effective on that date.

Issued in Kansas City, MO, on June 15, 2004.

**Paul J. Sheridan,**

*Acting Manager, Air Traffic Division, Central Region.*

[FR Doc. 04-14519 Filed 6-25-04; 8:45 am]

BILLING CODE 4910-13-M

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 97

[Docket No. 30416; Amdt. No. 3099]

#### Standard Instrument Approach Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective June 28, 2004. The compliance date for each SIAP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of June 28, 2004.

**ADDRESSES:** Availability of matters incorporated by reference in the amendment is as follows:

#### *For Examination*

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which the affected airport is located;

3. The Flight Inspection Area Office which originated the SIAP; or,

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030,

or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

#### *For Purchase*

Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

#### *By Subscription*

Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

#### **FOR FURTHER INFORMATION CONTACT:**

Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK 73125) telephone: (405) 954-4164.

**SUPPLEMENTARY INFORMATION:** This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description of each SIAP is contained in official FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation Regulations (FAR). The applicable FAA Forms are identified as FAA Forms 8260-3, 8260-4, and 8260-5. Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the

SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

#### **The Rule**

This amendment to part 97 is effective upon publication of each separate SIAP as contained in the transmittal. Some SIAP amendments may have been previously issued by the FAA in a National Flight Data Center (NFDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for some SIAP amendments may require making them effective in less than 30 days. For the remaining SIAPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these SIAPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and, where applicable, that good cause exists for making some SIAPs effective in less than 30 days.

#### **Conclusion**

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### **List of Subjects in 14 CFR Part 97**

Air Traffic Control, Airports, Incorporation by reference, and Navigation (Air).