



hazardous air pollutant, as set forth in the Information, EPA has strict rules regarding supervision and training for asbestos removal jobs, as well as specific, well-defined directives for

During the fall of 1998, workers employed by the sub-contractor performed demolition work in 13-25 Astor Place, including the removal of asbestos-containing insulation on pipes and ducts and other asbestos-containing building components.

According to the Information, the workers did not follow the asbestos work practice standards. For example, the workers did not wet the asbestos material before removing it; allowed the asbestos material to drop to the floor; and instead

