the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

### §39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA–2004–19945; Directorate Identifier 2004–NM–22–AD. Comments Due Date.

(a) The Federal Aviation Administration (FAA) must receive comments on this AD action by February 17, 2005.

### Affected ADs

(b) None.

### Applicability

(c) This AD applies to Boeing Model 747–200B, 747–200C, 747–200F, 747–300, and 747SR series airplanes; certificated in any category; equipped with General Electric CF6–45 or –50 series engines.

# **Unsafe Condition**

(d) This AD was prompted by reports of a gap at the interface of the lower portion of the side cowl and the aft flange of the thrust reverser. We are issuing this AD to prevent an excessive quantity of air from entering the fire zone that surrounds the engine, which, in the event of an engine fire, could result in an inability to control or extinguish the fire.

### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

### Modification

(f) Within 24 months after the effective date of this AD: Modify the side cowl assemblies on the engines by replacing existing wear plates with new extended wear plates and installing new stop fittings, by doing all actions according to the Accomplishment Instructions of Boeing Service Bulletin 747–71–2300, Revision 1, dated October 30, 2003. Any applicable corrective actions must be done before further flight.

### On Condition: Removal of Bulb Seals and Other Specified Actions

(g) If bulb seals were installed on the trailing edge of the fan thrust reverser in accordance with Boeing Service Letter 747–SL–71–045: Concurrent with or before further flight after accomplishing paragraph (f) of this AD, remove the bulb seals, plug the open holes in the trailing edge of the fan thrust reverser, and adjust the cowl latches as applicable, in accordance with Boeing Service Letter 747–SL–71–045–C, dated April 10, 2003.

# Alternative Methods of Compliance (AMOCs)

(h) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Issued in Renton, Washington, on December 20, 2004.

### Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 04–28667 Filed 12–30–04; 8:45 am] BILLING CODE 4910-13–P

## ENVIRONMENTAL PROTECTION AGENCY

## 40 CFR Part 52

[R06-OAR-2004-TX-0003; FRL-7856-6]

# Approval and Promulgation of Implementation Plans; Texas; Victoria County Maintenance Plan Update

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

**SUMMARY:** EPA is proposing to approve a State Implementation Plan (SIP) revision submitted by the Texas Commission on Environmental Quality (TCEQ) on February 18, 2003, concerning the Victoria County 1-hour ozone maintenance area. This SIP revision satisfies the Clean Air Act requirement as amended in 1990 for the second 10-year update to the Victoria County 1-hour ozone maintenance area. **DATES:** Written comments should be received on or before February 2, 2005. **ADDRESSES:** Comments may be mailed to Mr. Thomas Diggs, Chief, Air Planning Section (6PD-L), Environmental Protection Agency, 1445 Ross Avenue, Suite 1200, Dallas, Texas, 75202–2733. Comments may also be submitted electronically or through hand delivery/ courier by following the detailed instructions in the ADDRESSES section of the direct final rule located in the rules section of this Federal Register.

FOR FURTHER INFORMATION CONTACT: Peggy Wade, Air Planning Section (6PD–L), Environmental Protection Agency, Region 6, 1445 Ross Avenue, Suite 700, Dallas, Texas 75202–2733, telephone (214) 665–7247; fax number 214–665–7263; e-mail address wade.peggy@epa.gov.

**SUPPLEMENTARY INFORMATION:** In the final rules section of this **Federal Register**, EPA is approving the State's SIP submittal as a direct final rule without prior proposal because the Agency views this as a noncontroversial

submittal and anticipates no adverse comments. A detailed rationale for the approval is set forth in the direct final rule. If no adverse comments are received in response to this action rule, no further activity is contemplated. If EPA receives adverse comments, the direct final rule will be withdrawn and all public comments received will be addressed in a subsequent final rule based on this proposed rule. EPA will not institute a second comment period. Any parties interested in commenting on this action should do so at this time. Please note that if EPA receives adverse comment on an amendment, paragraph, or section of this rule and if that provision may be severed from the remainder of the rule, EPA may adopt as final those provisions of the rule that are not the subject of an adverse comment.

For additional information, see the direct final rule which is located in the rules section of this **Federal Register**.

Dated: December 17, 2004.

# Richard E. Greene,

Regional Administrator, Region 6. [FR Doc. 04–28701 Filed 12–30–04; 8:45 am] BILLING CODE 6560-50–P

## ENVIRONMENTAL PROTECTION AGENCY

## 40 CFR Part 52

[R04–OAR–2004–KY–0002–200424; FRL– 7856–8]

Approval and Promulgation of Implementation Plans for Kentucky: Inspection and Maintenance Program Removal for Jefferson County, KY; Source-Specific Nitrogen Oxides Emission Rate for Kosmos Cement Kiln

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA is proposing to approve a revision to the Jefferson County, Kentucky portion of the Kentucky State Implementation Plan (SIP) which requests removal of three regulations from the active portion of the Kentucky SIP related to the Jefferson County inspection and maintenance (I/M) program. Kentucky requested in a September 22, 2003, SIP revision that these I/M regulations be moved to the contingency measures section of the Kentucky portion of the Louisville 1-Hour Ozone Maintenance Plan. EPA is also proposing to approve a sourcespecific SIP revision amending the nitrogen oxides  $(NO_x)$  emission rate for Kosmos Cement Company's cement kiln