	UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION ACCIDENT INVESTIGATION REPORT					
	OCCURRED DATE: 02-JUL-2006 TIME: 1715 HOURS OPERATOR: GOM Shelf LLC REPRESENTATIVE: Dan Orr TELEPHONE: (337) 280-4195 CONTRACTOR: ISLAND OPERATORS CO. INC. REPRESENTATIVE: Wendell Baxter TELEPHONE: (337) 761-4716	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER				
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:				
	LEASE: G03079 AREA: MI LATITUDE: BLOCK: 555 LONGITUDE: PLATFORM: C RIG NAME:	<pre>X PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER</pre>				
	ACTIVITY: EXPLORATION(POE) DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE: HISTORIC INJURY REQUIRED EVACUATION LTA (1-3 days) LTA (>3 days) RW/JT (1-3 days) RW/JT (>3 days)	8. CAUSE: EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER				
	☐ Other Injury □ FATALITY 0	9. WATER DEPTH: <b>75</b> FT.				
	POLLUTION FIRE EXPLOSION LWC HISTORIC BLOWOUT UNDERGROUND SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	10. DISTANCE FROM SHORE: 15 MI. 11. WIND DIRECTION: SE SPEED: 15 M.P.H. 12. CURRENT DIRECTION: SPEED: M.P.H.				
	COLLISION HISTORIC >\$25K <- \$25K	13. SEA STATE: FT.				

EV2010R

Two employees with Gulf Crane Service were performing a required annual crane inspection. One of the employees was the supervisor, and the other was an inexperienced employee==just two days into his first seven-day offshore crane injection job. One employee (the supervisor) was in the cab of the crane, and the other employee was lubricating the boom cable of the crane from the top of the gantry on the entry side of the sheave when his gloved hand was pulled into the sheave. His right little finger was fractured from the second joint outward with no missing flesh. The right ring finger was severed from the third last joint outward with bone and flesh loss. A portion of a severed finger was recovered and transported on ice with the employee to the hospital in Port Lavaca, Texas. His middle finger was crushed beyond the third last joint at tip with missing flesh.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The employee who was injured was greasing the cable on the entry side of the sheave and as the cable was pulled into the sheave, his gloved hand was pulled into the sheave by a splintered wire. He was a new employee with only two days on the job and should have been visibly supervised.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

The supervisor was in the cab of the crane at the controls and could not visually supervise the injured man.

MMS - FORM 2010

EV2010R

MMS - FORM 2010

## 21. PROPERTY DAMAGED:

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE: The Lake Jackson District has no recommendations to prevent recurrance.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

25. DATE OF ONSITE INVESTIGATION:

07-JUL-2006

- 26. ONSITE TEAM MEMBERS: 29. ACCIDENT INVESTIGATION Phillip Couvillion / Ralph Tate / Henry Hite / OCS REPORT:
  - 30. DISTRICT SUPERVISOR:

Ed. Smith

APPROVED DATE: **14-AUG-2006** 

NATURE OF DAMAGE:

N/A

## **INJURY/FATALITY/WITNESS ATTACHMENT**

OPERATOR REPRESI	INTATIVE	x	INJURY	
X CONTRACTOR REPRI			FATALITY	
OTHER			WITNESS	
NAME :				
NAME . HOME ADDRESS:				
CITY:		SIALE		
WORK PHONE: TOTAL OFFSHORE EXPERIENCE:			YEARS	
EMPLOYED BY: ISL	AND OPERATORS CO.	INC. / 2	20324	
BUSINESS ADDRESS:	108 ZACHARY			
CITY:	LAFAYETTE		STATE: LA	
ZIP CODE:	70583			