




## Structurally Deficient Bridges on the National Highway System South Carolina - Congressional District 06



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 107 structurally deficient NHS bridges in South Carolina, 2 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	520032100200	US 321	4MI N OF OLAR
2	520032100300	US 321	6MI N OF DENMARK
3	520032100400	US 321	6.5MI N OF DENMARK
4	520032100500	US 321	7MI N OF DENMARK
5	520030110100	US 301	6MI S OF BAMBERG
6	520030130200	US 301	2.5MI S OF BAMBERG
7	520030130400	US 301	3MI N OF BAMBERG
8	4040027710600	SC 277	7 MI N OF COLA
9	520007800100	US 78	8.0 MI E OF BAMBERG
10	4020007620300	US 76	5MI E OF COLA
11	520007800200	US 78	8.5MI E OF BAMBERG
12	3820030100500	US 301	CITY OF ORANGEBURG
13	520007800400	US 78	10MI E OF BAMBERG
14	3820007800100	US 78	4MI W OF BRANCHVILLE
15	3820007800200	US 78	3MI SW OF BRANCHVILLE
16	1510009510400	I-95	2 MI NW OF WALTBR
17	4020007600500	US 76	3MI W OF EASTOVER
18	920060100300	US 601	10MI NE OF ST MATTHEWS
19	4020060100100	US 601	7MI S OF EASTOVER
20	4020060100200	US 601	6MI S OF EASTOVER
21	4020060100300	US 601	5MI S OF EASTOVER
22	4320007640100	US 76	12 MI W OF SUMTER
23	4320007620200	US 76	12 MI W OF SUMTER
24	4320007620300	US 76	12 MI W OF SUMTER
25	4320007620400	US 76	12 MI W OF SUMTER
26	3810009530100	I-95	8 MI SE OF BOWMAN
27	1520001700400	US 17	AT JACKSONBORO
28	1820007800600	US 78	3.7 MI NW OF RIDGEVILLE
29	4320001500200	US 15	TOWN OF SUMTER
30	1410009530800	I-95	2MI NW OF MANNING
31	1020001710300	US 17	5 MI NE OF RAVENEL
32	1420037840100	US 378	2MI W OF TURBEVILLE
33	1010002600600	I-26	N CHARLESTON
34	1040000700200	SC 7	IN N CHARLESTON
35	1020001710600	US 17	IN CHARLESTON
36	1420037800300	US 378	3MI E OF TURBEVILLE
37	3420037800100	US 378	1.0 MI SW GRESHAM
38	2220001730200	US 17	16MI SW GEORGETOWN
39	3420037800300	US 378	5 MI SE OF GRESHAM
40	3420037800400	US 378	7.0 MI SE GRESHAM
41	3420037800600	US 378	8.0 MI SE GRESHAM