



Intersection at taxiway C and Rwy 1R/19L.




Intersection at taxiway F and Rwy 9/27.




Looking South. Intersection of taxiway G and Ottawa Avenue.

Airport Operations: (816) 243-5248
 Air Traffic Control: (816) 243-2700
 Hours of Operation: 24 hours
 Latitude: N39°-17-86
 Longitude: W94°-42-84
 Elevation: 1026 ft.
 Variation: 04°E
 From City: 17 miles NNW
 Sectional chart: Kansas City
 Control Tower: Yes
 ARTCC: Kansas City Center
 FSS: Columbia Flight Service Station (1-800 992-7433)
 NOTAMs Facility: FAA Columbia
 Wind Indicator: Yes
 Beacon: Yes
 Fire and Rescue: On Site
 Airline Operations: Yes
 Customs: Yes
 UNICOM: 122.95
 ATIS: 128.35
 MCI Ground: 121.8
 MCI Tower: 128.2
 Clearance Delivery: 135.7
 Approach Control: 124.7
 Emergency: 121.5



ATIS 128.35
INTERNATIONAL TOWER
128.2 254.25
GND CON
121.8
CLNC DEL
135.7



HIGH ALERT INTERSECTIONS

- 1.** The intersection of taxiways C and D and runway 1R-19L
- 2.** The intersection of taxiways E and F and runway 9-27.
- 3.** The intersection of Taxiway G and Ottawa Avenue (vehicle service road) is located between Taxiway G-1 and Taxiway B on Taxiway G. This service road is a high traffic vehicle route for airlines and airline service vehicles.

CAUTION

The intersection of taxiway B-2 and Ottawa Ave. (vehicle service road). Taxiway B-2 is the only entrance to Executive Beechcraft. This service road is a high traffic vehicle route for airlines and cargo carriers.

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.

FIELD
ELEV
1026