

Farley 1

3Q/2003 Plant Inspection Findings

Initiating Events

Mitigating Systems

Significance:  Dec 31, 2002

Identified By: Self Disclosing

Item Type: FIN Finding

Improper Scheduling of Pump Motor Overhaul

Improper scheduling of vendor recommend 10 year overhaul of 1C Service Water pump motor.

A self-revealing finding was identified for the 1C Service Water pump motor failure. This finding is greater than minor significance because it adversely impacted the ultimate heat sink reliability and effected the mitigating systems cornerstone objective. Because there was no loss of system function, this finding is of very low safety significance.

Inspection Report# : [2002005\(pdf\)](#)

Barrier Integrity

Emergency Preparedness

Occupational Radiation Safety

Public Radiation Safety

Physical Protection

Miscellaneous

Last modified : December 01, 2003